

Appendix D
EE&G Environmental Reports
(Hazardous Materials Testing)



ENVIRONMENTAL SERVICES, LLC

**LIMITED ASBESTOS
INSPECTION SURVEY REPORT**

FOR

**GLYNN ARCHER ELEMENTARY SCHOOL COMPLEX
CITY HALL PLANNING PROJECT
1302 WHITE STREET
KEY WEST, FLORIDA 33040**

Prepared for

CH2M HILL
6410 5th STREET, SUITE 2A
KEY WEST, FLORIDA 33040

Mr. ANDREW H. SMYTH

Prepared by



EE&G Environmental Services, LLC
5751 Miami Lakes Drive
Miami Lakes, Florida 33014
(305) 374-8300
www.eeandg.com

August 29, 2012
EE&G Project No. 2012-2373

CONTENTS

<u>Section</u>	<u>Page</u>
1.0 - INTRODUCTION.....	1-1
2.0 - BUILDING DESCRIPTION.....	2-1
3.0 - METHODS AND LIMITATIONS	3-1
3.1 ASBESTOS SURVEY METHODS.....	3-1
3.2 LABORATORY ANALYSIS METHODS.....	3-1
3.3 LIMITATIONS	3-1
4.0 - SURVEY RESULTS.....	4-1
4.1 ASBESTOS ANALYSIS RESULTS	4-1
4.2 ADDITIONAL OBSERVATIONS	4-2
5.0 - RECOMMENDATIONS.....	5-1
5.1 RECOMMENDATIONS FOR REGULATED (FRIABLE) ACM.....	5-1
5.2 RECOMMENDATIONS FOR CATEGORY I NONFRIABLE ACM.....	5-1
5.3 RECOMMENDATIONS FOR CATEGORY II NONFRIABLE ACM.....	5-1
5.4 RECOMMENDATIONS FOR LESS THAN 1 PERCENT MATERIALS	5-1
5.5 GENERAL RECOMMENDATIONS	5-2
5.6 SPECIFIC RECOMMENDATIONS	5-2
6.0 - SIGNATURE PAGE	6-1

TABLES

TABLE 1	Survey Results – Building A.....	4-3
TABLE 2	Survey Results – Building B.....	4-9
TABLE 3	Survey Results – Building Auditorium.....	4-15
TABLE 4	Survey Results – Building C	4-17

APPENDICES

APPENDIX A	General Terms: Types of Asbestos-Containing Materials Types of Asbestos-Containing Roofing Materials NESHAP Categories
APPENDIX B	Laboratory Reports
APPENDIX C	Figures
APPENDIX D	Inspection Photographs
APPENDIX E	Certificates

SECTION 1.0

INTRODUCTION

An asbestos inspection was conducted at the Glynn Archer Elementary School Complex, located at 1302 White Street, Key West, Florida. The inspection was conducted in June 2012 by AHERA-certified inspectors Rich Grupenhoff, Ramsey Abreu, Hiram Aguiar, and Sean Nemser of EE&G Environmental Services, LLC (EE&G).

The purpose of this asbestos inspection was to identify the presence, extent, and condition of asbestos-containing materials (ACM) in the surveyed areas of this facility. The areas surveyed during this inspection include the dormitories and common area corridors. All observed suspect materials were either sampled to determine asbestos content or assumed to contain asbestos.

Terms used in this report are defined in the General Terms section located in Appendix A. Additional information on the classification of ACM for National Emissions Standards for Hazardous Air Pollutants (NESHAP) is also located in Appendix A. These NESHAP categories are helpful in determining the need for asbestos abatement and must be used in the NESHAP notification of intent to renovate or demolish.

SECTION 2.0**BUILDING DESCRIPTION****BUILDING A**

The two-story classroom building, constructed in the 1920's, was observed to be constructed primarily of concrete, steel, and wood; interior walls were observed to be finished with plaster and drywall, ceilings were observed to be finished with laid-in ceiling tile, plaster and drywall. Floors were observed to be finished with vinyl floor tile, wood, and ceramic tile. County records were not available to review during the time of this inspection. See Appendix C for Figures.

BUILDING B

The two-story classroom building, constructed in the 1920's, was observed to be constructed primarily of concrete, steel, and wood; interior walls were observed to be finished with plaster and drywall, ceilings were observed to be finished with laid-in ceiling tile, plaster and drywall. Floors were observed to be finished with vinyl floor tile, wood, and ceramic tile. County records were not available to review during the time of this inspection. See Appendix C for Figures.

AUDITORIUM BUILDING

The one-story auditorium building, constructed in the 1920's, was observed to be constructed primarily of concrete, steel, and wood; interior walls were observed to be finished with plaster and drywall, ceilings were observed to be finished with laid-in ceiling tile, plaster and drywall. Floors were observed to be finished with linoleum and wood. County records were not available to review during the time of this inspection. See Appendix C for Figures.

BUILDING C

The one-story classroom building, constructed in the 1950's, was observed to be constructed primarily of concrete, steel, and wood; interior walls were observed to be finished with plaster and drywall, ceilings were observed to be finished with laid-in ceiling tile, plaster and drywall. Floors were observed to be finished with vinyl floor tile, wood, and ceramic tile. County records were not available to review during the time of this inspection. See Appendix C for Figures.

SECTION 3.0

METHODS AND LIMITATIONS

3.1 ASBESTOS SURVEY METHODS

The classrooms, corridors, common areas, and roof areas were inspected for suspect ACM, unless otherwise noted. Each observed suspect material was assigned a homogenous area number, described, and measured. Each observed suspect material was either sampled or assumed to be asbestos-containing. Samples of suspect ACM were collected using procedures established by the United States (US) Environmental Protection Agency (EPA) Code of Federal Regulations (CFR) Title 40 Part 763 Subpart E, Asbestos-Containing Materials in Schools.

3.2 LABORATORY ANALYSIS METHODS

Samples were sent to AAL in Tampa, Florida for analysis. Upon arrival at the laboratory, the samples were logged-in and stored for analysis. Analyses were performed using the polarized light microscopy (PLM) method of asbestos detection using guidelines and procedures established in the Method for the Determination of Asbestos in Bulk Building Materials (EPA-600/R-93-116 July, 1993).

3.3 LIMITATIONS

This asbestos inspection report has been prepared by EE&G in a manner consistent with that level of care and skill ordinarily exercised by members of the profession currently practicing under similar conditions. No other warranty, expressed or implied is made. The intent of this survey report is to assist the owner or client in locating ACM. Under no circumstances is this survey to be utilized as a proposal or a project specification document without the expressed written consent of EE&G.

The survey was conducted to identify suspect ACM in accessible areas of the structure. If other areas at this location are to be impacted during planned or future renovations, a separate asbestos survey of these areas will be required. Some ACM may not have been discovered due to inaccessibility or missing/incomplete plans. Any suspect materials discovered subsequent to the issue of this survey report should be sampled and analyzed to determine asbestos content and to initiate appropriate responses.

Analyses were carried out by PLM. While the most commonly accepted analytical method for detecting asbestos in bulk materials, PLM is known to have limited resolution and may not detect extremely small asbestos fibers. Certain materials, notably vinyl floor tiles, may contain extremely fine asbestos fibers that are beyond the resolution of PLM.

EE&G's interpretations and recommendations are based upon the results of sample collection and analyses in compliance with environmental regulations, quality control and assurance standards, and the scope of work as indicated in EE&G's proposal, dated June 14, 2012. The results, conclusions, and recommendations contained in this report pertain to conditions observed at the time of the survey. Other conditions elsewhere in the subject building(s) may

differ from those in the inspected/surveyed locations and, such conditions are unknown, may change over time, and have not been considered.

This report was prepared solely for the use of EE&G's client, and is not intended for use by third party beneficiaries. The client shall indemnify and hold EE&G harmless against any liability for any loss arising out of or relating to reliance by any third party on any work performed thereunder, or the contents of this report. EE&G will not be held responsible for the interpretation or use by others of data developed pursuant to the compilation of this report, or for use of segregated portions of this report.

SECTION 4.0**SURVEY RESULTS****4.1 ASBESTOS ANALYSIS RESULTS**

The results of the PLM analyses and assessment of suspect ACM are summarized in Table 1. The original laboratory report is attached as Appendix B.

4.1.1 Asbestos-containing materials

Asbestos was identified in amounts greater than 1 percent in the following materials:

- **Building A**
 - Tan 12"x12" VFT mastic (2-5%C)
 - Black VFT (2-5%C)
 - Brown VFT (2-5%C)
 - Light Green 9"x9" VFT (2-5%C)
 - Green 12"x12" VFT (2-5%C)
 - Light Green VFT (2-5%C)
 - Cream 9"x9" VFT (2-5%C)
 - Green 9"x9" VFT (2-5%C)
 - Pink 9"x9" VFT (2-5%C)
 - Light Green 9"x9" VFT (2-5%C)
 - Black/Grey cap flashing/sealant (5-10%C)

- **Building B**
 - Brown VFT (2-5%C)
 - Beige 12"x12" VFT mastic (2-5%C)
 - Black VFT (2-5%C)
 - Grey VFT (2-5%C)
 - Brown 9"x9" VFT (2-5%C) with black mastic (2-5%C)
 - Black VFT (2-5%C) with black mastic (2-5%C)
 - Red 9"x9" VFT (2-5%C) with black mastic (2-5%C)
 - White 9"x9" VFT (2-5%C) with black mastic (2-5%C)
 - Green 9"x9" VFT (5-10%C)

- **Building C**
 - Grey 9"x9" VFT (2-5%C) with black mastic (5-10%C)
 - Green VFT (2-5%C) with black mastic (5-10%C)
 - Grey VFT (2-5%C) with black mastic (5-10%C)
 - Black roof curb wall counter flashing (5-10%C)

- **Auditorium**
 - Tan pebble linoleum (20-25%C in paper backing)
 - Maroon VFT (2-5%C)

Refer to Tables 1 for the location, quantity, and condition of these materials.

4.1.2 Nonasbestos-containing materials

Asbestos was not detected or was found in amounts less than or equal to 1 percent in the following materials:

- **Building A**
 - Grey/brown plaster system
 - White/red 2'x4' dot furrow red back ceiling tile
 - White 2'x4' dot dot ceiling tile
 - White 2'x4' dot furrow ceiling tile
 - White/tan 1'x1' ceiling tile
 - Beige/green exterior stucco with paint
 - Grey window glazing
 - Brown vinyl base board with glue
 - Blue vinyl baseboard with glue
 - Tan 12"x12" VFT
 - Brown ceiling tile board
 - Brown ceiling tile glue
 - Beige 12"x12" VFT
 - Black felt
 - White 12"x12" VFT with glue
 - Tan 12"x12" red stripe VFT and glue
 - Green 12"x12" VFT
 - Light blue 12"x12" VFT with glue
 - Tan VFT and glue
 - Blue 12"x12" VFT with glue
 - Dark tan 12"x12" VFT with glue
 - Grey/aqua 12"x12" VFT with glue
 - Sky blue 12"x12" VFT with glue
 - Black/grey felt field membrane
 - Black/grey edge flashing
 - Black/grey VTR flashing

- **Building B**
 - Grey/white plaster system
 - White/red 2'x4' dot furrow red back ceiling tile
 - White 2'x4' dot furrow ceiling tile
 - White/brown 1'x1' dot ceiling tile
 - Cream/green exterior stucco with paint
 - Tan vinyl baseboard with glue
 - Grey vinyl baseboard with glue
 - Brown vinyl baseboard with glue
 - Tan 12"x12" VFT
 - Beige 12"x12" VFT with glue
 - Cream 12"x12" VFT with glue
 - Tan 12"x12" red stripe VFT with glue
 - White 12"x12" VFT with glue

- Black/grey roof felt field membrane
- Black/grey cap seal flashing
- Black VTR flashing

- **Building C**
 - Grey plaster system
 - White 2"x4" dot furrow ceiling tile
 - White/red 1'x1' dot ceiling tile
 - Grey/pink exterior stucco with paint
 - Grey/green exterior stucco with paint
 - Grey window glazing
 - Black/white chill water thermal system insulation (TSI)
 - Pink 12"x12" VFT and glue
 - Blue 12'x12' VFT and glue
 - Light blue 12'x12' VFT and glue
 - Beige 12'x12' VFT and glue
 - Tan speck 12'x12' VFT and glue
 - Brown striped 12'x12' VFT and glue
 - Brown vinyl baseboard and glue
 - Black roof field membrane
 - Black edge flashing
 - Black wall curb flashing
 - Black VTR flashing
 - Black exhaust flashing
 - Black wall counter flashing

- **Auditorium**
 - Grey/white plaster system
 - White 2'x4' dot furrow ceiling tile
 - White/tan 1'x1' dot ceiling tile
 - Cream/green exterior stucco with paint
 - Grey window glazing
 - Grey ceiling plaster system
 - Black felt paper
 - Black/grey roof field membrane
 - Black edge flashing
 - Black wall curb flashing
 - Grey ceiling insulation.

Refer to Table 1 for the location of these materials.

TABLE 1: SURVEY RESULTS FOR GAES (BUILDING A), KEY WEST, FLORIDA

HA #	Material Description	HA Location	Approx. Quantity	Asbestos Content	Friability	Condition	NESHAP Category
01-03	Grey/brown plaster system	All partition and demising walls,, older upper ceilings	NA	NAD	NA	NA	NA
04	White/red 2'x4' dot furrow redback ceiling tile	Hallways on floor 1, Rooms 100, 102,124	NA	NAD	NA	NA	NA
05	White 2'x4' dot dot ceiling tile	Main office 119 replacement tile	NA	NAD	NA	NA	NA
06	White 2'x4' dot furrow ceiling tiles	Majority of newer lower ceilings, various halls and rooms n floors 1 & 2	NA	NAD	NA	NA	NA
07	White/tan 1'x1' ceiling tie	Upper ceilings (on plaster) on corridors, floors 1 & 2	NA	NAD	NA	NA	NA
08-09	Bumpy exterior stucco with beige or green paint	Exterior finishes, floors 1 & 2	NA	NAD	NA	NA	NA
10	Grey window glazing	Exterior windows on floors 1 & 2	NA	NAD	NA	NA	NA
11	Brown vinyl baseboard and glue	Stair treads in hall stairwells	NA	NAD	NA	NA	NA
12	Blue vinyl baseboard and glue	Room 102	NA	NAD	NA	NA	NA

NA = Not Applicable

VFT = Vinyl Floor Tile

SF = Square Feet

TSI = Thermal System Insulation

NAD = No Asbestos Detected

HA = Homogeneous Area

C = Chrysotile Asbestos

LF = Linear Feet

CT = Ceiling Tile

TBD = To Be Determined

All quantities are approximate.

HA #	Material Description	HA Location	Approx. Quantity	Asbestos Content	Friability	Condition	NESHAP Category
13-14	Tan/Beige 12"x12" VFT over 9" black VFT and felt	Floors 1 & 2 hallways and common areas (not bathrooms)	2,300 +2,100 = 4,400 SF total	2-5% in 9" black/brown VFTs base layer only	Non-friable	Good (enclosed)	I
15	White 12"x12" VFT	Room 200	NA	NAD	NA	NA	NA
16	Light green 9"x9" VFT and black felt	Main office 119 (under carpet various rooms) TBD	<1,100 SF	2-5%C in VFT only	Non-friable	Good	I
17	Tan 12"x12" red stripe VFT	Rooms 103A, 122A, 120, 202, 203, 213	NA	NAD	NA	NA	NA
18	Green 12"x12" VFT and black felt	Rooms 102 (exposed) and 212 (bottom layer)	102 = 600 SF 212 = 1,050 SF	2-5%C	Non-friable	Good	I
19	Green 12"x12" VFT and yellow glue	Room 212 (upper layer)	See above	NAD	NA	NA	NA
20	Light Blue 12"x12" VFT	Room 100 (top layer) and 119 Main office	NA	NAD	NA	NA	NA
21	Tan VFT and yellow glue	Room 100 (bottom layer)	NA	NAD	NA	NA	NA
22	Blue 12"x12" VFT over Tan VFT and yellow glue	Main office 119 complex	NA	NAD	NA	NA	NA

NA = Not Applicable

VFT = Vinyl Floor Tile

SF = Square Feet

TSI = Thermal System Insulation

NAD = No Asbestos Detected

HA = Homogeneous Area

C = Chrysotile Asbestos

LF = Linear Feet

CT = Ceiling Tile

TBD = To Be Determined

All quantities are approximate.

HA #	Material Description	HA Location	Approx. Quantity	Asbestos Content	Friability	Condition	NESHAP Category
23	Cream/Green/Pink 9"x9" VFT w/black mastic/felt	Rooms 204 and 205	1,250 SF total	2-5% in VFTs only	Non-friable	Good	I
24	Dark tan 12"x12" VFT	Room 120	NA	NAD	NA	NA	NA
25	Grey/aqua 12"x12" VFT	Room 103A	NA	NAD	NA	NA	NA
26	Black/grey felt field membrane	Roof south center, north, center	NA	NAD	NA	NA	NA
27	Black/grey edge flashing	Roof south edge	NA	NAD	NA	NA	NA
28	Black/grey VTR flashing	Roof north east	NA	NAD	NA	NA	NA
29	Black/grey cap flashing/sealant	Main Roof parapet perimeter	400LF x 6 = 2,400 SF total	5-10%C in sealant	Non-friable	Good	I
30	Brown ceiling tile glue	Sampled in Rm 200, present above most ceilings	NA	NAD	NA	NA	NA

NA = Not Applicable
 NAD = No Asbestos Detected
 TBD = To Be Determined
 All quantities are approximate.

VFT = Vinyl Floor Tile
 HA = Homogeneous Area

SF = Square Feet
 C = Chrysotile Asbestos

TSI = Thermal System Insulation
 LF = Linear Feet CT = Ceiling Tile

TABLE 2: SURVEY RESULTS FOR GAES (BUILDING B), KEY WEST, FLORIDA

HA #	Material Description	HA Location	Approx. Quantity	Asbestos Content	Friability	Condition	NESHAP Category
01	Grey/white/brown Plaster system	All partition and demising walls and cupper ceilings throughout	NA	NAD	NA	NA	NA
02	White 2'x4' dot furrow redback ceiling tile	Hallways on floor 1 (lower ceiling)	NA	NAD	NA	NA	NA
03	White 2'x4' dot furrow ceiling tile	Floor 1 and 2 hallways, majority lower ceiling tiles, also majority in classrooms	NA	NAD	NA	NA	NA
04	White/brown 1'x1' ceiling tile	Upper ceilings in halls and rooms on floors 1 & 2	NA	NAD	NA	NA	NA
05	Bumpy exterior stucco with cream/green paint	Floors 1 & 2 exterior finishes	NA	NAD	NA	NA	NA
06	Tan Vinyl baseboard and glue	Rooms 109, 104, 209, 210	NA	NAD	NA	NA	NA
07	Grey vinyl baseboard and glue	Room 106	NA	NAD	NA	NA	NA
08	Brown/Tan vinyl baseboards and glue	Stairwells NE and where present	NA	NAD	NA	NA	NA

NA = Not Applicable

VFT = Vinyl Floor Tile

SF = Square Feet

TSI = Thermal System Insulation

NAD = No Asbestos Detected

HA = Homogeneous Area

C = Chrysotile Asbestos

LF = Linear Feet

CT = Ceiling Tile

TBD = To Be Determined

All quantities are approximate.

HA #	Material Description	HA Location	Approx. Quantity	Asbestos Content	Friability	Condition	NESHAP Category
10	Tan/Beige 12"x12" VFTs over brown VFT and black mastic	Floors 1 & 2 hallways and common areas (not bathrooms)	2,300 +2,300 = 4,600 SF total	2-5%C in Brown VFT and black mastic only	Nonfriable	Good	I
11	Cream 12"x12" VFT over Grey VFT and black felt	Room 210	625SF	2-5%C in Grey VFT only	Nonfriable	Good	I
12	Tan 12"x12" redstripe VFT	Room 208, 209, 215	NA	NAD	NA	NA	NA
13	White 12" VFT over Green VFT and black felt	Room 108	460SF	2-5%C in Green VFT only	Nonfriable	Good	I
14	Brown 9" VFT over black VFT and black mastic	Room 107 (both layers)	625SF	2-5%C in VFTs and mastics	Nonfriable	Good	I
15	Red/White 9" VFTs over Black/Green VFTs and black mastic	Room 215 (checkerboard pattern, both layers)	700 SF	2-5%C in VFTs and mastics	Nonfriable	Good	I
16	White 9" VFT over Green VFT and black mastic and felt	Room 206 (both layers)	625SF	2-5%C in VFTs and mastics	Nonfriable	Good	I
17	Green VFT and black mastic and felt	Room 207	625 SF	2-5%C in VFT and mastics	Nonfriable	Good	I

NA = Not Applicable

VFT = Vinyl Floor Tile

SF = Square Feet

TSI = Thermal System Insulation

NAD = No Asbestos Detected

HA = Homogeneous Area

C = Chrysotile Asbestos

LF = Linear Feet

CT = Ceiling Tile

TBD = To Be Determined

All quantities are approximate.

HA #	Material Description	HA Location	Approx. Quantity	Asbestos Content	Friability	Condition	NESHAP Category
18	Black/grey roof felt field membrane	Floor 2 corridor center, northeast	NA	NAD	NA	NA	NA
19	Black/grey cap seal flashing	Cap southeast, northwest, southwest	NA	NAD	NA	NA	NA
20	Black VTR flashing	Vent center	NA	NAD	NA	NA	NA

NA = Not Applicable
 NAD = No Asbestos Detected
 TBD = To Be Determined
 All quantities are approximate.

VFT = Vinyl Floor Tile
 HA = Homogeneous Area

SF = Square Feet
 C = Chrysotile Asbestos

TSI = Thermal System Insulation
 LF = Linear Feet CT = Ceiling Tile

TABLE 3: SURVEY RESULTS FOR GAES (AUDITORIUM), KEY WEST, FLORIDA

HA #	Material Description	HA Location	Approx. Quantity	Asbestos Content	Friability	Condition	NESHAP Category
01	Grey/white plaster system	Upper ceilings	NA	NAD	NA	NA	NA
02	White 2'x4' dot furrow ceiling tile	Lower suspended ceilings	NA	NAD	NA	NA	NA
03	White/tan 1'x1' dot ceiling tile	Upper ceilings (glued on plaster)	NA	NAD	NA	NA	NA
04	Bumpy exterior stucco with cream/green paint	Exterior finishes	NA	NAD	NA	NA	NA
05	Grey window glazing	Old 117 windows	NA	NAD	NA	NA	NA
07	Tan pebble linoleum	Main floor under seats (top)	3,300 SF	20-25%C in backing	Non-friable	Good	I
08	Maroon VFT w/black felt/mastic	Main floor (bottom)	(Included above)	2-5%C in VFT only	Non-friable	Good	I
09	Black/grey field membrane	Roof proper	NA	NAD	NA	NA	NA
10	Black edge flashing	Main and walkway perimeter edges	NA	NAD	NA	NA	NA
11	Black wall curb flashing	Up against A and B walls	NA	NAD	NA	NA	NA

NA = Not Applicable

VFT = Vinyl Floor Tile

SF = Square Feet

TSI = Thermal System Insulation

NAD = No Asbestos Detected

HA = Homogeneous Area

C = Chrysotile Asbestos

LF = Linear Feet

CT = Ceiling Tile

TBD = To Be Determined

All quantities are approximate.

TABLE 4: SURVEY RESULTS FOR GAES (BUILDING C), KEY WEST, FLORIDA

HA #	Material Description	HA Location	Approx. Quantity	Asbestos Content	Friability	Condition	NESHAP Category
01	Grey Plaster system	All partition and demising walls	NA	NAD	NA	NA	NA
02	White 2'x4' dot furrow ceiling tile	Various Rooms including 115C, 112, 114	NA	NAD	NA	NA	NA
03	White/red 1'x1'dot ceiling tile	Hallways upper ceilings exposed	NA	NAD	NA	NA	NA
04	Bumpy grey exterior stucco with pink paint	Exterior finishes on library roof and back at 136D	NA	NAD	NA	NA	NA
05	Smooth grey exterior stucco with green paint	Floor 1 exterior finishes	NA	NAD	NA	NA	NA
06	Grey window glazing	Exterior windows	NA	NAD	NA	NA	NA
07	Black/white chill water TSI (straights and elbows)	Northside Mech exterior mech. areas	NA	NAD	NA	NA	NA
08	Grey 9x9" VFT and black mastic	Rooms 114B, 133	114B = 900SF 133 = 300SF	2-5%C in VFT, 5-10% C in mastic	Nonfriable	Good	I

NA = Not Applicable

VFT = Vinyl Floor Tile

SF = Square Feet

TSI = Thermal System Insulation

NAD = No Asbestos Detected

HA = Homogeneous Area

C = Chrysotile Asbestos

LF = Linear Feet

CT = Ceiling Tile

TBD = To Be Determined

All quantities are approximate.

HA #	Material Description	HA Location	Approx. Quantity	Asbestos Content	Friability	Condition	NESHAP Category
09	Green 9x9" VFT and black mastic	Room 113C	500 SF	2-5%C in VFT, 5-10% C in mastic	Nonfriable	Good	I
10	Pink 12"x12" VFT and glue	Room 111	NA	NAD	NA	NA	NA
11	Blue 12"x12" VFT over light blue and glue	Room 113A	NA	NAD	NA	NA	NA
12	Tan/Beige 12"x12" VFT over Green/Grey VFT and black mastic	Corridors (2 layers)	2,500 SF total	2-5%C in Green/grey VFTs, 5-10% C in mastic	Nonfriable	Good	I
13	White 12" VFT w/ black mastic	Cafeteria/Servery areas	<3,400 SF	2-5%C in remnant mastic only	Nonfriable	Good	I
14	Brown striped 12"x12" VFT and glue	114A, 126, Cafeteria (spots)	NA	NAD	NA	NA	NA
15	Brown vinyl baseboard and glue	Corridors	NA	NAD	NA	NA	NA
16	Black roof field membrane	Lower and upper decks	NA	NAD	NA	NA	NA
17	Black edge flashing	Lower and upper deck perimeters	NA	NAD	NA	NA	NA

NA = Not Applicable VFT = Vinyl Floor Tile SF = Square Feet TSI = Thermal System Insulation
 NAD = No Asbestos Detected HA = Homogeneous Area C = Chrysotile Asbestos LF = Linear Feet CT = Ceiling Tile
 TBD = To Be Determined
 All quantities are approximate.

HA #	Material Description	HA Location	Approx. Quantity	Asbestos Content	Friability	Condition	NESHAP Category
18	Black wall curb flashing	Upper decks at C walls	NA	NAD	NA	NA	NA
19	Black VTR flashing	Roof vents on all decks	NA	NAD	NA	NA	NA
20	Black exhaust flashing	Exhaust fan bases	NA	NAD	NA	NA	NA
21	Black wall counter flashing	Up against Library cap deck	300 LF/600 SF	5-10%C	Nonfriable	Good	I

NA = Not Applicable
 NAD = No Asbestos Detected
 TBD = To Be Determined
 All quantities are approximate.

VFT = Vinyl Floor Tile
 HA = Homogeneous Area

SF = Square Feet
 C = Chrysotile Asbestos

TSI = Thermal System Insulation
 LF = Linear Feet CT = Ceiling Tile

SECTION 5.0**RECOMMENDATIONS****5.1 RECOMMENDATIONS FOR REGULATED ACM (RACM)**

The following material was identified as RACM:

- None of the sampled materials were identified as RACM

5.2 RECOMMENDATIONS FOR CATEGORY I NONFRIABLE ACM

The following materials were identified as Category I Nonfriable ACM:

- **Building A**
 - Tan 12"x12" VFT mastic (2-5%C)
 - Black VFT (2-5%C)
 - Brown VFT (2-5%C)
 - Light Green 9"x9" VFT (2-5%C)
 - Green 12"x12" VFT (2-5%C)
 - Light Green VFT (2-5%C)
 - Cream 9"x9" VFT (2-5%C)
 - Green 9"x9" VFT (2-5%C)
 - Pink 9"x9" VFT (2-5%C)
 - Light Green 9"x9" VFT (2-5%C)
 - Black/Grey cap flashing/sealant (5-10%C)
- **Building B**
 - Brown VFT (2-5%C)
 - Beige 12"x12" VFT mastic (2-5%C)
 - Black VFT (2-5%C)
 - Grey VFT (2-5%C)
 - Brown 9"x9" VFT (2-5%C) with black mastic (2-5%C)
 - Black VFT (2-5%C) with black mastic (2-5%C)
 - Red 9"x9" VFT (2-5%C) with black mastic (2-5%C)
 - White 9"x9" VFT (2-5%C) with black mastic (2-5%C)
 - Green 9"x9" VFT (5-10%C)
- **Building C**
 - Grey 9"x9" VFT (2-5%C) with black mastic (5-10%C)
 - Green VFT (2-5%C) with black mastic (5-10%C)
 - Grey VFT (2-5%C) with black mastic (5-10%C)
 - Black wall counter flashing (5-10%C)
- **Auditorium**
 - Tan pebble linoleum (20-25%C)
 - Maroon VFT (2-5%C)

These materials must be removed prior to any activities that would release asbestos fibers. Specifically, any renovation activity that will crush, abrade, or dissolve the matrix of these materials must be performed by a Florida-licensed Asbestos Contractor. If they will not be impacted during renovation, then no other special handling is required. New tile or carpeting may be installed over asbestos-containing flooring as long as they are not impacted by the installation activities.

5.3 RECOMMENDATIONS FOR CATEGORY II NONFRIABLE ACM

None of the materials were identified as Category II Nonfriable ACM.

5.4 GENERAL RECOMMENDATIONS

- If other areas at this location are to be impacted during renovation, an asbestos survey of these areas will be required.
- Suspect materials discovered after this inspection should be sampled and analyzed to determine asbestos content and to initiate appropriate responses.

If any materials are to remain in-place:

- An operations and maintenance (O&M) program should be implemented to manage ACM that will remain in the building. An O&M program will prevent asbestos fiber release, resuspension of previously released fibers, and ensure proper control of asbestos fibers if a release occurs.
- Any repair and maintenance activities where the ACM is likely to release asbestos fibers must be conducted by personnel who have attended a 16-hour OSHA Class III operations training course.
- Any maintenance and custodial activities where the ACM is contacted but asbestos fibers are unlikely to be released must be conducted by personnel who have attended a 2-hour OSHA Class IV operations training course.

5.5 SPECIFIC RECOMMENDATIONS

Based on the results of this renovation survey, EE&G has the following specific recommendations:

- Removal and disposal of ACM for the purposes of renovation must be performed by a Florida-licensed asbestos contractor.
- A licensed asbestos consulting firm should perform daily air monitoring of the renovation areas during asbestos removal to document the air quality, perform daily inspections, and provide final visual inspections and final air clearance testing.

- Prior to renovation activities, the renovation areas should be inspected for potentially hazardous materials, such as Freon, mercury, lead, solvents, caustic materials, and flammable materials. The identified materials should be removed from the area, and properly disposed of in accordance with federal, state, and local regulations.
- EE&G recommends a hazards communications program be implemented to protect workers in other trades from inadvertent exposure to asbestos fibers during the renovation.
- The Monroe County Department of Environmental Protection (MCDEP) requires notification of intent to renovate. Notification must be sent at least 10 working days prior to the start of any renovation activities. The general contractor should also keep a copy of this survey at the construction site during the entire project as proof of compliance with 40 CFR 61 (NESHAP).

SECTION 6.0
SIGNATURE PAGE

Submitted by



Richard Grupenhoff
Sr. Operations Manager, EE&G

Reviewed by



Daniel J. Cottrell, Ph.D., P.G.
Senior Technical Advisor, EE&G
Asbestos Consultant #DD0000010

APPENDIX A

GENERAL TERMS:

**TYPES OF ASBESTOS-CONTAINING MATERIALS
TYPES OF ASBESTOS-CONTAINING ROOFING MATERIALS
NESHAP CATEGORIES FOR ACM**

TYPES OF ASBESTOS-CONTAINING MATERIALS

Asbestos-Containing Material (ACM)

Asbestos-containing materials, as defined by National Emission Standards for Hazardous Air Pollutants (NESHAP), are materials that have an asbestos content of greater than 1 percent.

Friable Material

Material that can be crumbled or reduced to a powder using normal hand pressure. Nonfriable material is too hard to be crumbled or reduced to a powder without the use of tools. Nonfriable materials may become friable if abraded or broken.

Suspect Materials

There are three broad classes that define suspect, asbestos-containing materials. These are: 1) surfacing material, 2) thermal system insulation, and 3) miscellaneous material. All materials that fit the description of these materials (as described below) are suspected to contain asbestos, until sampled and analyzed.

- **Surfacing Material** - Materials applied by spray or trowel are classified as surfacing materials. Asbestos was used in a variety of surfacing materials for fireproofing, acoustic dampening, condensation control, and decorative purposes. Surfacing materials that contain asbestos usually occur as fireproofing on steel-frame members, textured ceilings, or acoustic plaster ceilings.
- **Thermal System Insulation (TSI) Material** - Chill water, hot water, and steam-generating mechanical systems are frequently insulated with materials that contain asbestos. Pipes may be insulated with a nonasbestos-containing material, but have mastic or plastered joints that contain asbestos. Insulation materials that contain asbestos are generally found in boiler rooms and chiller rooms, in pipe chases in walls, in pipe runs above suspended ceilings, or in crawl spaces under buildings. Insulation covered with an undamaged jacket or wrap is classified as nonfriable. Adhesives used to hold insulation in place or provide an airtight seal are also nonfriable materials. Most other types of thermal insulation are friable.
- **Miscellaneous Material** - Miscellaneous building materials are materials that are used for finishing of interior spaces, or adhesive materials applied to building materials and roofs. These materials have been manufactured with asbestos for strength enhancement, fire retardation, condensation control, acoustical dampening, or corrosion resistance. The most common type of friable miscellaneous material is ceiling tile. Most other miscellaneous materials are nonfriable materials such as vinyl floor tile, adhesives, and cementitious panels (Transite™).

TYPES OF ASBESTOS-CONTAINING ROOFING MATERIALS (ACRM)**Field Membrane**

This area is usually the predominant part of any roof deck and is comprised of all nonflashed areas and is applied directly to the roof substrate over an intermediate insulating layer. It usually consists of alternating layers of rolled-out felts and hot tar, topped with more hot tar to waterseal, and gravel. The asbestos, if found, is in one or more of the layers of tar or may be in the felts themselves.

Edge Flashing

This component consists of a cold bull/pitch applied to the substrate around the perimeter of a flat roof deck. An additional 8" - 12" of felt is applied to the bull/pitch to seal the edge of the roof substrate before a 4" - 6" piece of metal drip guard is placed over these materials to counterflash and protect against wind and rain. The field membrane felts are then blended in with the inner edge to conform with the rest of the roof. The asbestos, if found, is in the layers of bull/pitch, tar, or may be in the flashing felts themselves.

Wall Base/Parapet Flashing

This component consists of a cold bull/pitch applied to the roof substrate, adjoining wall base, fan/vent, scupper trough, hatch, chimney, or raised parapet wall. An additional 12" - 48" of felt (often painted silver) is applied to the bull/pitch to seal the edges of the roof substrate, wall(s), or the side or top of the concrete parapet wall. The field membrane felts are then blended in with the inner edge to conform with the rest of the roof. The asbestos, if found, is in the layers of bull/pitch, tar, or may be in the flashing felts themselves.

Roof Fixture Flashing

This component consists of a cold bull/pitch applied to the roof substrate around any of the following fixtures: roof drain, vent-thru-roof stack (VTR), pitch pan, gooseneck vents, mechanical equipment supports, or any other roof penetration. An additional sheet of metal counterflashing (extending 4" - 24" from the center) is applied to the bull/pitch to seal the edges to the roof substrate. The field membrane felts are placed over up to the fixture sides to conform with the rest of the roof. The asbestos, if found, is in the layers of bull/pitch, tar, or may be in the flashing felts themselves.

NESHAP CATEGORIES FOR ACM**Regulated ACM (RACM)**

All ACM that is friable or likely to become friable during renovation or demolition activities is considered to be RACM. These materials must be removed from buildings prior to renovation or demolition activities that will disturb them.

Category I Nonfriable ACM

Resilient flooring, such as vinyl floor tile and rolled vinyl sheeting, valve packings and gaskets, and asphalt (bituminous) roofing materials are all classified as Category I Nonfriable materials. If these materials are in good condition, they are not likely to become friable during demolition, and therefore, may remain in place for demolition. However, these materials must be removed prior to renovations if the renovation involves alteration that would render them friable.

Category II Nonfriable ACM

Category II materials are all other nonfriable materials that are not classified as Category I. Asbestos cement products and plaster are the most common types of Category II materials. Most Category II materials are likely to become friable during demolition, and therefore, must be removed prior to demolition. These materials must be removed prior to renovations if the renovation involves alteration that would render them friable.

APPENDIX B
LABORATORY ANALYSIS REPORT
PLM RESULTS

REPORT

SENT CH2M HILL

TO: 6410 5TH STREET, SUITE 2A
KEY WEST, FL 33040
ANDREW SMYTH

Phone: 305-294-1645 **Fax:** 305-294-4913
Email: asmyth@ch2m.com

Thank you for your business.

PREPARED AAL

BY: Asbestos Department
5005 WEST LAUREL STREET
SUITE 110
TAMPA, FL 33607
NVLAP Code 101775
(813) 287-1005

Analysis: Polarized Light Microscopy (PLM) with dispersion staining techniques according to the United States (US) Environmental Protection Agency (EPA) "Method for the Determination of Asbestos in Bulk Building Materials", EPA/600/R-93-116, July 1993.

Sample Type: BULK

of Samples: 55

Work Order# T1206102
AAL Project# 2012-2373

Project: GLYNN ARCHER ES: BLDG A

Date in: Tuesday, June 26, 2012

Date out: Friday, Jun 29 2012

Transported: FEDEX

Sampled by: R.G.

Received by: KIA



Authorized Analyst
KHANDAKER ANAM



Laboratory Manager
KHANDAKER ANAM

Due to the small size of asbestos fibers associated with vinyl floor tiles, TEM analysis is recommended for all floor tiles containing <1% or no detectable asbestos by visual estimation.

This report may not be reproduced except in full, without the written approval of AAL. AAL will not be held responsible for the use of its reports issued in part to third parties or authorized agents of the client.

This report shall not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All NVLAP reports displaying NVLAP logo must have at least one signature to be valid.

The following analytical results presented in this report pertain only to the samples analyzed. American Asbestos Laboratories assumes no responsibility for whether the samples accurately represent the material in question

LABORATORY BULK SAMPLE ANALYSIS REPORT

CLIENT: CH2M HILL
PROJECT: GLYNN ARCHER ES: BLDG A
Work Order: T1206102

Samples were analyzed in accordance with the Interim Method as described in 40 CFR, Part 763, Vol. 52, No. 210

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	CHRY	PERCENT ASBESTOS FIBERS				%NON-ASB FIBERS	
						AMOS	CROC	TREM	ANTH		OTHER
01 A	KIA	GREY/BROWN PLASTER SYSTEM	HALL CEILING @102	062012RG01		NO ASBESTOS DETECTED					1 -2
01 B	KIA	GREY/BROWN PLASTER SYSTEM	HALL CEILING @ENTRY	062012RG02		NO ASBESTOS DETECTED					1 -2
01 C	KIA	GREY/BROWN PLASTER SYSTEM	HALL CEILING @100/103	062012RG03		NO ASBESTOS DETECTED					1 -2
01 D	KIA	GREY/BROWN PLASTER SYSTEM	HALL WALL @103	062012RG04		NO ASBESTOS DETECTED					1 -2
01 E	KIA	GREY/BROWN PLASTER SYSTEM	HALL WALL @OFFICE	062012RG05		NO ASBESTOS DETECTED					1 -2
01 F	KIA	GREY/BROWN PLASTER SYSTEM	WALL @GIRLS ROOM	062012RG06		NO ASBESTOS DETECTED					1 -2
02 A	KIA	GREY/BROWN PLASTER SYSTEM	WALL IN RM 100	062012RG07		NO ASBESTOS DETECTED					1 -2
02 B	KIA	GREY/BROWN PLASTER SYSTEM	WALL IN RM 103	062012RG08		NO ASBESTOS DETECTED					1 -2
02 C	KIA	GREY/BROWN PLASTER SYSTEM	WALL IN RM 119G	062012RG09		NO ASBESTOS DETECTED					1 -2
02 D	KIA	GREY/BROWN PLASTER SYSTEM	WALL IN RM 202	062012RG10		NO ASBESTOS DETECTED					1 -2
02 E	KIA	GREY/BROWN PLASTER SYSTEM	WALL IN RM 205	062012RG11		NO ASBESTOS DETECTED					1 -2
02 F	KIA	GREY/BROWN PLASTER SYSTEM	WALL IN RM 203	062012RG12		NO ASBESTOS DETECTED					1 -2

CLIENT: CH2M HILL
PROJECT: GLYNN ARCHER ES: BLDG A
Work Order: T1206102

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	CHRY	PERCENT ASBESTOS FIBERS				%NON-ASB FIBERS
						AMOS	CROC	TREM	ANTH OTHER	
02 G	KIA	GREY/BROWN PLASTER SYSTEM	WALL IN RM 204	062012RG13		NO ASBESTOS DETECTED				1 - 2
02 H	KIA	GREY/BROWN PLASTER SYSTEM	WALL IN RM 212	062012RG14		NO ASBESTOS DETECTED				1 - 2
02 I	KIA	GREY/BROWN PLASTER SYSTEM	WALL IN RM 200	062012RG15		NO ASBESTOS DETECTED				1 - 2
02 J	KIA	GREY/BROWN PLASTER SYSTEM	WALL IN RM 213	062012RG16		NO ASBESTOS DETECTED				1 - 2
03 A	KIA	GREY/BROWN PLASTER SYSTEM	WALL IN HALL NW	062012RG17		NO ASBESTOS DETECTED				1 - 2
03 B	KIA	GREY/BROWN PLASTER SYSTEM	WALL IN HALL SE	062012RG18		NO ASBESTOS DETECTED				1 - 2
03 C	KIA	GREY/BROWN PLASTER SYSTEM	WALL IN BOYS 124	062012RG19		NO ASBESTOS DETECTED				1 - 2
03 D	KIA	GREY/BROWN PLASTER SYSTEM	CEILING @212	062012RG20		NO ASBESTOS DETECTED				1 - 2
04 A	KIA	WHITE/RED 2'X4' DOT FURROW RED BACK CT	HALL @102	062012RG21		NO ASBESTOS DETECTED				60 - 70
04 B	KIA	WHITE/RED 2'X4' DOT FURROW RED BACK CT	HALL @MAIN OFFICE	062012RG22		NO ASBESTOS DETECTED				60 - 70
04 C	KIA	WHITE/RED 2'X4' DOT FURROW RED BACK CT	HALL @100	062012RG23		NO ASBESTOS DETECTED				60 - 70
04 D	KIA	WHITE/RED 2'X4' DOT FURROW RED BACK CT	HALL @102	062012RG24		NO ASBESTOS DETECTED				60 - 70
04 E	KIA	WHITE/RED 2'X4' DOT FURROW RED BACK CT	HALL @124	062012RG25		NO ASBESTOS DETECTED				60 - 70
05 A	KIA	WHITE 2'X4' DOT DOT CEILING TILE	MAIN OFFICE 119	062012RG26		NO ASBESTOS DETECTED				60 - 70

Friday, June 29, 2012

Page 3 of 5

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG A

Work Order: T1206102

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM	ANTH		OTHER
06 A	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	GIRLS ROOM	062012RG27			NO ASBESTOS DETECTED				60 - 70
06 B	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	M/O 119	062012RG28			NO ASBESTOS DETECTED				60 - 70
06 C	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	HALL @102	062012RG29			NO ASBESTOS DETECTED				60 - 70
06 D	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	ROOM 100	062012RG30			NO ASBESTOS DETECTED				60 - 70
06 E	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	ROOM 103	062012RG31			NO ASBESTOS DETECTED				60 - 70
06 F	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	ROOM 203	062012RG32			NO ASBESTOS DETECTED				60 - 70
06 G	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	ROOM 205	062012RG33			NO ASBESTOS DETECTED				60 - 70
06 H	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	ROOM 119F	062012RG34			NO ASBESTOS DETECTED				60 - 70
06 I	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	ROOM 102	062012RG35			NO ASBESTOS DETECTED				60 - 70
07 A	KIA	WHITE/TAN 1'X1' CEILING TILE	HALL @100	062012RG36			NO ASBESTOS DETECTED				20 - 25
07 B	KIA	WHITE/TAN 1'X1' CEILING TILE	HALL @102	062012RG37			NO ASBESTOS DETECTED				20 - 25
07 C	KIA	WHITE/TAN 1'X1' CEILING TILE	HALL @103	062012RG38			NO ASBESTOS DETECTED				20 - 25
07 D	KIA	WHITE/TAN 1'X1' CEILING TILE	HALL @202	062012RG39			NO ASBESTOS DETECTED				20 - 25

Report Continued on Next Page

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG A

Work Order: T1206102

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	CHRY	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS
						AMOS	CROC	TREM	ANTH	OTHER	
07 E	KIA	WHITE/TAN 1'X1' CEILING TILE	HALL@203	062012RG40		NO ASBESTOS DETECTED					20 - 25
07 F	KIA	WHITE/TAN 1'X1' CEILING TILE	HALL @205	062012RG41		NO ASBESTOS DETECTED					20 - 25
07 G	KIA	WHITE/TAN 1'X1' CEILING TILE	HALL @212	062012RG42		NO ASBESTOS DETECTED					20 - 25
08 A	KIA	BEIGE/GREEN EXT. STUCCO W/APINT	FLR 1 @NE CORNER	062012RG43		NO ASBESTOS DETECTED					1 - 2
08 B	KIA	BEIGE/GREEN EXT. STUCCO W/APINT	FLR 1 @NE WALL	062012RG44		NO ASBESTOS DETECTED					1 - 2
08 C	KIA	BEIGE/GREEN EXT. STUCCO W/APINT	FLR 1 @SE DOOR	062012RG45		NO ASBESTOS DETECTED					1 - 2
08 D	KIA	BEIGE/GREEN EXT. STUCCO W/APINT	FLR 1 @EAST ENTRY	062012RG46		NO ASBESTOS DETECTED					1 - 2
08 E	KIA	BEIGE/GREEN EXT. STUCCO W/APINT	FLR 1 @FRONT NW	062012RG47		NO ASBESTOS DETECTED					1 - 2
08 F	KIA	BEIGE/GREEN EXT. STUCCO W/APINT	FLR 1 @NW DOOR	062012RG48		NO ASBESTOS DETECTED					1 - 2
08 G	KIA	BEIGE/GREEN EXT. STUCCO W/APINT	FLR 1 @WEST DOOR	062012RG49		NO ASBESTOS DETECTED					1 - 2
08 H	KIA	BEIGE/GREEN EXT. STUCCO W/APINT	FLR 1 @NW FIRE ESC	062012RG50		NO ASBESTOS DETECTED					1 - 2
09 A	KIA	BEIGE/GREEN EXT. STUCCO W/APINT	FLR 2 @NE FIRE ESC	062012RG51		NO ASBESTOS DETECTED					1 - 2
09 B	KIA	BEIGE/GREEN EXT. STUCCO W/APINT	FLR 2 @NW FIRE ESC	062012RG52		NO ASBESTOS DETECTED					1 - 2
09 C	KIA	BEIGE/GREEN EXT. STUCCO W/APINT	FLR 2 @WEST WALKWAY	062012RG53		NO ASBESTOS DETECTED					1 - 2

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG A

Work Order: T1206102

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS						%NON-ASB FIBERS
					CHRY	AMOS	CROC	TREM	ANTH	OTHER	
10 A	KIA	GREY WINDOW GLAZING	FLR 1 @NW FRONT	062012RG54	NO ASBESTOS DETECTED						1 - 2
10 B	KIA	GREY WINDOW GLAZING	FLR 1 @NE ENTRY	062012RG55	NO ASBESTOS DETECTED						0 - 0



Quality Control Officer

Analytical results pertain only to the sample(s) analyzed. All Samples analyzed were acceptable for analysis.

ABBREVIATIONS:
 ANA = Analyst; ASB = Asbestos; CHRY = Chrysotile; AMOS = Amosite; CROC = Crocidolite; TERM = Term/Act; ANTH = Anthophyllite;
 ACT = Actinolite; AL = Aluminum; BLK = Black; BACK = Backing; BL = Blue; BRN = Brown; C = Cellulose; CALC = Calcareous; CPT = Carpet; CTL = Ceiling Tile;
 CEM = Cement; COV = Cover; DEB = Debris; FG = Fiberglass; FIB = Fibrous; MAS = Mastic; MAT = Material; MIC = Micaceous; MW = Mineral Wool; ORG = Orange;
 PAI = Paint; PAP = Paper; PL = Plaster; PLAS = Plastic; PWDR = Powder; RCF = Refractory Ceramic Fiber; RUB = Rubber; SIL = Silver; SR = Sheet Rock; S = Synthetic;
 SUB = Substance; TEXT = Textured; TR = Trace; TRAN = Transite; TERM = Tremolite; VERM = Vermiculite; VYL = Vinyl; W = Wollastonite; WH = White; YEL = Yellow.



EE&G Environmental Services, LLC
 5751 Miami Lakes Drive East
 Miami Lakes, Florida 33014

TT206102

1/4

BULK TRANSMITTAL FORM CHAIN OF CUSTODY

CLIENT: CH2M HILL

CLIENT CONTACT: ANDREW SMYTH

DATE COLLECTED: 062012

DATE SENT: 062512

STOP AT FIRST POSITIVE: Y N (circle one)

PROJECT: GLYNN ARCHER ES: BLDG A

PROJECT NO./BILL GROUP: 2012-2373/IH

PROJECT PHASE: ACM SURV

DATE VERBAL NEEDED: 0706

DATE WRITTEN NEEDED: 0206PM

SAMPLE PREFIX 062012Re

SAMPLE NUMBER	COLOR	SAMPLE DESCRIPTION	SAMPLE LOCATION
1. <u>01</u>	<u>grey/brown</u>	<u>plaster system</u>	<u>hall ceiling 6 102</u>
2. <u>2</u>			<u>entry</u>
3. <u>3</u>			<u>100/103</u>
4. <u>4</u>			<u>hall wall 8 103</u>
5. <u>5</u>			<u>office</u>
6. <u>6</u>			<u>wall girls room</u>
7. <u>7</u>			<u>wall in room 100</u>
8. <u>8</u>			
9. <u>9</u>			
10. <u>10</u>			<u>103</u>
11. <u>11</u>			<u>112G</u>
12. <u>12</u>			<u>202</u>
13. <u>13</u>			<u>205</u>
14. <u>14</u>			<u>203</u>
15. <u>15</u>			<u>204</u>
16. <u>16</u>			<u>212</u>
17. <u>17</u>			<u>200</u>
18. <u>18</u>			<u>213</u>
19. <u>19</u>			<u>hall NW</u>
20. <u>20</u>			<u>hall SE</u>
			<u>boys 124</u>
			<u>ceiling 6 212</u>

CHAIN OF CUSTODY:
DATE/TIME

062012

062012

PRINT NAME/SIGNATURE

[Handwritten Signature]

PURPOSE

RECEIVED

JUN 26 2012

C T A

C T A

[Handwritten Signature]

C= Collection T= Transportation A= Analysis



CONTINUATION OF
BULK TRANSMITTAL FORM
CHAIN OF CUSTODY

Trn 664

CLIENT: CH2M Hill

SAMPLE PREFIX 062012P6

PROJECT NO./BILL GROUP: 237314 SUPV

SAMPLE NUMBER	COLOR	SAMPLE DESCRIPTION	SAMPLE LOCATION
1. <u>21</u>	<u>white/red</u>	<u>2x4' dot furrow red brick CT</u>	<u>hall @ 102</u>
2. <u>22</u>			<u>hall @ MANOF</u>
3. <u>23</u>			<u>hall @ 100</u>
4. <u>24</u>			<u>hall @ 102</u>
5. <u>25</u>			<u>hall @ 124</u>
6. <u>26</u>	<u>white</u>	<u>2x4' dot dot CT</u>	<u>man office #119</u>
7. <u>27</u>	<u>white</u>	<u>2x4 dot furrow CT</u>	<u>girls room</u>
8. <u>28</u>			<u>M/O 119</u>
9. <u>29</u>			<u>hall @ 102</u>
10. <u>30</u>			<u>Rm 102</u>
11. <u>31</u>			<u>Rm 103</u>
12. <u>32</u>			<u>Rm 203</u>
13. <u>33</u>			<u>Rm 205</u>
14. <u>34</u>			<u>Rm 119E</u>
15. <u>35</u>			<u>Rm 102</u>
16. <u>36</u>	<u>white/tan</u>	<u>1x1' striped CT</u>	<u>hall @ 100</u>
17. <u>37</u>			<u>102</u>
18. <u>38</u>			<u>103</u>
19. <u>39</u>			<u>202</u>
20. <u>40</u>			<u>203</u>
21. <u>41</u>			<u>Rm 205</u>
22. <u>42</u>			<u>Rm 212</u>
23. <u>43</u>	<u>beige/green</u>	<u>ext. stucco w/paint</u>	<u>Fir 1 @ NE corner</u>
24. <u>44</u>			<u>1 @ NE well</u>
25. <u>45</u>			<u>@ SE door</u>
26. <u>46</u>			<u>@ E entry</u>
27. <u>47</u>			<u>@ front NW</u>
28. <u>48</u>			<u>@ NW door</u>
29. <u>49</u>			<u>@ W door</u>
30. <u>50</u>			<u>@ NW fire esc</u>
31. <u>51</u>			<u>2 @ NE fire ESC</u>
32. <u>52</u>			<u>2 @ NW fire esc</u>
33. <u>53</u>			<u>2 @ WW walkway</u>
34. <u>54</u>	<u>grey</u>	<u>window pane glazing</u>	<u>Fir 1 NW front</u>
35. <u>55</u>			<u>@ NE entry</u>

CHAIN OF CUSTODY:
DATE/TIME

062012

062512

PRINT NAME/SIGNATURE

[Handwritten Signature]

RECEIVED	PURPOSE
	<u>C T A</u>
	<u>C T A</u>
	<u>C T A</u>

C = Collection T = Transportation A = Analysis

REPORT

SENT CH2M HILL

TO: 6410 5TH STREET, SUITE 2A
KEY WEST, FL 33040
ANDREW SMYTH

Phone: 305-294-1645 **Fax:** 305-294-4913

Email: asmyth@ch2m.com

Thank you for your business.

PREPARED AAL

BY: Asbestos Department
5005 WEST LAUREL STREET
SUITE 110
TAMPA, FL 33607
NVLAP Code 101775
(813) 287-1005

Analysis: Polarized Light Microscopy (PLM) with dispersion staining techniques according to the United States (US) Environmental Protection Agency (EPA) "Method for the Determination of Asbestos in Bulk Building Materials", EPA/600/R-93-116, July 1993.

Sample Type: BULK

of Samples: 66

Work Order# T1206103

AAL Project# 2012-2373

Project: GLYNN ARCHER ES: BLDG A

Date in: Tuesday, June 26, 2012

Date out: Thursday, Jun 28 2012

Transported: FEDEX

Sampled by: R.G.

Received by: KIA



Authorized Analyst
KHANDAKER ANAM



Laboratory Manager
KHANDAKER ANAM

Due to the small size of asbestos fibers associated with vinyl floor tiles, TEM analysis is recommended for all floor tiles containing <1% or no detectable asbestos by visual estimation.

This report may not be reproduced except in full, without the written approval of AAL. AAL will not be held responsible for the use of its reports issued in part to third parties or authorized agents of the client.

This report shall not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All NVLAP reports displaying NVLAP logo must have at least one signature to be valid.

The following analytical results presented in this report pertain only to the samples analyzed. American Asbestos Laboratories assumes no responsibility for whether the samples accurately represent the material in question

LABORATORY BULK SAMPLE ANALYSIS REPORT

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG A

Work Order: T1206103

Samples were analyzed in accordance with the Interim Method as described in 40 CFR, Part 763, Vol. 52, No. 210

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM	ANTH		OTHER
01 A	KIA	BROWN VINYL BASEBOARD & GLUE	STAIR TREADS NW	062012RG56			NO ASBESTOS DETECTED				1 - 2
02 A	KIA	BLUE VINYL BASEBOARD & GLUE	ROOM 102	062012RG57			NO ASBESTOS DETECTED IN BEIGE/BLACK GLUE				1 - 2
03 A	KIA	TAN 12"X12" VFT & BLACK MASTIC	1 HALL @103	062012RG58			NO ASBESTOS DETECTED				1 - 2
		*Comments:	NO ASBESTOS DETECTED IN YELLOW GLUE				2-5% CHRYSOTILE DETECTED IN BLACK MASTIC				
03 B	KIA	TAN 12"X12" VFT	1 HALL @WEST FRONT	062012RG59			NO ASBESTOS DETECTED				1 - 2
		*Comments:	NO BLACK MASTIC PRESENT				NO ASBESTOS DETECTED IN YELLOW GLUE				
03 C	KIA	TAN 12"X12" VFT	1 HALL @ M/OFFICE	062012RG60			NO ASBESTOS DETECTED				1 - 2
		*Comments:	NO BLACK MASTIC PRESENT				NO ASBESTOS DETECTED IN YELLOW GLUE				
03 D	KIA	TAN 12"X12" VFT	2 FLR HALL @205	062012RG61			NO ASBESTOS DETECTED				1 - 2
		*Comments:	NO BLACK MASTIC PRESENT				NO ASBESTOS DETECTED IN YELLOW GLUE				
03 E	KIA	TAN 12"X12" VFT	2 FLR HALL @202	062012RG62			NO ASBESTOS DETECTED				1 - 2
		*Comments:	NO BLACK MASTIC PRESENT				NO ASBESTOS DETECTED IN YELLOW GLUE				

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG A

Work Order: T1206103

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM	ANTH		OTHER
03 F	KIA	TAN 12"X12" VFT	2 FLR HALL @204	062012RG63			NO ASBESTOS DETECTED				1 - 2
*Comments: NO BLACK MASTIC PRESENT											
04 A	KIA	BLACK VFT	1 HALL @103	062012RG584	2 - 5		NO ASBESTOS DETECTED IN BLACK FELT				1 - 2
04 B	KIA	BLACK VFT	1 HALL @ M/OFFICE	062012RG604	-		STOP AT FIRST POSITIVE, NOT ANALYZED				0 - 0
04 C	KIA	BLACK VFT	2 FLR HALL @202	062012RG624	-		STOP AT FIRST POSITIVE, NOT ANALYZED				0 - 0
04 D	KIA	BLACK VFT	2 FLR HALL @204	062012RG634	-		STOP AT FIRST POSITIVE, NOT ANALYZED				0 - 0
05 A	KIA	BROWN CEILING TILE BOARD	1 HALL @WEST FRONT	062012RG594			NO ASBESTOS DETECTED				20 - 25
06 A	KIA	BROWN VFT	2 FLR HALL @205	062012RG614	2 - 5						1 - 2
07 A	KIA	BEIGE 12"X12" VFT	FLR 1 HALL @MAIN	062012RG64			NO ASBESTOS DETECTED				1 - 2
07 B	KIA	BEIGE 12"X12" VFT	FLR 1 HALL @WFTN	062012RG65			NO ASBESTOS DETECTED				1 - 2
NO ASBESTOS DETECTED IN YELLOW GLUE											

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG A

Work Order: T1206103

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	CHRY	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS
						AMOS	CROC	TREM	ANTH	OTHER	
07 C	KIA	BEIGE 12"X12" VFT	FLR 1 HALL @103	062012RG66		NO ASBESTOS DETECTED	NO ASBESTOS DETECTED	NO ASBESTOS DETECTED	NO ASBESTOS DETECTED	NO ASBESTOS DETECTED	1 - 2
08 A	KIA	BLACK VFT	FLR 1 HALL @MAIN	062012RG64A	2 - 5						1 - 2
08 B	KIA	BLACK VFT	FLR 1 HALL @103	062012RG66A	-						0 - 0
09 A	KIA	BLACK FELT	FLR 1 HALL @MAIN	062012RG64B		STOP AT FIRST POSITIVE, NOT ANALYZED					10 - 15
09 B	KIA	BLACK FELT	FLR 1 HALL @103	062012RG66B							10 - 15
10 A	KIA	BROWN CEILING TILE BOARD	FLR 1 HALL @WFTN	062012RG65A							20 - 25
11 A	KIA	BEIGE 12"X12" VFT	FLR 2 HALL @NW	062012RG67		NO ASBESTOS DETECTED	NO ASBESTOS DETECTED	NO ASBESTOS DETECTED	NO ASBESTOS DETECTED	NO ASBESTOS DETECTED	1 - 2
11 B	KIA	BEIGE 12"X12" VFT	FLR 2 HALL @CENTER	062012RG68		NO ASBESTOS DETECTED	NO ASBESTOS DETECTED	NO ASBESTOS DETECTED	NO ASBESTOS DETECTED	NO ASBESTOS DETECTED	1 - 2
11 C	KIA	BEIGE 12"X12" VFT	FLR 2 HALL @SE	062012RG69		NO ASBESTOS DETECTED	NO ASBESTOS DETECTED	NO ASBESTOS DETECTED	NO ASBESTOS DETECTED	NO ASBESTOS DETECTED	1 - 2
12 A	KIA	BROWN VFT & BLACK FELT	FLR 2 HALL @NW	062012RG67A	2 - 5						1 - 2
						NO ASBESTOS DETECTED	NO ASBESTOS DETECTED	NO ASBESTOS DETECTED	NO ASBESTOS DETECTED	NO ASBESTOS DETECTED	

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG A

Work Order: T1206103

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM	ANTH		OTHER
13 A	KIA	BLACK VFT	FLR 2 HALL @CENTER	062012RG684	5 - 10						1 - 2
13 B	KIA	BLACK VFT	FLR 2 HALL @SE	062012RG694	-						10 - 15
STOP AT FIRST POSITIVE, NOT ANALYZED											
14 A	KIA	WHITE 12"X12" VFT & GLUE	ROOM 200	062012RG70			NO ASBESTOS DETECTED				1 - 2
15 A	KIA	LIGHT GREEN 9"X9" VFT & MASTIC	FLR 1 A	062012RG71	2 - 5		NO ASBESTOS DETECTED IN BLACK MASTIC/FELT				1 - 2
16 A	KIA	TAN 12"X12" RED STRIPE VFT & GLUE	ROOM 103A	062012RG72			NO ASBESTOS DETECTED				1 - 2
16 B	KIA	TAN 12"X12" RED STRIPE VFT & GLUE	ROOM 122A	062012RG73			NO ASBESTOS DETECTED IN YELLOW GLUE				1 - 2
16 C	KIA	TAN 12"X12" RED STRIPE VFT & GLUE	ROOM 120	062012RG74			NO ASBESTOS DETECTED IN YELLOW GLUE				1 - 2
16 D	KIA	TAN 12"X12" RED STRIPE VFT & GLUE	ROOM 202	062012RG75			NO ASBESTOS DETECTED				1 - 2
16 E	KIA	TAN 12"X12" RED STRIPE VFT & GLUE	ROOM 203	062012RG76			NO ASBESTOS DETECTED IN YELLOW GLUE				1 - 2

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG A

Work Order: T1206103

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	CHRY	PERCENT ASBESTOS FIBERS				%NON-ASB FIBERS	
						AMOS	CROC	TREM	ANTH		OTHER
16 F	KIA	TAN 12"X12" RED STRIPE VFT & GLUE	ROOM 213	062012RG77		NO ASBESTOS DETECTED					1 - 2
17 A	KIA	GREEN 12"X12" VFT & BLACK FELT	ROOM 102	062012RG78	2 - 5	NO ASBESTOS DETECTED IN BLACK FELT					1 - 2
17 B	KIA	GREEN 12"X12" VFT & BLACK FELT	ROOM 212	062012RG79		NO ASBESTOS DETECTED					1 - 2
*Comments: NO BLACK FELT PRESENT											
18 A	KIA	LT GREEN VFT & BLACK FELT	ROOM 212	062012RG79A	2 - 5	NO ASBESTOS DETECTED IN BLACK FELT					1 - 2
19 A	KIA	LIGHT BLUE 12"X12" VFT & GLUE	ROOM 100	062012RG80		NO ASBESTOS DETECTED					1 - 2
19 B	KIA	LIGHT BLUE 12"X12" VFT & GLUE	ROOM 119 M/O	062012RG81		NO ASBESTOS DETECTED					1 - 2
20 A	KIA	TAN VFT & YELLOW GLUE	ROOM 100	062012RG80A		NO ASBESTOS DETECTED					1 - 2
21 A	KIA	BLUE 12"X12" VFT & GLUE	ROOM A	062012RG82		NO ASBESTOS DETECTED					1 - 2
21 B	KIA	BLUE 12"X12" VFT & GLUE	ROOM 119	062012RG83		NO ASBESTOS DETECTED					1 - 2

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES. BLDG A

Work Order: T1206103

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM	ANTH		OTHER
22 A	KIA	TAN VFT & YELLOW GLUE	ROOM A	062012RG824			NO ASBESTOS DETECTED				1 - 2
23 A	KIA	CREAM 9"X9" VFT W/MASTIC	ROOM 204	062012RG84	2 - 5		NO ASBESTOS DETECTED IN YELLOW GLUE				1 - 2
23 B	KIA	CREAM 9"X9" VFT W/MASTIC	ROOM 205	062012RG85	-		NO ASBESTOS DETECTED IN BLACK MASTIC/FELT				0 - 0
24 A	KIA	GREEN 9"X9" VFT W/MASTIC	ROOM 204	062012RG86	2 - 5		STOP AT FIRST POSITIVE, NOT ANALYZED				0 - 0
25 A	KIA	PINK 9"X9" VFT W/MASTIC	ROOM 205	062012RG87	2 - 5		NO ASBESTOS DETECTED IN BLACK MASTIC				1 - 2
26 A	KIA	LIGHT GREEN 9"X9" VFT & MASTIC	ROOM 119F U/C	062012RG88	2 - 5		NO ASBESTOS DETECTED IN BLACK MASTIC/FELT				1 - 2
27 A	KIA	DARK TAN 12"X12" VFT & GLUE	ROOM 120	062012RG89			NO ASBESTOS DETECTED				1 - 2
28 A	KIA	GREY/AQUA 12"X12" VFT & GLUE	ROOM 103A	062012RG90			NO ASBESTOS DETECTED IN YELLOW GLUE				1 - 2

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG A

Work Order: T1206103

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM	ANTH		OTHER
29 A	KIA	WHITE 12"X12" VFT & GLUE	ROOM 212	062012RG91			NO ASBESTOS DETECTED				1 - 2
30 A	KIA	LT GREEN VFT & BLACK FELT	ROOM 212	062012RG91A	2 - 5		NO ASBESTOS DETECTED IN BLACK FELT				1 - 2
31 A	KIA	SKY BLUE 12"X12" VFT & GLUE	ROOM 100	062012RG92			NO ASBESTOS DETECTED				1 - 2
32 A	KIA	TAN VFT & YELLOW GLUE	ROOM 100	062012RG92A			NO ASBESTOS DETECTED				1 - 2
33 A	KIA	BLACK/GREY FELT FIELD MEMBRANE	SOUTH CENTER	062012RG93			NO ASBESTOS DETECTED				5 - 10
33 B	KIA	BLACK/GREY FELT FIELD MEMBRANE	ROOF NORTH	062012RG94			NO ASBESTOS DETECTED				5 - 10
33 C	KIA	BLACK/GREY FELT FIELD MEMBRANE	ROOF CENTER	062012RG95			NO ASBESTOS DETECTED				10 - 20
34 A	KIA	BLACK/GREY EDGE FLASHING	SOUTH EDGE	062012RG96			NO ASBESTOS DETECTED				10 - 20
35 A	KIA	BLACK/GREY VTR FLASHING	NORTHEAST	062012RG97			NO ASBESTOS DETECTED				10 - 20
36 A	KIA	BLACK/GREY CAP FLASHING/SEALANT	SOUTHEAST WALL	062012RG98	5 - 10						5 - 10
36 B	KIA	BLACK/GREY CAP FLASHING/SEALANT	NORTHEAST WALL	062012RG99	5 - 10						5 - 10

CLIENT: CH2M HILL
PROJECT: GLYNN ARCHER ES: BLDG A
Work Order: T1206103

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	CHRY	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS
						AMOS	CROC	TREM	ANTH	OTHER	
36 C	KIA	BLACK/GREY CAP FLASHING/SEALANT	NORTH WALL	062012RG100	5 - 10						5 - 10
37 A	KIA	BROWN CEILING TILE GLUE	ROOM A200	062012RG101		NO ASBESTOS DETECTED					1 - 2
37 B	KIA	BROWN CEILING TILE GLUE	ROOM A200	062012RG102		NO ASBESTOS DETECTED					1 - 2



Quality Control Officer

Analytical results pertain only to the sample(s) analyzed. All Samples analyzed were acceptable for analysis.

ABBREVIATIONS: ANA = Analyst; ASB = Asbestos; CHRY = Chrysotile; AMOS = Amosite; CROC = Crocidolite; TERM = Term/Act; ANTH = Anthophyllite; ACT = Actinolite; AL = Aluminum; BLK = Black; BACK = Backing; BL = Blue; BRN = Brown; C = Cellulose; CALC = Calcareous; CPT = Carpet; CTL = Ceiling Tile; CEM = Cement; COV = Cover; DEB = Debris; FG = Fiberglass; FIB = Fibrous; MAS = Mastic; MAT = Material; MIC = Micaceous; MW = Mineral Wool; ORG = Orange; PAI = Paint; PAP = Paper; PL = Plaster; PLAS = Plastic; PWDR = Powder; RCF = Refractory Ceramic Fiber; RUB = Rubber; SIL = Silver; SR = Sheet Rock; S = Synthetic; SUB = Substance; TEXT = Textured; TR = Trace; TRAN = Transite; TERM = Tremolite; VERM = Vermiculite; VYL = Vinyl; W = Wollastonite; WH = White; YEL = Yellow.



CONTINUATION OF
BULK TRANSMITTAL FORM
CHAIN OF CUSTODY

TID 06103
Page 3 of 4

CLIENT: CH2M HILL

SAMPLE PREFIX 062012

PROJECT NO./BILL GROUP: 2-2373 IH SUP

SAMPLE NUMBER	COLOR	SAMPLE DESCRIPTION	SAMPLE LOCATION
1. 56	brown	vinyl baseboard + glue	stair treads NW
2. 57	blue	↓ ↓ ↓	Rm 102
3. 58	tan	12x12" speckled VFT + mastic	hall @ 103
4. 59	↓	↓ ↓ ↓	hall E WFNT
5. 60	↓	↓ ↓ ↓	hall E W/OFF
6. 61	↓	↓ ↓ ↓	2nd hall @ 205
7. 62	↓	↓ ↓ ↓	↓ ↓ ↓ 202
8. 63	↓	↓ ↓ ↓	↓ ↓ ↓ 204
9. 64	beige	12" speckled VFT + mastic	Flr 1 hall @ main
10. 65	↓	↓ ↓ ↓	↓ ↓ ↓ SWFTN
11. 66	↓	↓ ↓ ↓	↓ ↓ ↓ @ 103
12. 67	↓	↓ ↓ ↓	Flr 2 hall @ NW
13. 68	↓	↓ ↓ ↓	↓ ↓ ↓ C
14. 69	↓	↓ ↓ ↓	↓ ↓ ↓ SE
15. 70	white	12" VFT + glue	Rm 200
16. 71	light green	9" VFT + mastic	Flr 1 A
17. 72	tan	12" red stripe VFT + glue	Rm 103 A
18. 73	↓	↓ ↓ ↓	Rm 122 A
19. 74	↓	↓ ↓ ↓	Rm 120
20. 75	↓	↓ ↓ ↓	Rm 202
21. 76	↓	↓ ↓ ↓	↓ 203
22. 77	↓	↓ ↓ ↓	↓ 213
23. 78	green	12x12 VFT + black felt	Rm 102
24. 79	↓	↓ ↓ ↓	Rm 212
25. 80	light blue	12" VFT + glue	Rm 100
26. 81	↓	↓ ↓ ↓	↓ 119 M/O
27. 82	blue	12" VFT + glue	Rm A
28. 83	↓	↓ ↓ ↓	Rm 119
29. 84	cream	9x9" VFT w/mastic	Rm 204
30. 85	↓	↓ ↓ ↓	Rm 205
31. 86	green	↓ ↓ ↓	Rm 204
32. 87	pink	↓ ↓ ↓	Rm 205
33. 88	light green	↓ ↓ ↓	Rm 119 F U/C
34. 89	dark tan	12" VFT + glue	Rm 120
35. 90	grey/aqua	12" VFT + glue	Rm 103

CHAIN OF CUSTODY:
DATE/TIME
062012
062012

PRINT NAME/SIGNATURE

RECEIVED PURPOSE
CIT A
CIT A
CIT A

2012 JUN 26 11:19

C= Collection T= Transportation A= Analysis



CONTINUATION OF BULK TRANSMITTAL FORM CHAIN OF CUSTODY

CLIENT: CH2MHILL

SAMPLE PREFIX: 06201216


PROJECT NO./BILL GROUP: 2-2373 IH

SAMPLE NUMBER	COLOR	SAMPLE DESCRIPTION	SAMPLE LOCATION	
1. 06201216				
2. 91	white	12" VFTS glue	Rm 212	
3. 92	sky blue	12" VFT glue	Rm 100	
4.				
5. 93	blk grey	felt field memb	South Center	
6. 94	↓		roof north	
7. 95			roof center	
8. 96			south edge	
9. 97			edge flashing	NE
10. 98			VTR flashing	SE wall
11. 99			cap flash/sealant	NE
12. 100				N ↓
13.				
14.				
15.				
16.				
17.				
18.				
19.				
20.				
21.				
22.				
23.				
24.				
25.				
26.				
27.				
28.				
29.				
30.				
31.				
32.				
33.				
34.				
35.				

CHAIN OF CUSTODY: DATE/TIME 062012 062012

PRINT NAME/SIGNATURE [Signature]

C= Collection T= Transportation A= Analysis



REPORT

SENT CH2M HILL

TO: 6410 5TH STREET, SUITE 2A
KEY WEST, FL 33040
ANDREW SMYTH

Phone: 305-294-1645 **Fax:** 305-294-4913

Email: asmyth@ch2m.com

Thank you for your business.

PREPARED AAL

BY: Asbestos Department
5005 WEST LAUREL STREET
SUITE 110
TAMPA, FL 33607
NVLAP Code 101775
(813) 287-1005

Analysis: Polarized Light Microscopy (PLM) with dispersion staining techniques according to the United States (US) Environmental Protection Agency (EPA) "Method for the Determination of Asbestos in Bulk Building Materials", EPA/600/R-93-116, July 1993.

Sample Type: BULK

of Samples: 59

Work Order# T1206105

AAL Project# 2012-2373

Project: GLYNN ARCHER ES: BLDG B

Date in: Thursday, June 28, 2012

Date out: Monday, Jul 2 2012

Transported: FEDEX

Sampled by: R.G.

Received by: KIA



Authorized Analyst
KHANDAKER ANAM



Laboratory Manager
KHANDAKER ANAM

Due to the small size of asbestos fibers associated with vinyl floor tiles, TEM analysis is recommended for all floor tiles containing <1% or no detectable asbestos by visual estimation.

This report may not be reproduced except in full, without the written approval of AAL. AAL will not be held responsible for the use of its reports issued in part to third parties or authorized agents of the client.

This report shall not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All NVLAP reports displaying NVLAP logo must have at least one signature to be valid.

The following analytical results presented in this report pertain only to the samples analyzed. American Asbestos Laboratories assumes no responsibility for whether the samples accurately represent the material in question

LABORATORY BULK SAMPLE ANALYSIS REPORT

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG B

Work Order: T1206105

Samples were analyzed in accordance with the Interim Method as described in 40 CFR, Part 763, Vol. 52, No. 210

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM	ANTH		OTHER
01 A	KIA	GREY/WHITE PLASTER SYSTEM	WALL ROOM 104	062112RG01			NO ASBESTOS DETECTED				1 - 2
01 B	KIA	GREY/WHITE PLASTER SYSTEM	WALL ROOM 105	062112RG02			NO ASBESTOS DETECTED				1 - 2
01 C	KIA	GREY/WHITE PLASTER SYSTEM	WALL ROOM 106	062112RG03			NO ASBESTOS DETECTED				1 - 2
01 D	KIA	GREY/WHITE PLASTER SYSTEM	WALL ROOM 107	062112RG04			NO ASBESTOS DETECTED				1 - 2
01 E	KIA	GREY/WHITE PLASTER SYSTEM	WALL ROOM 108	062112RG05			NO ASBESTOS DETECTED				1 - 2
01 F	KIA	GREY/WHITE PLASTER SYSTEM	WALL ROOM 109B	062112RG06			NO ASBESTOS DETECTED				1 - 2
02 A	KIA	GREY/WHITE PLASTER SYSTEM	CEILING OVER @104	062112RG07			NO ASBESTOS DETECTED				1 - 2
02 B	KIA	GREY/WHITE PLASTER SYSTEM	CEILING OVER @LOBBY	062112RG08			NO ASBESTOS DETECTED				1 - 2
02 C	KIA	GREY/WHITE PLASTER SYSTEM	CEILING OVER @N. HALL	062112RG09			NO ASBESTOS DETECTED				1 - 2
03 A	KIA	GREY/WHITE PLASTER SYSTEM	WALL ROOM 206	062112RG10			NO ASBESTOS DETECTED				1 - 2
03 B	KIA	GREY/WHITE PLASTER SYSTEM	WALL ROOM 207	062112RG11			NO ASBESTOS DETECTED				1 - 2
03 C	KIA	GREY/WHITE PLASTER SYSTEM	WALL ROOM 208	062112RG12			NO ASBESTOS DETECTED				1 - 2

Monday, July 02, 2012

Page 2 of 5

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG B

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Work Order: T1206105

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM	ANTH		OTHER
03 D	KIA	GREY/WHITE PLASTER SYSTEM	WALL ROOM 209	062112RG13			NO ASBESTOS DETECTED				1 - 2
03 E	KIA	GREY/WHITE PLASTER SYSTEM	WALL ROOM 210	062112RG14			NO ASBESTOS DETECTED				1 - 2
03 F	KIA	GREY/WHITE PLASTER SYSTEM	WALL ROOM 215	062112RG15			NO ASBESTOS DETECTED				1 - 2
03 G	KIA	GREY/WHITE PLASTER SYSTEM	WALL ROOM 216	062112RG16			NO ASBESTOS DETECTED				1 - 2
03 H	KIA	GREY/WHITE PLASTER SYSTEM	WALL ROOM 217B	062112RG17			NO ASBESTOS DETECTED				1 - 2
03 I	KIA	GREY/WHITE PLASTER SYSTEM	WALL CORR CENTER	062112RG18			NO ASBESTOS DETECTED				1 - 2
04 A	KIA	GREY/WHITE PLASTER SYSTEM	CEILING HALL @209	062112RG19			NO ASBESTOS DETECTED				1 - 2
04 B	KIA	GREY/WHITE PLASTER SYSTEM	CEILING HALL @217	062112RG20			NO ASBESTOS DETECTED				1 - 2
04 C	KIA	GREY/WHITE PLASTER SYSTEM	CEILING HALL CENTER	062112RG21			NO ASBESTOS DETECTED				1 - 2
05 A	KIA	WHITE 2'X4' DOT FURROW REDBACK CT	HALL @108	062112RG22			NO ASBESTOS DETECTED				60 - 70
05 B	KIA	WHITE 2'X4' DOT FURROW REDBACK CT	HALL @109	062112RG23			NO ASBESTOS DETECTED				60 - 70
05 C	KIA	WHITE 2'X4' DOT FURROW REDBACK CT	HALL @108	062112RG24			NO ASBESTOS DETECTED				60 - 70
06 A	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	HALL @105	062112RG25			NO ASBESTOS DETECTED				60 - 70
06 B	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	HALL @104	062112RG26			NO ASBESTOS DETECTED				60 - 70

Report Continued on Next Page

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG B

Work Order: T1206105

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM	ANTH		OTHER
06 C	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	HALL @108	062112RG27			NO ASBESTOS DETECTED				60 - 70
06 D	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	HALL @109	062112RG28			NO ASBESTOS DETECTED				60 - 70
07 A	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	ROOM 105	062112RG29			NO ASBESTOS DETECTED				60 - 70
07 B	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	ROOM 108	062112RG30			NO ASBESTOS DETECTED				60 - 70
07 C	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	ROOM 121	062112RG31			NO ASBESTOS DETECTED				60 - 70
07 D	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	ROOM 204	062112RG32			NO ASBESTOS DETECTED				60 - 70
07 E	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	ROOM 207	062112RG33			NO ASBESTOS DETECTED				60 - 70
07 F	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	ROOM 208	062112RG34			NO ASBESTOS DETECTED				60 - 70
07 G	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	ROOM 215	062112RG35			NO ASBESTOS DETECTED				60 - 70
08 A	KIA	WHITE/BROWN 1'X1' DOT CEILING TILE	FLR 1 HALL ABOVE NW	062112RG36			NO ASBESTOS DETECTED				60 - 70
08 B	KIA	WHITE/BROWN 1'X1' DOT CEILING TILE	FLR 1 HALL ABOVE CENT	062112RG37			NO ASBESTOS DETECTED				20 - 25
08 C	KIA	WHITE/BROWN 1'X1' DOT CEILING TILE	FLR 1 HALL ABOVE SE	062112RG38			NO ASBESTOS DETECTED				20 - 25
08 D	KIA	WHITE/BROWN 1'X1' DOT CEILING TILE	ROOM 108	062112RG39			NO ASBESTOS DETECTED				20 - 25

Monday, July 02, 2012

Page 4 of 5

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG B

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Work Order: T1206105

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM	ANTH		OTHER
08 E	KIA	WHITE/BROWN 1'X1' DOT CEILING TILE	HALL @216	062112RG40			NO ASBESTOS DETECTED				20 - 25
08 F	KIA	WHITE/BROWN 1'X1' DOT CEILING TILE	HALL @211	062112RG41			NO ASBESTOS DETECTED				20 - 25
08 G	KIA	WHITE/BROWN 1'X1' DOT CEILING TILE	HALL @208	062112RG42			NO ASBESTOS DETECTED				20 - 25
08 H	KIA	WHITE/BROWN 1'X1' DOT CEILING TILE	HALL @207	062112RG43			NO ASBESTOS DETECTED				20 - 25
09 A	KIA	CREAM/GREEN EXT. STUCCO W/PAINT	FLR 1 SW	062112RG44			NO ASBESTOS DETECTED				1 - 2
09 B	KIA	CREAM/GREEN EXT. STUCCO W/PAINT	FLR 1 WEST ENTRY	062112RG45			NO ASBESTOS DETECTED				1 - 2
09 C	KIA	CREAM/GREEN EXT. STUCCO W/PAINT	FLR 1 WEST CENTER	062112RG46			NO ASBESTOS DETECTED				1 - 2
09 D	KIA	CREAM/GREEN EXT. STUCCO W/PAINT	FLR 1 EAST ENTRY	062112RG47			NO ASBESTOS DETECTED				1 - 2
09 E	KIA	CREAM/GREEN EXT. STUCCO W/PAINT	FLR 1 NORTH WALL	062112RG48			NO ASBESTOS DETECTED				1 - 2
09 F	KIA	CREAM/GREEN EXT. STUCCO W/PAINT	FLR 1 SE CORNER	062112RG49			NO ASBESTOS DETECTED				1 - 2
09 G	KIA	CREAM/GREEN EXT. STUCCO W/PAINT	FLR 2 SOUTH CENTER	062112RG50			NO ASBESTOS DETECTED				1 - 2
09 H	KIA	CREAM/GREEN EXT. STUCCO W/PAINT	FLR 2 SOUTHWEST	062112RG51			NO ASBESTOS DETECTED				1 - 2
09 I	KIA	CREAM/GREEN EXT. STUCCO W/PAINT	FLR 2 WEST WW	062112RG52			NO ASBESTOS DETECTED				1 - 2

Report Continued on Next Page

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG B

Work Order: T1206105

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	CHRY	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS
						AMOS	CROC	TREM	ANTH	OTHER	
10 A	KIA	TAN VINYL BASEBOARD & GLUE	ROOM 109	062112RG53		NO ASBESTOS DETECTED					1 - 2
10 B	KIA	TAN VINYL BASEBOARD & GLUE	ROOM 104	062112RG54		NO ASBESTOS DETECTED					1 - 2
10 C	KIA	TAN VINYL BASEBOARD & GLUE	ROOM 209	062112RG55		NO ASBESTOS DETECTED					1 - 2
10 D	KIA	TAN VINYL BASEBOARD & GLUE	ROOM 210	062112RG56		NO ASBESTOS DETECTED					1 - 2
11 A	KIA	GREY VINYL BASEBOARD & GLUE	ROOM 106	062112RG57		NO ASBESTOS DETECTED					1 - 2
12 A	KIA	BROWN VINYL BASEBOARD & GLUE	STAIRS NORTHEAST	062112RG58		NO ASBESTOS DETECTED					1 - 2
13 A	KIA	TAN VINYL BASEBOARD & GLUE	STAIRS NORTHEAST	062112RG584		NO ASBESTOS DETECTED					1 - 2



Quality Control Officer

Analytical results pertain only to the sample(s) analyzed. All Samples analyzed were acceptable for analysis.

ABBREVIATIONS: ANA = Analyst; ASB = Asbestos; CHRY = Chrysotile; AMOS = Amosite; CROC = Crocidolite; TERM = Termi/Act; ANTH = Anthophyllite; ACT = Actinolite; AL = Aluminum; BLK = Black; BACK = Backing; BL = Blue; BRN = Brown; C = Cellulose; CALC = Calcareous; CPT = Carpet; CTL = Ceiling Tile; CEM = Cement; COV = Cover; DEB = Debris; FG = Fiberglass; FIB = Fibrous; MAS = Mastic; MAT = Material; MIC = Micaeous; MW = Mineral Wool; ORG = Orange; PAI = Paint; PAP = Paper; PL = Plaster; PLAS = Plastic; PWDR = Powder; RCF = Refractory Ceramic Fiber; RUB = Rubber; SIL = Silver; SR = Sheet Rock; S = Synthetic; SUB = Substance; TEXT = Textured; TR = Trace; TRAN = Transite; TERM = Tremolite; VERM = Vermiculite; VYL = Vinyl; W = Wollastonite; WH = White; YEL = Yellow.

TT206105

13



EE&G Environmental Services, LLC
5751 Miami Lakes Drive East
Miami Lakes, Florida 33014

BULK TRANSMITTAL FORM CHAIN OF CUSTODY

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG B

CLIENT CONTACT: ANDREW SMYTH

PROJECT NO./BILL GROUP: 2012-2373/IH

DATE COLLECTED: 062112

PROJECT PHASE: ACM SURV

DATE SENT: 062612

DATE VERBAL NEEDED: 0706 PM

STOP AT FIRST POSITIVE: Y (circle one)

DATE WRITTEN NEEDED: 0706 PM

SAMPLE PREFIX 062112R0

SAMPLE NUMBER	COLOR	SAMPLE DESCRIPTION	SAMPLE LOCATION
1. <u>01</u>	<u>grey/white</u>	<u>plaster system</u>	<u>wall rm 104</u>
2. <u>2</u>			<u>105</u>
3. <u>3</u>			<u>106</u>
4. <u>4</u>			<u>107</u>
5. <u>5</u>			<u>108</u>
6. <u>6</u>			<u>109B</u>
7. <u>7</u>			<u>ceiling over 104</u>
8. <u>8</u>			<u>lobby</u>
9. <u>9</u>			<u>W hall</u>
10. <u>10</u>			<u>wall rm 206</u>
11. <u>11</u>			<u>207</u>
12. <u>12</u>			<u>208</u>
13. <u>13</u>			<u>209</u>
14. <u>14</u>			<u>210</u>
15. <u>15</u>			<u>215</u>
16. <u>16</u>			<u>216</u>
17. <u>17</u>			<u>217B</u>
18. <u>18</u>			<u>corr ceate</u>
19. <u>19</u>			<u>ceiling hall 209</u>
20. <u>20</u>			<u>217</u>
21. <u>21</u>			<u>center</u>

CHAIN OF CUSTODY:
DATE/TIME

PRINT NAME/SIGNATURE

PURPOSE

062112

[Signature]


C T A

062612

C T A

C T A

C= Collection T= Transportation A= Analysis





CONTINUATION OF
BULK TRANSMITTAL FORM
CHAIN OF CUSTODY

71206105

CLIENT: CH2M Hill

SAMPLE PREFIX 06211226

PROJECT NO./BILL GROUP: 2373/H

SAMPLE NUMBER	COLOR	SAMPLE DESCRIPTION	SAMPLE LOCATION
1. <u>22</u>	<u>white/grey</u>	<u>2x4' dot furrow redback CT</u>	<u>hall G 108</u>
2. <u>23</u>	↓	↓	↓ <u>E 109</u>
3. <u>24</u>	↓	↓	↓ <u>E 108</u>
4. <u>25</u>	<u>white</u>	<u>2x4' dot furrow CT</u>	<u>hall G 105</u>
5. <u>26</u>	↓	↓	↓ <u>E 104</u>
6. <u>27</u>	↓	↓	↓ <u>E 108</u>
7. <u>28</u>	↓	↓	↓ <u>E 109</u>
8. <u>29</u>	↓	↓	<u>Rm 105</u>
9. <u>30</u>	↓	↓	<u>108</u>
10. <u>31</u>	↓	↓	<u>(2)</u>
11. <u>32</u>	↓	↓	<u>204</u>
12. <u>33</u>	↓	↓	<u>207</u>
13. <u>34</u>	↓	↓	<u>208</u>
14. <u>35</u>	↓	↓	<u>215</u>
15. <u>36</u>	<u>wht/brn</u>	<u>1x1' dot CT</u>	<u>FLR 200 hall above Nce</u>
16. <u>37</u>	↓	↓	↓ <u>center</u>
17. <u>38</u>	↓	↓	↓ <u>SE</u>
18. <u>39</u>	↓	↓	<u>Rm 108</u>
19. <u>40</u>	↓	↓	<u>hall G 216</u>
20. <u>41</u>	↓	↓	↓ <u>211</u>
21. <u>42</u>	↓	↓	↓ <u>208</u>
22. <u>43</u>	↓	↓	↓ <u>207</u>
23. <u>44</u>	<u>green</u>	<u>exter. stucco w/paint</u>	<u>FLR 1 SW</u>
24. <u>45</u>	↓	↓	↓ <u>w entry</u>
25. <u>46</u>	↓	↓	↓ <u>w/center</u>
26. <u>47</u>	↓	↓	↓ <u>E entry</u>
27. <u>48</u>	↓	↓	↓ <u>N well</u>
28. <u>49</u>	↓	↓	↓ <u>SE corner</u>
29. <u>50</u>	↓	↓	<u>FLR 2 center</u>
30. <u>51</u>	↓	↓	↓ <u>SW</u>
31. <u>52</u>	↓	↓	↓ <u>west ww</u>
32. <u>53</u>	<u>tan</u>	<u>vinyl baseboard + glue</u>	<u>Rm 109</u>
33. <u>54</u>	↓	↓	↓ <u>109</u>
34. <u>55</u>	↓	↓	↓ <u>209</u>
35. <u>56</u>	↓	↓	↓ <u>210</u>

CHAIN OF CUSTODY:
DATE/TIME
062112
062612

PRINT NAME/SIGNATURE

RECEIVED
JUN 28 2012
PURPOSE
C T A
C T A
C T A

C= Collection T= Transportation A= Analysis

REPORT

SENT CH2M HILL

TO: 6410 5TH STREET, SUITE 2A
KEY WEST, FL 33040
ANDREW SMYTH

Phone: 305-294-1645 **Fax:** 305-294-4913
Email: asmyth@ch2m.com

Thank you for your business.

PREPARED AAL

BY: Asbestos Department
5005 WEST LAUREL STREET
SUITE 110
TAMPA, FL 33607
NVLAP Code 101775
(813) 287-1005

Analysis: Polarized Light Microscopy (PLM) with dispersion staining techniques according to the United States (US) Environmental Protection Agency (EPA) "Method for the Determination of Asbestos in Bulk Building Materials", EPA/600/R-93-116, July 1993.

Sample Type: BULK

of Samples: 53

Work Order# T1206106

AAL Project# 2012-2373

Project: GLYNN ARCHER ES: BLDG B

Date in: Thursday, June 28, 2012

Date out: Monday, Jul 2 2012

Transported: FEDEX

Sampled by: R.G.

Received by: KIA



Authorized Analyst
KHANDAKER ANAM



Laboratory Manager
KHANDAKER ANAM

Due to the small size of asbestos fibers associated with vinyl floor tiles, TEM analysis is recommended for all floor tiles containing <1% or no detectable asbestos by visual estimation.

This report may not be reproduced except in full, without the written approval of AAL. AAL will not be held responsible for the use of its reports issued in part to third parties or authorized agents of the client.

This report shall not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All NVLAP reports displaying NVLAP logo must have at least one signature to be valid.

The following analytical results presented in this report pertain only to the samples analyzed. American Asbestos Laboratories assumes no responsibility for whether the samples accurately represent the material in question

LABORATORY BULK SAMPLE ANALYSIS REPORT

CLIENT: CH2M HILL
PROJECT: GLYNN ARCHER ES: BLDG B
Work Order: T1206106

Samples were analyzed in accordance with the Interim Method as described in 40 CFR, Part 763, Vol. 52, No. 210

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM	ANTH		OTHER
01 A	KIA	TAN 12"X12" VFT & MASTIC	FLR 1 CORR SOUTHEAST	062112RG59			NO ASBESTOS DETECTED				1 - 2
01 B	KIA	TAN 12"X12" VFT & MASTIC	FLR 1 CORR SOUTHWEST	062112RG60			NO ASBESTOS DETECTED IN BROWN MASTIC				1 - 2
02 A	KIA	TAN 12"X12" VFT & MASTIC	FLR 2 CORR SOUTHEAST	062112RG61			NO ASBESTOS DETECTED				1 - 2
02 B	KIA	TAN 12"X12" VFT & MASTIC	FLR 2 CORR CENTER	062112RG62			2-5% CHRYSOTILE DETECTED IN BLACK MASTIC				1 - 2
02 C	KIA	TAN 12"X12" VFT & MASTIC	FLR 2 CORR SOUTHWEST	062112RG63			2-5% CHRYSOTILE DETECTED IN BLACK MASTIC				1 - 2
*Comments: NO BLACK MASTIC PRESENT											
03 A	KIA	BROWN VFT	FLR 2 CORR SOUTHEAST	062112RG61A	2 - 5		NO ASBESTOS DETECTED				1 - 2
03 B	KIA	BROWN VFT	FLR 2 CORR CENTER	062112RG62A			STOP AT FIRST POSITIVE, NOT ANALYZED				0 - 0
04 A	KIA	BEIGE 12"X12" VFT & GLUE	FLR 1 CORR NORTHEAST	062112RG64			NO ASBESTOS DETECTED				1 - 2
NO ASBESTOS DETECTED IN YELLOW GLUE											

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG B

Work Order: T1206106

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM	ANTH		OTHER
04 B	KIA	BEIGE 12"X12" VFT & GLUE	FLR 1 CORR NORTHWEST	062112RG65		NO ASBESTOS DETECTED					1 - 2
04 C	KIA	BEIGE 12"X12" VFT & GLUE	IN ROOM 104	062112RG66		NO ASBESTOS DETECTED					1 - 2
04 D	KIA	BEIGE 12"X12" VFT & GLUE	IN ROOM 105	062112RG67		NO ASBESTOS DETECTED					1 - 2
04 E	KIA	BEIGE 12"X12" VFT & GLUE	IN ROOM 106	062112RG68		NO ASBESTOS DETECTED					1 - 2
05 A	KIA	GREY LEVELLING COMPOUND & BROWN MAS	FLR 1 CORR NORTHEAST	062112RG64A		NO ASBESTOS DETECTED					1 - 2
05 B	KIA	GREY LEVELLING COMPOUND & BROWN MAS	IN ROOM 104	062112RG66A		NO ASBESTOS DETECTED					1 - 2
06 A	KIA	TAN VFT & BLACK MASTIC	IN ROOM 105	062112RG67A		NO ASBESTOS DETECTED					1 - 2
07 A	KIA	BEIGE 12"X12" VFT & GLUE	FLR 2 CORR SOUTHEAST	062112RG69		NO ASBESTOS DETECTED					1 - 2
*Comments: NO ASBESTOS DETECTED IN YELLOW GLUE											
07 B	KIA	BEIGE 12"X12" VFT & GLUE	FLR 2 CORR CENTER	062112RG70		NO ASBESTOS DETECTED		2-5% CHRYSOTILE		DETECTED IN BLACK MASTIC	1 - 2
NO ASBESTOS DETECTED IN YELLOW GLUE											

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG B

Work Order: T1206106

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	CHRY	PERCENT ASBESTOS FIBERS				%NON-ASB FIBERS	
						AMOS	CROC	TREM	ANTH		OTHER
07 C	KIA	BEIGE 12"X12" VFT & GLUE	FLR 2 CORR SOUTHWEST	062112RG71		NO ASBESTOS DETECTED					1 - 2
*Comments: NO ASBESTOS DETECTED IN YELLOW GLUE											
07 D	KIA	BEIGE 12"X12" VFT & GLUE	IN ROOM 209	062112RG72		NO ASBESTOS DETECTED					1 - 2
07 E	KIA	BEIGE 12"X12" VFT & GLUE	IN ROOM 210	062112RG73		NO ASBESTOS DETECTED IN YELLOW GLUE					1 - 2
08 A	KIA	BROWN VFT	FLR 2 CORR SOUTHEAST	062112RG69A	2 - 5	NO ASBESTOS DETECTED					1 - 2
08 B	KIA	BROWN VFT	FLR 2 CORR CENTER	062112RG71A		NO ASBESTOS DETECTED					0 - 0
STOP AT FIRST POSITIVE, NOT ANALYZED											
08 C	KIA	BLACK VFT	FLR 2 CORR SOUTHWEST	062112RG70A	2 - 5	NO ASBESTOS DETECTED					1 - 2
09 A	KIA	CREAM 12"X12" VFT & GLUE	ROOM 210	062112RG74		NO ASBESTOS DETECTED					1 - 2
10 A	KIA	GREY VFT & BLACK FELT	ROOM 210	062112RG74A	2 - 5	NO ASBESTOS DETECTED IN BLACK FELT					1 - 2
11 A	KIA	TAN 12"X12" RED STRIPE VFT & GLUE	ROOM 208	062112RG75		NO ASBESTOS DETECTED					1 - 2
NO ASBESTOS DETECTED IN YELLOW GLUE											
11 B	KIA	TAN 12"X12" RED STRIPE VFT & GLUE	ROOM 215	062112RG76		NO ASBESTOS DETECTED					1 - 2
NO ASBESTOS DETECTED IN YELLOW GLUE											

CLIENT: CH2M HILL
PROJECT: GLYNN ARCHER ES: BLDG B
Work Order: T1206106

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM	ANTH		OTHER
11 C	KIA	TAN 12"X12" RED STRIPE VFT & GLUE	ROOM 209B	062112RG77			NO ASBESTOS DETECTED				1 - 2
12 A	KIA	WHITE 12"X12" VFT & GLUE	ROOM 108	062112RG78			NO ASBESTOS DETECTED IN YELLOW GLUE				1 - 2
13 A	KIA	BROWN 9"X9" VFT & BLACK MASTIC	ROOM 107	062112RG79	2 - 5		2-5% CHRYSOTILE DETECTED IN BLACK MASTIC				1 - 2
14 A	KIA	BLACK VFT & BLACK MASTIC	ROOM 107	062112RG79A	2 - 5		2-5% CHRYSOTILE DETECTED IN BLACK MASTIC				1 - 2
15 A	KIA	RED 9"X9" VFT & BLACK MASTIC	ROOM 215	062112RG80	2 - 5		2-5% CHRYSOTILE DETECTED IN BLACK MASTIC				1 - 2
16 A	KIA	BLACK VFT & BLACK MASTIC	ROOM 215	062112RG80A	2 - 5		2-5% CHRYSOTILE DETECTED IN BLACK MASTIC				1 - 2
17 A	KIA	WHITE 9"X9" VFT & BLACK MASTIC	ROOM 206	062112RG81	2 - 5		2-5% CHRYSOTILE DETECTED IN BLACK MASTIC				1 - 2
17 B	KIA	WHITE 9"X9" VFT & BLACK MASTIC	ROOM 215	062112RG82			STOP AT FIRST POSITIVE, NOT ANALYZED				0 - 0
18 A	KIA	GREEN VFT	ROOM 206	062112RG81A	2 - 5						1 - 2

CLIENT: CH2M HILL
PROJECT: GLYNN ARCHER ES: BLDG B
Work Order: T1206106

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM	ANTH		OTHER
18 B	KIA	GREEN VFT	ROOM 215	062112RG82A	-						0 - 0
STOP AT FIRST POSITIVE, NOT ANALYZED											
19 A	KIA	BLACK FELT PAPER	ROOM 206	062112RG81B			NO ASBESTOS DETECTED				10 - 15
20 A	KIA	BLACK VFT & BLACK MASTIC	ROOM 215	062112RG82B	2 - 5						1 - 2
2-5% CHRYSOTILE DETECTED IN BLACK MASTIC											
21 A	KIA	GREEN 9"X9" VFT & BLACK MASTIC	ROOM 108	062112RG83	5 - 10						1 - 2
21 B	KIA	GREEN 9"X9" VFT & BLACK MASTIC	ROOM 206	062112RG84	-						0 - 0
STOP AT FIRST POSITIVE, NOT ANALYZED											
21 C	KIA	GREEN 9"X9" VFT & BLACK MASTIC	ROOM 207	062112RG85	-						0 - 0
STOP AT FIRST POSITIVE, NOT ANALYZED											
22 A	KIA	BLACK FELT PAPER	ROOM 108	062112RG83A			NO ASBESTOS DETECTED				10 - 15
22 B	KIA	BLACK FELT PAPER	ROOM 206	062112RG84A			NO ASBESTOS DETECTED				10 - 15
22 C	KIA	BLACK FELT PAPER	ROOM 207	062112RG85A			NO ASBESTOS DETECTED				10 - 15
23 A	KIA	BLACK/GREY ROOF FELT FIELD MEMBRANE	ROOF NORTH	062112RG86			NO ASBESTOS DETECTED				10 - 20
23 B	KIA	BLACK/GREY ROOF FELT FIELD MEMBRANE	ROOF SOUTH	062112RG87			NO ASBESTOS DETECTED				10 - 20

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG B

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Work Order: T1206106

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM	ANTH		OTHER
23 C	KIA	BLACK/GREY ROOF FELT FIELD MEMBRANE	ROOF CENTER	062112RG88			NO ASBESTOS DETECTED				10 - 20
24 A	KIA	BLACK/GREY CAP SEAL FLASHING	CAP SOUTHEAST	062112RG89			NO ASBESTOS DETECTED				5 - 10
24 B	KIA	BLACK/GREY CAP SEAL FLASHING	CAP NORTHWEST	062112RG90			NO ASBESTOS DETECTED				5 - 10
24 C	KIA	BLACK/GREY CAP SEAL FLASHING	CAP SOUTHWEST	062112RG91			NO ASBESTOS DETECTED				5 - 10
25 A	KIA	BLACK/ VTR FLASHING	VENT CENTER	062112RG92			NO ASBESTOS DETECTED				10 - 20
26 A	KIA	BLACK VFT	FLR 2 CORR SOUTHWEST	062112RG634		2 - 5					1 - 2



Quality Control Officer

Analytical results pertain only to the sample(s) analyzed. All Samples analyzed were acceptable for analysis.

ABBREVIATIONS: ANA = Analyst; ASB = Asbestos; CHRY = Chrysothile; AMOS = Amosite; CROC = Crocidolite; TERM = Term/Act; ANTH = Anthrophyllite; ACT = Actinolite; AL = Aluminum; BLK = Black; BACK = Backing; BL = Blue; BRN = Brown; C = Cellulose; CALC = Calcareous; CPT = Carpet; CTL = Ceiling Tile; CEM = Cement; COV = Cover; DEB = Debris; FG = Fiberglass; FIB = Fibrous; MAS = Mastic; MAT = Material; MIC = Micaceous; MW = Mineral Wool; ORG = Orange; PAI = Paint; PAP = Paper; PL = Plaster; PLAS = Plastic; PWDR = Powder; RCF = Refractory Ceramic Fiber; RUB = Rubber; SIL = Silver; SR = Sheet Rock; S = Synthetic; SUB = Substance; TEXT = Textured; TR = Trace; TRAN = Transite; TERM = Tremolite; VERM = Vermiculite; VYL = Vinyl; W = Wollastonite; WH = White; YEL = Yellow.



CONTINUATION OF BULK TRANSMITTAL FORM CHAIN OF CUSTODY

CLIENT: CH2MHILL

SAMPLE PREFIX 062112R

PROJECT NO./BILL GROUP: 2-2373 IH

SAMPLE NUMBER	COLOR	SAMPLE DESCRIPTION	SAMPLE LOCATION
1. 57	grey	vinyl baseboard glue	Rm 106
2. 58	brown/teal	↓	stairs NE
3. 59	tan	12" speck VFT + bm	Fir 1 corr SE
4. 60	↓	↓	↓ SW
5. 61	↓	↓	Fir 2 SE
6. 62	↓	↓	center
7. 63	↓	↓	↓ SW
8. 64	beige/crm	12" spec kd VFT + glue	Fir 1 corr NE
9. 65	↓	↓	↓ W ↓ NW
10. 66	↓	↓	IN Rm 104
11. 67	↓	↓	↓ 105
12. 68	↓	↓	↓ 106
13. 69	↓	↓	Fir 2 corr SE
14. 70	↓	↓	↓ C
15. 71	↓	↓	↓ SW
16. 72	↓	↓	IN Rm 209
17. 73	↓	↓	IN Rm 210
18. 74	cream/grey	12" VFT (2) + glue	Rm 210
19. 75	tan	12" red stripe VFT + glue	Rm 208
20. 76	↓	↓	↓ 215
21. 77	↓	↓	↓ 109B
22. 78	white	12" blue stripe VFT + glue	Rm 108
23. 79	brown	9x9" VFT + blk mastic	Rm 107
24. 80	red	↓	Rm 215
25. 81	wht/green	↓	Rm 206
26. 82	↓	↓	↓ 215
27. 83	green	↓	↓ 109
28. 84	↓	↓	↓ 206
29. 85	↓	↓	↓ 207
30. 86	blk/grey	roof felt + field memb	roof N
31. 87	↓	↓	↓ S
32. 88	↓	↓	↓ center
33. 89	↓	roof cap seal / flash	cap SE
34. 90	↓	↓	↓ NW
35. 91	↓	↓	↓ SW
92	↓	VTR flash	vent center

CHAIN OF CUSTODY: DATE/TIME 062112 062612

PRINT NAME/SIGNATURE [Signature]

RECEIVED stamp with date JUN 28 2012 and purpose G T A C T A

C= Collection T= Transportation A= Analysis

REPORT

SENT CH2M HILL

TO: 6410 5TH STREET, SUITE 2A
KEY WEST, FL 33040
ANDREW SMYTH

Phone: 305-294-1645 Fax: 305-294-4913
Email: asmyth@ch2m.com

Thank you for your business.

PREPARED AAL

BY: Asbestos Department
5005 WEST LAUREL STREET
SUITE 110
TAMPA, FL 33607
NVLAP Code 101775
(813) 287-1005

Analysis: Polarized Light Microscopy (PLM) with dispersion staining techniques according to the United States (US) Environmental Protection Agency (EPA) "Method for the Determination of Asbestos in Bulk Building Materials", EPA/600/R-93-116, July 1993.

Sample Type: BULK

of Samples: 46

Work Order# T1207001
AAL Project# 2012-2373

Project: GLYNN ARCHER ES: AUDITORIUM BLDG

Date in: Thursday, June 28, 2012

Date out: Tuesday, Jul 3 2012

Transported: FEDEX

Sampled by: R.G.

Received by: KIA



Authorized Analyst
KHANDAKER ANAM



Laboratory Manager
KHANDAKER ANAM

Due to the small size of asbestos fibers associated with vinyl floor tiles, TEM analysis is recommended for all floor tiles containing <1% or no detectable asbestos by visual estimation.

This report may not be reproduced except in full, without the written approval of AAL. AAL will not be held responsible for the use of its reports issued in part to third parties or authorized agents of the client.

This report shall not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All NVLAP reports displaying NVLAP logo must have at least one signature to be valid.

The following analytical results presented in this report pertain only to the samples analyzed. American Asbestos Laboratories assumes no responsibility for whether the samples accurately represent the material in question

LABORATORY BULK SAMPLE ANALYSIS REPORT

CLIENT: CH2M HILL
PROJECT: GLYNN ARCHER ES: AUDITORIUM BLDG
Work Order: T1207001

Samples were analyzed in accordance with the Interim Method as described in 40 CFR, Part 763, Vol. 52, No. 210

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS				%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM		ANTH
01 A	KIA	GREY/WHITE PLASTER SYSTEM	2ND CEILING NW	062212RG01			NO ASBESTOS DETECTED			1 - 2
01 B	KIA	GREY/WHITE PLASTER SYSTEM	2ND CEILING WEST	062212RG02			NO ASBESTOS DETECTED			1 - 2
01 C	KIA	GREY/WHITE PLASTER SYSTEM	2ND CEILING WC	062212RG03			NO ASBESTOS DETECTED			1 - 2
01 D	KIA	GREY/WHITE PLASTER SYSTEM	WALL SW TECH RM	062212RG04			NO ASBESTOS DETECTED			1 - 2
01 E	KIA	GREY/WHITE PLASTER SYSTEM	WALL SE MECH 117	062212RG05			NO ASBESTOS DETECTED			1 - 2
02 A	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	AUD NORTHEAST	062212RG06			NO ASBESTOS DETECTED			60 - 70
02 B	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	AUD SOUTH	062212RG07			NO ASBESTOS DETECTED			60 - 70
02 C	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	AUD EAST	062212RG08			NO ASBESTOS DETECTED			60 - 70
02 D	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	AUD CENTER	062212RG09			NO ASBESTOS DETECTED			60 - 70
02 E	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	AUD NORTHWEST	062212RG10			NO ASBESTOS DETECTED			60 - 70
02 F	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	AUD SOUTHEAST	062212RG11			NO ASBESTOS DETECTED			60 - 70
02 G	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	AUD NORTH	062212RG12			NO ASBESTOS DETECTED			60 - 70

Tuesday, July 03, 2012

Page 2 of 4

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: AUDITORIUM BLDG

Work Order: T1207001

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM	ANTH		OTHER
03 A	KIA	WHITE/TAN 1'X1' DOT CEILING TILE	AUD UPPER NORTH	062212RG13			NO ASBESTOS DETECTED				20 - 25
03 B	KIA	WHITE/TAN 1'X1' DOT CEILING TILE	AUD UPPER WEST	062212RG14			NO ASBESTOS DETECTED				20 - 25
03 C	KIA	WHITE/TAN 1'X1' DOT CEILING TILE	AUD UPPER SOUTH	062212RG15			NO ASBESTOS DETECTED				20 - 25
04 A	KIA	CREAM/GREEN EXT. SUTCCO W/PAINT	SOUTHEAST	062212RG16			NO ASBESTOS DETECTED				1 - 2
04 B	KIA	CREAM/GREEN EXT. SUTCCO W/PAINT	SOUTHWEST @117	062212RG17			NO ASBESTOS DETECTED				1 - 2
04 C	KIA	CREAM/GREEN EXT. SUTCCO W/PAINT	NE WINDOW 117	062212RG18			NO ASBESTOS DETECTED				1 - 2
04 D	KIA	CREAM/GREEN EXT. SUTCCO W/PAINT	NORTHWEST ENTRY	062212RG19			NO ASBESTOS DETECTED				1 - 2
04 E	KIA	CREAM/GREEN EXT. SUTCCO W/PAINT	BACK SOUTH WALL	062212RG20			NO ASBESTOS DETECTED				1 - 2
05 A	KIA	GREY WINDOW GLAZING	MECH RM 117 WINDOW	062212RG21			NO ASBESTOS DETECTED				1 - 2
05 B	KIA	GREY WINDOW GLAZING	MECH RM 117 WINDOW	062212RG22			NO ASBESTOS DETECTED				1 - 2
06 A	KIA	GREY CEILING PLASTER SYSTEM	AUD UPPER NORTH	062212RG23			NO ASBESTOS DETECTED				1 - 2
06 B	KIA	GREY CEILING PLASTER SYSTEM	AUD UPPER SOUTH	062212RG24			NO ASBESTOS DETECTED				1 - 2
07 A	KIA	TAN PEBBLE LINOLEUM	AUD NORTH	062212RG25						20 - 25	1 - 2
07 B	KIA	TAN PEBBLE LINOLEUM	AUD CENTER	062212RG26						20 - 25	1 - 2

Report Continued on Next Page

Tuesday, July 03, 2012

Page 3 of 4

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: AUDITORIUM BLDG

Work Order: T1207001

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	CHRY	PERCENT ASBESTOS FIBERS				%NON-ASB FIBERS
						AMOS	CROC	TREM	ANTH OTHER	
07 C	KIA	TAN PEBBLE LINOLEUM	AUD SOUTH STAGE	062212RG27	20 - 25					1 - 2
08 A	KIA	MARRON VFT	AUD NORTH	062212RG25A	2 - 5	NO ASBESTOS DETECTED IN BLACK FELT/MASTIC				1 - 2
08 B	KIA	MARRON VFT	AUD CENTER	062212RG26A	-	STOP AT FIRST POSITIVE, NOT ANALYZED				0 - 0
08 C	KIA	MARRON VFT	AUD SOUTH STAGE	062212RG27A	-	STOP AT FIRST POSITIVE, NOT ANALYZED				0 - 0
09 A	KIA	BLACK FELT PAPER	AUD NORTH	062212RG25B		NO ASBESTOS DETECTED				10 - 15
09 B	KIA	BLACK FELT PAPER	AUD CENTER	062212RG26B		NO ASBESTOS DETECTED				10 - 15
09 C	KIA	BLACK FELT PAPER	AUD SOUTH STAGE	062212RG27B		NO ASBESTOS DETECTED				10 - 15
10 A	KIA	BLACK/GREY ROOF FIELD MEMBRANE	AUD MAIN CENTER	062212RG28		NO ASBESTOS DETECTED				5 - 10
10 B	KIA	BLACK/GREY ROOF FIELD MEMBRANE	AUD MAIN S. CENTER	062212RG29		NO ASBESTOS DETECTED				5 - 10
10 C	KIA	BLACK/GREY ROOF FIELD MEMBRANE	AUD MAIN NORTHWEST	062212RG30		NO ASBESTOS DETECTED				5 - 10
11 A	KIA	BLACK/GREY ROOF FIELD MEMBRANE	WEST WALKWAY	062212RG31		NO ASBESTOS DETECTED				5 - 10
11 B	KIA	BLACK/GREY ROOF FIELD MEMBRANE	EAST WALKWAY	062212RG32		NO ASBESTOS DETECTED				5 - 10

Report Continued on Next Page

Tuesday, July 03, 2012

Page 4 of 4

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: AUDITORIUM BLDG

Work Order: T1207001

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM	ANTH		OTHER
11 A	KIA	BLACK EDGE FLASHING	AUD MAIN SOUTH	062212RG33			NO ASBESTOS DETECTED				5 - 10
12 B	KIA	BLACK EDGE FLASHING	AUD MAIN SE	062212RG34			NO ASBESTOS DETECTED				5 - 10
12 C	KIA	BLACK EDGE FLASHING	AUD MAIN NW	062212RG35			NO ASBESTOS DETECTED				5 - 10
12 D	KIA	BLACK EDGE FLASHING	EAST WALKWAY NE	062212RG36			NO ASBESTOS DETECTED				5 - 10
12 A	KIA	BLACK WALL CURB FLASHING	AUD MAIN NORTHEAST	062212RG37			NO ASBESTOS DETECTED				10 - 20
12 B	KIA	BLACK WALL CURB FLASHING	AUD MAIN AC UNIT	062212RG38			NO ASBESTOS DETECTED				5 - 10
12 C	KIA	BLACK WALL CURB FLASHING	EAST WALKWAY N.	062212RG39			NO ASBESTOS DETECTED				5 - 10
12 D	KIA	BLACK WALL CURB FLASHING	WEST WALKWAY S.	062212RG40			NO ASBESTOS DETECTED				5 - 10

Quality Control Officer

Analytical results pertain only to the sample(s) analyzed. All Samples analyzed were acceptable for analysis.

ABBREVIATIONS:

- ANA = Analyst; ASB = Asbestos; CHRY = Chrysofile; AMOS = Amosite; CROC = Crocidolite; TERM = Term/Act; ANTH = Anthophyllite;
- ACT = Actinolite; AL = Aluminum; BLK = Black; BACK = Backing; BL = Blue; BRN = Brown; C = Cellulose; CALC = Calcareous; CPT = Carpet; CTL = Ceiling Tile;
- CEM = Cement; COV = Cover; DEB = Debris; FG = Fiberglass; FIB = Fibrous; MAS = Mastic; MAT = Material; MIC = Micaeous; MW = Mineral Wool; ORG = Orange;
- PAI = Paint; PAP = Paper; PL = Plaster; PLAS = Plastic; PWDR = Powder; RCF = Refractory Ceramic Fiber; RUB = Rubber; SIL = Silver; SR = Sheet Rock; S = Synthetic;
- SUB = Substance; TEXT = Textured; TR = Trace; TRAN = Transite; TERM = Tremolite; VYL = Vermiculite; VEM = Vermiculite; WH = Wollastonite; YEL = Yellow.



EE&G Environmental Services, LLC
5751 Miami Lakes Drive East
Miami Lakes, Florida 33014

T100700

BULK TRANSMITTAL FORM CHAIN OF CUSTODY

CLIENT: CH2M HILL
 CLIENT CONTACT: ANDREW SMYTH
 DATE COLLECTED: 062212
 DATE SENT: 062112
 STOP AT FIRST POSITIVE: Y (circle one)

PROJECT: GLYNN ARCHER ES: BLDG
 PROJECT NO./BILL GROUP: 2012-2373
 PROJECT PHASE: ACM SURV
 DATE VERBAL NEEDED: _____
 DATE WRITTEN NEEDED: 07/01

SAMPLE PREFIX 062212-PG

SAMPLE NUMBER	COLOR	SAMPLE DESCRIPTION	SAMPLE LOC.
1. <u>1</u>	<u>grey/whit</u>	<u>plaster system</u>	<u>2nd ceiling</u>
2. <u>2</u>	↓	↓	↓
3. <u>3</u>	↓	↓	↓
4. <u>4</u>	↓	↓	↓
5. <u>5</u>	↓	↓	↓
6. <u>6</u>	<u>white</u>	<u>2x4 dot framework</u>	<u>wall swite</u>
7. <u>7</u>	↓	↓	↓
8. <u>8</u>	↓	↓	↓
9. <u>9</u>	↓	↓	↓
10. <u>10</u>	↓	↓	↓
11. <u>11</u>	↓	↓	↓
12. <u>12</u>	↓	↓	↓
13. <u>13</u>	<u>white/tan</u>	<u>1x1" dot CT</u>	↓
14. <u>14</u>	↓	↓	↓
15. <u>15</u>	↓	↓	↓
16. <u>16</u>	<u>cream/green</u>	<u>ext. stucco w/paint</u>	↓
17. <u>17</u>	↓	↓	↓
18. <u>18</u>	↓	↓	↓
19. <u>19</u>	↓	↓	↓
20. <u>20</u>	↓	↓	↓

CHAIN OF CUSTODY:
 DATE/TIME
062212
062012

PRINT NAME/SIGNATURE

RECEIVED
 JUN 28 2012

C= Collection T= Transportation A= Analysis

PURPOSE
 C T A
 C T A
 C T A



CONTINUATION OF
BULK TRANSMITTAL FORM
CHAIN OF CUSTODY

CLIENT: CH2M Hill

PROJECT NO./BILL GROUP: 2-2373 114

SAMPLE PREFIX 062212R6


SAMPLE NUMBER	COLOR	SAMPLE DESCRIPTION	SAMPLE LOCATION
1. <u>21</u>	<u>grey</u>	<u>window glazing</u>	<u>mech rm 117 window</u>
2. <u>22</u>	↓	↓	↓ ↓ ↓
3. <u>23</u>	<u>grey</u>	<u>ceiling plaster system</u>	<u>AUD upper N</u>
4. <u>24</u>	↓	↓	↓ ↓ ↓ S
5. <u>25</u>	<u>tan/maroon</u>	<u>pebble / no / VFT / mastic</u>	<u>AUD N</u>
6. <u>26</u>	↓	↓	↓ center
7. <u>27</u>	↓	↓	↓ S stage
8. <u>28</u>	<u>blk/grey</u>	<u>roof field membrane</u>	<u>AUD MAIN center</u>
9. <u>29</u>	↓	↓	↓ S center
10. <u>30</u>	↓	↓	↓ NW
11. <u>31</u>	↓	↓	<u>west walkway</u>
12. <u>32</u>	↓	↓	<u>east walkway</u>
13. <u>33</u>	↓	<u>edge flashing</u>	<u>AUD MAIN S</u>
14. <u>34</u>	↓	↓	↓ ↓ SE
15. <u>35</u>	↓	↓	↓ ↓ NW
16. <u>36</u>	↓	↓	<u>east walkway NE</u>
17. <u>37</u>	↓	<u>wall curb flashing</u>	<u>AUD MAIN NW</u>
18. <u>38</u>	↓	↓	↓ ↓ AC unit
19. <u>39</u>	↓	↓	<u>east walkway N</u>
20. <u>40</u>	↓	↓	<u>west walkway S</u>
21.			
22.			
23.			
24.			
25.			
26.			
27.			
28.			
29.			
30.			
31.			
32.			
33.			
34.			
35.			

CHAIN OF CUSTODY:
DATE/TIME

062242
062612

PRINT NAME/SIGNATURE

[Handwritten Signature]



AAL

American Asbestos Laboratories

Wednesday, Aug 1 2012, 4:37 PM

REPORT

SENT CH2M HILL

TO: 6410 5TH STREET, SUITE 2A
KEY WEST, FL 33040
ANDREW SMYTH

Phone: 305-294-1645 **Fax:** 305-294-4913

Email: asmyth@ch2m.com

Thank you for your business.

PREPARED AAL

BY: Asbestos Department
5005 WEST LAUREL STREET
SUITE 110
TAMPA, FL 33607
NVLAP Code 101775
(813) 287-1005

Analysis: Polarized Light Microscopy (PLM) with dispersion staining techniques according to the United States (US) Environmental Protection Agency (EPA) "Method for the Determination of Asbestos in Bulk Building Materials", EPA/600/R-93-116, July 1993.

Sample Type: BULK

of Samples: 3

Work Order# T1208005

AAL Project# 2012-2373

Project: GLYNN ARCHER ES: BLDG AUDITORIUM

Date in: Monday, July 23, 2012

Date out: Wednesday, Aug 1 2012

Transported: FEDEX

Sampled by: R.G.

Received by: KIA



Authorized Analyst
KHANDAKER ANAM



Laboratory Manager
KHANDAKER ANAM

Due to the small size of asbestos fibers associated with vinyl floor tiles, TEM analysis is recommended for all floor tiles containing <1% or no detectable asbestos by visual estimation.

This report may not be reproduced except in full, without the written approval of AAL. AAL will not be held responsible for the use of its reports issued in part to third parties or authorized agents of the client.

This report shall not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All NVLAP reports displaying NVLAP logo must have at least one signature to be valid.

The following analytical results presented in this report pertain only to the samples analyzed. American Asbestos Laboratories assumes no responsibility for whether the samples accurately represent the material in question

LABORATORY BULK SAMPLE ANALYSIS REPORT

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG AUDITORIUM

Work Order: T1208005

Samples were analyzed in accordance with the Interim Method as described in 40 CFR, Part 763, Vol. 52, No. 210

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM	ANTH		OTHER
01 A	KIA	GREY CEILING INSULATION	AUD UPPER 212	071812NS01				NO ASBESTOS DETECTED			85 - 90
01 B	KIA	GREY CEILING INSULATION	AUD UPPER 212	071812NS02				NO ASBESTOS DETECTED			85 - 90
01 C	KIA	GREY CEILING INSULATION	AUD UPPER 212	071812NS03				NO ASBESTOS DETECTED			85 - 90

Quality Control Officer

Analytical results pertain only to the sample(s) analyzed. All Samples analyzed were acceptable for analysis.

ABBREVIATIONS:

- ANA = Analyst; ASB = Asbestos; CHRY = Chrysotile; AMOS = Amosite; CROC = Crocidolite; TERM = Term/Act; ANTH = Anthophyllite;
- ACT = Actinolite; AL = Aluminum; BLK = Black; BACK = Backing; BL = Blue; BRN = Brown; C = Cellulose; CALC = Calcareous; CPT = Carpet; CTL = Ceiling Tile;
- CEM = Cement; COV = Cover; DEB = Debris; FG = Fiberglass; FIB = Fibrous; MAS = Mastic; MAT = Material; MIC = Micaceous; MW = Mineral Wool; ORG = Orange;
- PAI = Paint; PAP = Paper; PL = Plaster; PLAS = Plastic; PWDR = Powder; RCF = Refractory Ceramic Fiber; RUB = Rubber; SIL = Silver; SR = Sheet Rock; S = Synthetic;
- SUB = Substance; TEXT = Textured; TR = Trace; TRAN = Transite; TERM = Tremolite; VERM = Vermiculite; VYL = Viny; W = Wollastonite; WH = White; YEL = Yellow.

71208005



EE&G Environmental Services, LLC
5751 Miami Lakes Drive East
Miami Lakes, Florida 33014

BULK TRANSMITTAL FORM CHAIN OF CUSTODY

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG AUD

CLIENT CONTACT: ANDREW SMYTH

PROJECT NO./BILL GROUP: 2012-2373/IH

DATE COLLECTED: 07/19/12

PROJECT PHASE: ACM SURV

DATE SENT: 07/20/12

DATE VERBAL NEEDED: 07/31/12

STOP AT FIRST POSITIVE: Y (circle one)

DATE WRITTEN NEEDED: _____

SAMPLE PREFIX 07/19/12MS

SAMPLE NUMBER	COLOR	SAMPLE DESCRIPTION	SAMPLE LOCATION
1. <u>01</u>	<u>grey</u>	<u>ceiling insulation</u>	<u>AUD upper on 212</u>
2. <u>2</u>	↓	↓	↓ ↓ ↓
3. <u>3</u>	↓	↓	↓ ↓ ↓
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____
11. _____	_____	_____	_____
12. _____	_____	_____	_____
13. _____	_____	_____	_____
14. _____	_____	_____	_____
15. _____	_____	_____	_____
16. _____	_____	_____	_____
17. _____	_____	_____	_____
18. _____	_____	_____	_____
19. _____	_____	_____	_____
20. _____	_____	_____	_____


CHAIN OF CUSTODY:
DATE/TIME

PRINT NAME/SIGNATURE

PURPOSE

07/19/12
07/20/12

[Signature]
[Signature]



C T A
 C T A
 C T A

C= Collection T= Transportation A= Analysis

REPORT

SENT CH2M HILL

TO: 6410 5TH STREET, SUITE 2A
KEY WEST, FL 33040
ANDREW SMYTH

Phone: 305-294-1645 **Fax:** 305-294-4913
Email: asmyth@ch2m.com

Thank you for your business.

PREPARED AAL

BY: Asbestos Department
5005 WEST LAUREL STREET
SUITE 110
TAMPA, FL 33607
NVLAP Code 101775
(813) 287-1005

Analysis: Polarized Light Microscopy (PLM) with dispersion staining techniques according to the United States (US) Environmental Protection Agency (EPA) "Method for the Determination of Asbestos in Bulk Building Materials", EPA/600/R-93-116, July 1993.

Sample Type: BULK

of Samples: 77

Work Order# T1207065

AAL Project# 2012-2373

Project: GLYNN ARCHER ES; BLDG C

Date in: Monday, July 16, 2012

Date out: Wednesday, Aug 1 2012

Transported: FEDEX

Sampled by: R.G.

Received by: KIA



Authorized Analyst
KHANDAKER ANAM



Laboratory Manager
KHANDAKER ANAM

Due to the small size of asbestos fibers associated with vinyl floor tiles, TEM analysis is recommended for all floor tiles containing <1% or no detectable asbestos by visual estimation.

This report may not be reproduced except in full, without the written approval of AAL. AAL will not be held responsible for the use of its reports issued in part to third parties or authorized agents of the client.

This report shall not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All NVLAP reports displaying NVLAP logo must have at least one signature to be valid.

The following analytical results presented in this report pertain only to the samples analyzed. American Asbestos Laboratories assumes no responsibility for whether the samples accurately represent the material in question

AAL LABORATORY BULK SAMPLE ANALYSIS REPORT

CLIENT: CH2M HILL
PROJECT: GLYNN ARCHER ES: BLDG C
Work Order: T1207065

Samples were analyzed in accordance with the Interim Method as described in 40 CFR, Part 763, Vol. 52, No. 210

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS				%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM		ANTH
01 A	KIA	GREY PLASTER SYSTEM	114A	062112RG-01			NO ASBESTOS DETECTED			1 - 2
01 B	KIA	GREY PLASTER SYSTEM	136	062112RG-02			NO ASBESTOS DETECTED			1 - 2
01 C	KIA	GREY PLASTER SYSTEM	CORR @136	062112RG-03			NO ASBESTOS DETECTED			1 - 2
01 D	KIA	GREY PLASTER SYSTEM	115A	062112RG-04			NO ASBESTOS DETECTED			1 - 2
01 E	KIA	GREY PLASTER SYSTEM	CAFÉ STORES	062112RG-05			NO ASBESTOS DETECTED			1 - 2
01 F	KIA	GREY PLASTER SYSTEM	CAFÉ STORES CEILING	062112RG-06			NO ASBESTOS DETECTED			1 - 2
01 G	KIA	GREY PLASTER SYSTEM	111	062112RG-07			NO ASBESTOS DETECTED			1 - 2
02 A	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	115C SOUTH	062112RG-08			NO ASBESTOS DETECTED			60 - 70
02 B	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	115C NORTH	062112RG-09			NO ASBESTOS DETECTED			60 - 70
02 C	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	112	062112RG-10			NO ASBESTOS DETECTED			60 - 70
02 D	KIA	WHITE 2'X4' DOT FURROW CEILING TILE	114	062112RG-11			NO ASBESTOS DETECTED			60 - 70
03 A	KIA	WHITERED 1'X1' DOT CEILING TILE	HALL @136 CAFÉ	062112RG-12			NO ASBESTOS DETECTED			60 - 70

Wednesday, August 01, 2012

Page 2 of 8

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG C

Work Order: T1207065

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS				%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM		ANTH
03 B	KIA	WHITE/RED 1'X1' DOT CEILING TILE	HALL @CAFÉ	062112RG-13			NO ASBESTOS DETECTED			20 - 25
03 C	KIA	WHIT/RED 1'X1' DOT CEILING TILE	HALL @112	062112RG-14			NO ASBESTOS DETECTED			20 - 25
03 D	KIA	WHITE/RED 1'X1' DOT CEILING TILE	HALL @114	062112RG-15			NO ASBESTOS DETECTED			20 - 25
03 E	KIA	WHIT/RED 1'X1' DOT CEILING TILE	HALL @113C	062112RG-16			NO ASBESTOS DETECTED			20 - 25
04 A	KIA	GREY/PINK EXT. STUCCO W/PAINT	LIBRARY ROOF NORTH	062112RG-17			NO ASBESTOS DETECTED			1 - 2
04 B	KIA	GREY/PINK EXT. STUCCO W/PAINT	LIBRARY ROOF SOUTH	062112RG-18			NO ASBESTOS DETECTED			1 - 2
04 C	KIA	GREY/PINK EXT. STUCCO W/PAINT	LIBRARY ROOF NW	062112RG-19			NO ASBESTOS DETECTED			1 - 2
04 D	KIA	GREY/PINK EXT. STUCCO W/PAINT	BACK @136D	062112RG-20			NO ASBESTOS DETECTED			1 - 2
05 A	KIA	GREY/GREEN EXT. STUCCO W/PAINT	@MENS ROOM	062112RG-21			NO ASBESTOS DETECTED			1 - 2
05 B	KIA	GREY/GREEN EXT. STUCCO W/PAINT	SOUTHEAST CORNER	062112RG-22			NO ASBESTOS DETECTED			1 - 2
05 C	KIA	GREY/GREEN EXT. STUCCO W/PAINT	SOUTHWEST WINDOW	062112RG-23			NO ASBESTOS DETECTED			1 - 2
05 D	KIA	GREY/GREEN EXT. STUCCO W/PAINT	BACK DOOR	062112RG-24			NO ASBESTOS DETECTED			1 - 2
05 E	KIA	GREY/GREEN EXT. STUCCO W/PAINT	SOUTHEAST CAFÉ	062112RG-25			NO ASBESTOS DETECTED			1 - 2
06 A	KIA	GREY WINDOW GLAZING	SE CAFÉ WINDOW	062112RG-26			NO ASBESTOS DETECTED			1 - 2

Report Continued on Next Page

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG C

Work Order: T1207065

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM	ANTH		OTHER
06 B	KIA	GREY WINDOW GLAZING	SC WINDOW	062112RG-27			NO ASBESTOS DETECTED				1 - 2
06 C	KIA	GREY WINDOW GLAZING	BACK @136D	062112RG-28			NO ASBESTOS DETECTED				1 - 2
06 D	KIA	GREY WINDOW GLAZING	EAST CAFÉ	062112RG-29			NO ASBESTOS DETECTED				1 - 2
06 E	KIA	GREY WINDOW GLAZING	NORTHWEST	062112RG-30			NO ASBESTOS DETECTED				1 - 2
06 F	KIA	GREY WINDOW GLAZING	SOUTHEAST SIDE	062112RG-31			NO ASBESTOS DETECTED				1 - 2
07 A	KIA	BLACK/WHITE CHW TSI Layer1: NO ASBESTOS DETECTED IN BLACK FOAMGLASS Layer2: NO ASBESTOS DETECTED IN WHITE WRAP/MASTIC	NW STRAIGHT EXT.	062112RG-32			NO ASBESTOS DETECTED				10 - 20
07 B	KIA	BLACK/WHITE CHW TSI Layer1: NO ASBESTOS DETECTED IN BLACK FOAMGLASS Layer2: NO ASBESTOS DETECTED IN WHITE WRAP/MASTIC	NW ELBOW EXT.	062112RG-33			NO ASBESTOS DETECTED				5 - 10
08 A	KIA	BLACK/YELLOW CHW TSI Layer1: NO ASBESTOS DETECTED IN BLACK FOAMGLASS Layer2: NO ASBESTOS DETECTED IN WHITE/YELLOW WRAP/MASTIC	NW ELBOW EXT.	062112RG-34			NO ASBESTOS DETECTED				1 - 2
08 B	KIA	BLACK/YELLOW CHW TSI Layer1: NO ASBESTOS DETECTED IN BLACK FOAMGLASS Layer2: NO ASBESTOS DETECTED IN WHITE/YELLOW WRAP/MASTIC	NW ELBOW EXT.	062112RG-35			NO ASBESTOS DETECTED				1 - 2

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG C

Work Order: T1207065

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM	ANTH		OTHER
09 A	KIA	GREY 9"X9" VFT & BLACK MASTIC	ROOM 114B	062112RG-36	2 - 5						1 - 2
5-10% CHRYSOTILE DETECTED IN BLACK MASTIC											
09 B	KIA	GREY 9"X9" VFT & BLACK MASTIC	ROOM 133	062112RG-37	2 - 5						1 - 2
5-10% CHRYSOTILE DETECTED IN BLACK MASTIC											
10 A	KIA	GREEN 9"X9" VFT & BLACK MASTIC	ROOM 113C	062112RG-38	2 - 5						1 - 2
5-10% CHRYSOTILE DETECTED IN BLACK MASTIC											
11 A	KIA	PINK 12"X12" VFT & GLUE	ROOM 111	062112RG-39							1 - 2
NO ASBESTOS DETECTED IN YELLOW GLUE											
12 A	KIA	BLUE 12"X12" VFT & GLUE	ROOM 113A	062112RG-40							1 - 2
NO ASBESTOS DETECTED											
13 A	KIA	LT BLUE 12"X12" VFT & GLUE	ROOM 113A	062112RG-40A							1 - 2
NO ASBESTOS DETECTED											
14 A	KIA	BEIGE 12"X12" VFT & GLUE	CORR @113A	062112RG-41							1 - 2
NO ASBESTOS DETECTED IN YELLOW GLUE											
14 B	KIA	BEIGE 12"X12" VFT & GLUE	CORR @112	062112RG-42							1 - 2
NO ASBESTOS DETECTED											
14 C	KIA	BEIGE 12"X12" VFT & GLUE	CORR @114	062112RG-43							1 - 2
NO ASBESTOS DETECTED											
NO ASBESTOS DETECTED IN YELLOW GLUE											

Wednesday, August 01, 2012

Page 5 of 8

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG C

Work Order: T1207065

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	CHRY	PERCENT ASBESTOS FIBERS				%NON-ASB FIBERS
						AMOS	CROC	TREM	ANTH	
15 A	KIA	GREEN VFT & BLACK MASTIC	CORR @113A	062112RG-41A	2 - 5	5-10% CHRYSOTILE DETECTED IN BLACK MASTIC				1 - 2
16 A	KIA	GREY VFT & BLACK MASTIC	CORR @112	062112RG-42A	2 - 5	5-10% CHRYSOTILE DETECTED IN BLACK MASTIC				1 - 2
17 A	KIA	TAN SPECK 12"X12" VFT & GLUE	CORR @113A	062112RG-44		NO ASBESTOS DETECTED				1 - 2
17 B	KIA	TAN SPECK 12"X12" VFT & GLUE	CORR @112	062112RG-45		NO ASBESTOS DETECTED				1 - 2
17 C	KIA	TAN SPECK 12"X12" VFT & GLUE	CORRIDOR	062112RG-46		NO ASBESTOS DETECTED				1 - 2
18 A	KIA	GREEN VFT & BLACK MASTIC	CORR @113A	062112RG-44A	2 - 5	5-10% CHRYSOTILE DETECTED IN BLACK MASTIC				1 - 2
19 A	KIA	GREY VFT & BLACK MASTIC	CORR @112	062112RG-45A	2 - 5	5-10% CHRYSOTILE DETECTED IN BLACK MASTIC				1 - 2
20 A	KIA	BROWN STRIPED 12"X12" VFT & GLUE	114A	062112RG-47		NO ASBESTOS DETECTED				1 - 2
						NO ASBESTOS DETECTED IN YELLOW GLUE				

Report Continued on Next Page

Wednesday, August 01, 2012

Page 6 of 8

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG C

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Work Order: T1207065

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM	ANTH		OTHER
20 B	KIA	BROWN STRIPED 12"X12" VFT & GLUE	126	062112RG-48		NO ASBESTOS DETECTED					1 - 2
20 C	KIA	BROWN STRIPED 12"X12" VFT & GLUE	CAFETERIA	062112RG-49		NO ASBESTOS DETECTED					1 - 2
21 A	KIA	BROWN VINYL BASEBOARD & GLUE	CORR @113	062112RG-50		NO ASBESTOS DETECTED					1 - 2
21 B	KIA	BROWN VINYL BASEBOARD & GLUE	CORR @115	062112RG-51		NO ASBESTOS DETECTED					1 - 2
21 C	KIA	BROWN VINYL BASEBOARD & GLUE	CORR @112	062112RG-52		NO ASBESTOS DETECTED					1 - 2
22 A	KIA	BLACK ROOF FIELD MEMBRANE	UPPER NORTH	062112RG-53		NO ASBESTOS DETECTED					5 - 10
22 B	KIA	BLACK ROOF FIELD MEMBRANE	UPPER SOUTHWEST	062112RG-54		NO ASBESTOS DETECTED					5 - 10
22 C	KIA	BLACK ROOF FIELD MEMBRANE	UPPER CENTER	062112RG-55		NO ASBESTOS DETECTED					5 - 10
23 A	KIA	BLACK FILED MEMBRANE	LOWER ESE	062112RG-56		NO ASBESTOS DETECTED					5 - 10
23 B	KIA	BLACK FILED MEMBRANE	LOWER WEST	062112RG-57		NO ASBESTOS DETECTED					5 - 10
23 C	KIA	BLACK FILED MEMBRANE	LOWER SOUTH	062112RG-58		NO ASBESTOS DETECTED					5 - 10

Report Continued on Next Page

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG C

Work Order: T1207065

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	PERCENT ASBESTOS FIBERS					%NON-ASB FIBERS	
					CHRY	AMOS	CROC	TREM	ANTH		OTHER
23 D	KIA	BLACK FILED MEMBRANE	LOWER NORTHWEST	062112RG-59			NO ASBESTOS DETECTED				10 - 20
23 E	KIA	BLACK FILED MEMBRANE	LOWER ENE	062112RG-60			NO ASBESTOS DETECTED				10 - 20
23 F	KIA	BLACK FILED MEMBRANE	LOWER SSE	062112RG-61			NO ASBESTOS DETECTED				5 - 10
24 A	KIA	BLACK EDGE FLASHING (ROOF)	UPPER NORTHEAST	062112RG-62			NO ASBESTOS DETECTED				5 - 10
24 B	KIA	BLACK EDGE FLASHING (ROOF)	UPPER SOUTHWEST	062112RG-63			NO ASBESTOS DETECTED				5 - 10
24 C	KIA	BLACK EDGE FLASHING (ROOF)	UPPER SOUTHCENTER	062112RG-64			NO ASBESTOS DETECTED				5 - 10
25 A	KIA	BLACK EDGE FLASHING (ROOF)	LOWER SOUTH	062112RG-65			NO ASBESTOS DETECTED				5 - 10
25 B	KIA	BLACK EDGE FLASHING (ROOF)	LOWER NORTH	062112RG-66			NO ASBESTOS DETECTED				5 - 10
25 C	KIA	BLACK EDGE FLASHING (ROOF)	LOWER SOUTHWEST	062112RG-67			NO ASBESTOS DETECTED				5 - 10
26 A	KIA	BLACK WALL CURB FLASHING	SOUTH	062112RG-68			NO ASBESTOS DETECTED				10 - 20
26 B	KIA	BLACK WALL CURB FLASHING	NORTH	062112RG-69			NO ASBESTOS DETECTED				10 - 20
27 A	KIA	BLACK VTR FLASHING	SSW	062112RG-70			NO ASBESTOS DETECTED				10 - 20
28 A	KIA	BLACK EXHAUST FLASHING	SOUTH	062112RG-71			NO ASBESTOS DETECTED				10 - 20
29 A	KIA	BLACK WALL COUNTER FLASHING	NORTHWEST WALL	062112RG-72		5 - 10					5 - 10

Wednesday, August 01, 2012

Page 8 of 8

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG C

Work Order: T1207065

LABORATORY BULK SAMPLE ANALYSIS REPORT CONTINUED

Dash No.	ANA	DESCRIPTION	LOCATION	Sample No.	CHRY	PERCENT ASBESTOS FIBERS				%NON-ASB FIBERS
						AMOS	CROC	TREM	ANTH	

Quality Control Officer

Analytical results pertain only to the sample(s) analyzed. All samples analyzed were acceptable for analysis.

ABBREVIATIONS:

ANA = Analyst; ASB = Asbestos; CHRY = Chrysotile; AMOS = Amosite; CROC = Crocidolite; TERM = Term/Act; ANTH = Anthrophyllite;

ACT = Actinolite; AL = Aluminum; BLK = Black; BACK = Backing; BL = Blue; BRN = Brown; C = Cellulose; CALC = Calcareous; CPT = Carpet; CTL = Ceiling Tile;

CEM = Cement; COV = Cover; DEB = Debris; FG = Fiberglass; FIB = Fibrous; MAS = Mastic; MAT = Material; MIC = Micaceous; MW = Mineral Wool; ORG = Orange;

PAI = Paint; PAP = Paper; PL = Plaster; PLAS = Plastic; PWDR = Powder; RCF = Refractory Ceramic Fiber; RUB = Rubber; SIL = Silver; SR = Sheet Rock; S = Synthetic;

SUB = Substance; TEXT = Textured; TR = Trace; TRAN = Transite; TERM = Tremolite; VYL = Vermiculite; VYM = Wollastonite; WH = White; YEL = Yellow.



EE&G Environmental Services, LLC
 5751 Miami Lakes Drive East
 Miami Lakes, Florida 33014

7/20/07

BULK TRANSMITTAL FORM CHAIN OF CUSTODY

CLIENT: CH2M HILL

PROJECT: GLYNN ARCHER ES: BLDG C

CLIENT CONTACT: ANDREW SMYTH

PROJECT NO./BILL GROUP: 2012-2373/IH

DATE COLLECTED: 06/21/12

PROJECT PHASE: ACM SURV

DATE SENT: 06/21/12

DATE VERBAL NEEDED: 07/31/12

STOP AT FIRST POSITIVE: Y (circle one)

DATE WRITTEN NEEDED: 07/31/12

SAMPLE PREFIX 062112 M

SAMPLE NUMBER	COLOR	SAMPLE DESCRIPTION	SAMPLE LOCATION
1. <u>01</u>	<u>gray</u>	<u>plaster system</u>	<u>114A</u>
2. <u>2</u>			<u>136</u>
3. <u>3</u>			<u>corr @ 136</u>
4. <u>4</u>			<u>115A</u>
5. <u>5</u>			<u>cafe stores</u>
6. <u>6</u>			<u>cafe stores ceiling</u>
7. <u>7</u>			<u>111</u>
8. <u>8</u>	<u>white</u>	<u>2x4' dot furrow CT</u>	<u>115C S</u>
9. <u>9</u>			<u>115C N</u>
10. <u>10</u>			<u>112</u>
11. <u>11</u>			<u>114</u>
12. <u>12</u>	<u>white/red</u>	<u>1x1' dot CT</u>	<u>hall @ 136 cafe</u>
13. <u>13</u>			<u>@ cafe</u>
14. <u>14</u>			<u>@ 112</u>
15. <u>15</u>			<u>@ 114</u>
16. <u>16</u>			<u>@ 113C</u>
17. <u>17</u>	<u>grey/pink</u>	<u>exter. stucco w/paint</u>	<u>library roof N</u>
18. <u>18</u>			<u>S</u>
19. <u>19</u>			<u>MW</u>
20. <u>20</u>			<u>back @ 136D</u>

CHAIN OF CUSTODY:
DATE/TIME

PRINT NAME/SIGNATURE


PURPOSE

0621
0707

[Signature]

C T A
 C T A
 C T A

C = Collection T = Transportation A = Analysis



T 120 7065



CONTINUATION OF BULK TRANSMITTAL FORM CHAIN OF CUSTODY

CLIENT: CH2M HILL

SAMPLE PREFIX 06212R PROJECT NO./BILL GROUP: 2-2373 / # SUB

SAMPLE NUMBER	COLOR	SAMPLE DESCRIPTION	SAMPLE LOCATION
1. 21	gray/green	ext. stucco w/put	@ mens room
2. 22			SE corner
3. 23			SW window
4. 24			back door
5. 25			NE cafe
6. 26	grey	window glazing	SE cafe window
7. 27			SC window
8. 28			back @ 136D
9. 29			East cafe
10. 30			NW
11. 31			SE side
12. 32	black/white	CHW TSI	NW straight ext
13. 33			NW elbow
14. 34	black/yellow		NW elbow
15. 35			
16. 36	grey	9x9" VFT + blk nst	Rm 114B
17. 37			↓ 133
18. 38	green		Rm 113C
19. 39	pink	12" VFT + glue	Rm 111
20. 40	blue	2x12" VFT + glue	113A
21. 41	beige	12" VFT + glue	corr @ 113A
22. 42			↓ @ 112A
23. 43			↓ @ 114
24. 44	tan	speck 12" VFT + glue	corr @ 113A
25. 45			↓ @ 112
26. 46			↓ corridor
27. 47	brown	12" striped VFT + glue	114A
28. 48			126
29. 49			cafeteria
30. 50	brown	vinyl baseboard + glue	corr @ 113
31. 51			↓ @ 115
32. 52			↓ @ 112
33. 53	black	roof field membrane	upper N
34. 54			↓ SW
35. 55			↓ C

CHAIN OF CUSTODY DATE/TIME

PRINT NAME/SIGNATURE

06212R 07/13/11

RECEIVED JUL 13 2011 [Signature]

PURPOSE

1102 9 1 2011

GNT A
C DA
C T A

C= Collection T= Transportation A= Analysis

Handwritten initials/signature



CONTINUATION OF
BULK TRANSMITTAL FORM
CHAIN OF CUSTODY

71207065

CLIENT: CH 2 M/H/L

SAMPLE PREFIX 062112R

PROJECT NO./BILL GROUP: 2-2373114


SAMPLE NUMBER	COLOR	SAMPLE DESCRIPTION	SAMPLE LOCATION
1. <u>57</u>	<u>black</u>	<u>field membrane</u>	<u>lower ESE</u>
2. <u>57</u>	↓	↓	<u>west</u>
3. <u>58</u>	↓	↓	<u>south</u>
4. <u>59</u>	↓	↓	<u>NW</u>
5. <u>60</u>	↓	↓	<u>ENE</u>
6. <u>61</u>	↓	↓	<u>SSE</u>
7. <u>62</u>	<u>black</u>	<u>edge flashing (roof)</u>	<u>upper NE</u>
8. <u>63</u>	↓	↓	<u>SW</u>
9. <u>64</u>	↓	↓	<u>SC</u>
10. <u>65</u>	<u>black</u>	↓	<u>lower S</u>
11. <u>66</u>	↓	↓	<u>N</u>
12. <u>67</u>	↓	↓	<u>SW</u>
13. <u>68</u>	<u>black</u>	<u>wall curb flashing</u>	<u>south</u>
14. <u>69</u>	↓	↓	<u>north</u>
15. <u>70</u>	<u>black</u>	<u>VPR flashing</u>	<u>SSW</u>
16. <u>71</u>	↓	<u>exh fan flashing</u>	<u>south</u>
17. <u>72</u>	↓	<u>wall counter flashing</u>	<u>NW wall</u>
18.			
19.			
20.			
21.			
22.			
23.			
24.			
25.			
26.			
27.			
28.			
29.			
30.			
31.			
32.			
33.			
34.			
35.			

CHAIN OF CUSTODY:
DATE/TIME

062112
06/2/11

PRINT NAME/SIGNATURE

[Signature]
[Signature]



PURPOSE

C T A
 C T A
 C T A

C= Collection T= Transportation A= Analysis

[Handwritten initials]

APPENDIX C

FIGURES

ZONING SITE PLAN DATA:

REQUIRED LRS	PROVIDED
ZONING DESIGNATION	HPS
LOT SIZE	114,155 sq ft
SET BACKS	
FRONT	20'
REAR	10'
STREET SIDE	55' (10)
MAXIMUM FLOOR AREA	20,000 sq ft
MAXIMUM BUILDING COVER	20% (4,000 sq ft)
MAXIMUM IMPERVIOUS SURFACE	40% (8,000 sq ft)
MINIMUM TRAIL LANE WIDTH	50' (4,000 sq ft)
MINIMUM TRAIL LANE WIDTH	49' (4,000 sq ft)

PARKING

LPR REQUIRED: OFFICE USES 120 SPACES. MAINTENANCE USES: 8 SPACES. TOTAL 128 SPACES. ADDITIONAL 10 SPACES FOR TOTAL 138 SPACES. TOTAL 14 SPACES ARE NOT RECORDED IN 108 CASES. BICYCLES @ 15% = 64 / OK - 84


PROVIDED: (NOTE: PARKING MAY BE REDUCED IN FAVOR OF ADDITIONAL LANDSCAPING)

TYPE	QUANTITY	AREA (sq ft)
FULL SIZE SPACES	124	1996
COMPACT SPACES	20	300
BIKE SPACES	64	960
LANDSCAPING SPACES	6	90
TOTAL	214	3346

PLUS (1) LOADING SPACE @ 12' x 50'

BICYCLES: 64 @ 15% = 2 / BIKE

65



SCHEMATIC SITE PLAN

1" = 30'

GLYNN ARCHER SCHOOL
WHITE STREET
KEY WEST, FLORIDA



410 Ancestry Street
427 East, Florida 33106
Tel: (305) 355-1211
Fax: (305) 355-1212
Florida License #00000000


Bender & Associates
ARCHITECTS

Project No. 1025
Date: 8/29/79

OF 30

STRUCTURAL INVESTIGATION BUILDINGS A & B AND AUDITORIUM - FIRST FLOOR PLAN

GLYNN ARCHER SCHOOL - 1300 WHITE STREET
Key West - Florida




UNITED ST.

"A" WING
600T SF - NET AREA

"B" WING
1582 SF - NET AREA

SEMINARY STREET



- LEGEND:**
- ACCESS HOLES:
INDICATES 24"x24" ACCESS HOLE TO BE CUT AT THE EXISTING FIRST LEVEL TO EXPOSE THE EXISTING FLOOR STRUCTURE (BEAMS AND JOISTS) MEMBERS, UNLESS OTHER MEANS TO ACCESS THE UNDER SIDE OF THE FIRST FLOOR STRUCTURE EXISTS.
 - BORE HOLES:
INDICATES APPROXIMATE LOCATIONS OF THE SOIL INVESTIGATION BY BORING.
 - WALL OPENINGS:
INDICATES APPROXIMATE LOCATIONS OF THE INTERIOR WALL INVESTIGATION. EXPOSE BOTTOM OF WALL BY CUTTING 12"x16" OPENING AND EXPOSE TOP OF WALL ABOVE THE DROPPED CEILING LEVEL BY CUTTING 12"x16" OPENING.
 - FOOTING INVESTIGATION:
LOCATE TWO INTERIOR SPREAD FOOTINGS AND EXCAVATE TO THE BOTTOM OF FOOTING TO VERIFY THE FOOTING SIZE (LENGTH, WIDTH, AND THICKNESS).

- ACM KEY**
- CORR VFTS (2 LAYERS)
 - ROOM VFTS (1-2 LAYERS)
 - ROOM VFTS (1-2 LAYERS)
 - AUD LINO VFT (2 LAYERS)

- ROOM NUMBER**
- xxx - NOT USED
 - C - CEILING OPENING
 - W - WALL OPENING
 - F - FLOOR OPENING

- FOOTING INVESTIGATION:**
- ① CUT LATH & VERTICAL TILE AT COLUMN
 - ② FLOOR OPENING NOT MARKED

PROVIDE 24"x24" TEST PIT HOLE TO VERIFY PERIMETER FOOTING SIZE (WIDTH, THICKNESS)

PROVIDE 24"x24" TEST PIT HOLE TO VERIFY PERIMETER FOOTING SIZE (WIDTH, THICKNESS)


PROVIDE 24"x24" TEST PIT HOLE TO VERIFY PERIMETER FOOTING SIZE (WIDTH, THICKNESS)

PROVIDE 24"x24" TEST PIT HOLE TO VERIFY PERIMETER FOOTING SIZE (WIDTH, THICKNESS)


PROVIDE 24"x24" TEST PIT HOLE TO VERIFY PERIMETER FOOTING SIZE (WIDTH, THICKNESS)

PROVIDE 24"x24" TEST PIT HOLE TO VERIFY PERIMETER FOOTING SIZE (WIDTH, THICKNESS)

STRUCTURAL INVESTIGATION BUILDINGS A & B AND AUDITORIUM - SECOND FLOOR PLAN



Partial Second Floor Plan - A&B Wings



Primary Route →
 Secondary Route - - - - -

C - BUILDING

BACK COURT


EMPLOYEE PARKING


MIDDLE COURT

FIRST COURT

SEMINARY STREET

LEED STREET



ACM KEY	
	ROOF FLASHING
	VFT/MASTIC
	VFT/MASTIC (2 layers)
	VFT/MASTIC
	VFT/MASTIC

APPENDIX D
INSPECTION PHOTOGRAPHS



Photo 1: Glynn Archer Elementary School @ 1302 White Street, Key West



Photo 2: Typical nonACM 1'x1' ceiling tile on upper plaster ceilings




Photo 3: Typical nonACM 12"x12" beige VFT over Green ACM VFT/mastic



Photo 4: Typical 9" Red/white VFTs with ACM black mastic



Photo 5: Typical ACM 9"x9" VFT



Photo 6: Typical ACM 9"x9" Pink VFT



Photo 7: Typical ACM 9"x9" red and white VFTs in B215



Photo 8: Typical nonACM 2'x4' white ceiling tiles below nonACM 1x1' upper ceilings



Photo 9: Typical ACM 9"x9" white and green VFTs in B206




Photo 10: Auditorium – ACM linoleum over ACM maroon VFT under seats




Photo 11: Typical ACM pebble linoleum (top layer)



Photo 12: Typical nonACM 1'x1' brown ceiling tiles on Auditorium upper ceilings



Photo 13: Typical nonACM roof field membrane on Bldgs A, B, Aud, C



Photo 14: ACM VFT/mastic under carpet in office 119F



Photo 15: ACM VFT under newer VFTs in Bldg A main corridors



Photo 16: ACM VFT under newer VFTs in Bldg B main corridors




Photo 17: ACM VFT/mastic in C-133



Photo 18: Typical nonACM ceiling tiles in Bldg C corridors



Photo 19: Typical nonACM stucco finish on Aud building.



Photo 20: Typical nonACM 1x1' ceiling tiles and plaster above stage in Aud.



Photo 21: Typical nonACM window glazing on Building C



Photo 22: Typical nonACM TSI on Northside mech complex on Bldg C



Photo 23: Typical nonACM exterior stucco finishes on Bldg A



Photo 24: Typical nonACM exterior stucco finishes on Bldg A



Photo 25: Typical nonACM exterior stucco on Bldg C




Photo 26: Typical ACM mastic under VFT in cafeteria #136 servery areas



Photo 27: Typical ACM mastic under VFT in Cafeteria 135



Photo 28: Typical crawlspace view of Bldg B, no suspect ACMs observed



Photo 29: Typical crawlspace view of Bldg A, no suspect ACMs observed



Photo 30: Typical nonACM glue on 1x1' ceiling tiles



Photo 31: No suspect ACM in kitchen stores




Photo 32: ACM black curb/counterflashing on Bldg C against Library deck

APPENDIX E
CERTIFICATES



M·E·T·A

Mayhew Environmental Training Associates
I N C O R P O R A T E D

Certificate # 7ME04121208AIR00005

This is to certify that

Hiram Aguiar

has on 4/12/12, in Miami Lakes, FL

completed the requirements for asbestos accreditation under Section 206 of TSCA Title II, 15 U.S.C. 2646

AHERA Asbestos Building Inspector Refresher Course

*as approved by the State of Florida and the U.S.E.P.A. under 40 C.F.R. 763 (AHERA)
on 4/12/12 - 4/12/12 and passed the associated examination on 4/12/12*

with a score of 70% or better

CM = 0.5

Provider #: FL49-0001221

Course #: FL49-0004718

Soc. Sec #: XXX-XX-9801

Accreditation Expires: 4/12/13



W. 2. Young
Instructor
Bill Young

T. Bradford Mayhew
President
Thomas Bradford Mayhew

META - P.O. Box 786 - Lawrence KS 66044 - 800-444-6382

Asbestos Consulting & Training Systems

39388.6861CERT/BIR

900 N.W. 5TH Avenue, Fort Lauderdale, Florida 33311

(954) 524-7208

This is to Certify that

Ramsey Abreu



X X X - X X - 4 3 0 1

17934 SW 154 Ave. , Miami, FL

Processed By:

Seagull

To Authenticate Certificate:
www.seagulltraining.com
1-800-966-9933

has successfully completed an English

Asbestos Building Inspection Refresher

14-Oct-11

TO

14-Oct-11

Individual above has completed the requisite training for accreditation under TSCA Title II

Meets state requirements of FL49-0001020/CN-0006273.

NDAAC Provider #451

Trainer(s): James F. Stump

Training Address: 900 Northwest Fifth Ave., Fort Lauderdale, FL, 33311

Successful course completion based on exam score on: 14-Oct-11


This Certificate Expires:



1 0 / 1 3 / 1 2

13-Oct-12


James F. Stump, Course Sponsor



Certificate Number..... 1 5 0 9 1 5

Course Number SE1141

UNDER CIVIL AND CRIMINAL PENALTIES OF LAW FOR MAKING OR
REPRESENTING FALSE OR FRAUDULENT STATEMENTS OR
STATEMENTS OF OPINION (18 U.S.C. 1001 AND 18 U.S.C. 1013), I
CERTIFY THAT THIS TRAINING COMPLIES WITH ALL APPLICABLE
REGULATORY REQUIREMENTS OF TITLE II OF THE "TOXIC SUBSTANCES
CONTROL ACT," 40 CFR PART 763, AND ANY OTHER
APPLICABLE FEDERAL, STATE OR LOCAL REGULATIONS AS
APPROVED.



M·E·T·A
 Mayhew Environmental Training Associates
 I N C O R P O R A T E D

Certificate # 7ME09091101AIR0002

This is to certify that

Richard Grupenhoff

has on 9/9/11, in Miami Lakes, FL

completed the requirements for asbestos accreditation under Section 206 of TSCA Title II, 15 U.S.C. 2646

AHERA Asbestos Building Inspector Refresher Course

*as approved by the State of Florida and the U.S.E.P.A. under 40 C.F.R. 763 (AHERA)
 on 9/9/11 - 9/9/11 and passed the associated examination on 9/9/11
 with a score of 70% or better
 CM = 0.5*

CM = 0.5

Provider #: FL49-0001221

Course #: FL49-0004718

Soc. Sec #: XXX-XX-5232

Accreditation Expires: 9/9/12



W. Young


Instructor
 Bill Young

T. Bradford Mayhew

President
 Thomas Bradford Mayhew

M E T A - P.O. Box 786 - Lawrence KS 66044 - 800-444-6382

United States Department of Commerce
National Institute of Standards and Technology



Certificate of Accreditation to ISO/IEC 17025:2005

NVLAP LAB CODE: 101775-0

American Asbestos Laboratories, Inc.
Tampa, FL

is accredited by the National Voluntary Laboratory Accreditation Program for specific services,
listed on the Scope of Accreditation, for:

BULK ASBESTOS FIBER ANALYSIS

*This laboratory is accredited in accordance with the recognized International Standard ISO/IEC 17025:2005.
This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality
management system (refer to joint ISO-IAC-IAF Communique dated January 2009).*

2011-04-01 through 2012-03-31

Effective dates



Dolly S. Buce

For the National Institute of Standards and Technology



**National Voluntary
Laboratory Accreditation Program**



SCOPE OF ACCREDITATION TO ISO/IEC 17025:2005

American Asbestos Laboratories, Inc.

5005 W. Laurel St., Suite 110

Tampa, FL 33607

Dr. Daniel J. Cottrell

Phone: 813-287-1005 Fax: 813-285-8545

E-Mail: dcottrell@eeandg.com

BULK ASBESTOS FIBER ANALYSIS (PLM)

NVLAP LAB CODE 101775-0

NVLAP Code Designation / Description

18/A01 EPA-600/M4-82-020: Interim Method for the Determination of Asbestos in Bulk Insulation Samples

2011-04-01 through 2012-03-31

Effective dates

Dally S. Bruce

For the National Institute of Standards and Technology

AC# 5227070

STATE OF FLORIDA

DEPARTMENT OF BUSINESS AND PROFESSIONAL REGULATION
ASBESTOS LICENSING UNIT

SEQ# L10092501299

DATE	BATCH NUMBER	LICENSE NBR
09/25/2010	100120327	DD0000010

The ASBESTOS CONSULTANT
Named below IS LICENSED
Under the provisions of Chapter 469 FS.
Expiration date: NOV 30, 2012

COTTRELL, DANIEL JOSEPH
6367 SW 44 ST
MIAMI

FL 33155-5142



CHARLIE CRIST
GOVERNOR

DISPLAY AS REQUIRED BY LAW

CHARLIE LIEM
SECRETARY



Environmental Services, LLC

5751 Miami Lakes Drive
Miami Lakes, Florida 33014
Tel (305) 374-8300
Fax (305) 374-9004
www.eeandg.com

August 17, 2012
EE&G Project No. 2012-2373

Mr. Andrew H. Smyth
CH2M Hill
6410 5th Street, Suite 2A
Key West, Florida 33040

**Subject: Dust Wipe Sampling for Lead
Glynn Archer Elementary School
Buildings A, B and Auditorium
1302 White Street
Key West, Florida**

Dear Mr. Smyth:

At the request of CH2M Hill, EE&G Environmental Services L.L.C. (EE&G) conducted limited lead dust sampling at the subject property. Initial background sampling was conducted on July 16, 2012. Follow-up post testing was conducted on July 24 and 31, 2012. All testing was performed by certified Lead Risk Assessor Hiram Aguiar of EE&G. The purpose of the sampling was to determine the presence of lead in dust on floor surfaces impacted during exploratory engineering studies by CH2M Hill.

METHODS

Wipe samples of dust on various floor surfaces impacted during the renovation at Building A, B, and Auditorium were collected using protocols described by the Department of Housing and Urban Development (HUD), the Environmental Protection Agency (EPA), and the American Society for Testing and Materials (ASTM E 1728). The wipe samples were delivered to EMSL in Cinnaminson, New Jersey, for analysis of total lead by Flame AAS (Method SW 846, 7420). EMSL participates in the American Industrial Hygiene Association's (AIHA) Environmental Lead Laboratory Approval Program.

LIMITATIONS

This report has been prepared by EE&G in a manner consistent with standards exercised by members of the lead inspection profession practicing under similar conditions. No other warranty, expressed or implied is made. The intent of this report is to assist the client in assessing the occurrence of lead in dust. Under no circumstances is this letter to be utilized as a proposal or a project specification document without the written consent of EE&G.

EE&G's interpretations and recommendations are based upon the results of the sample analyses in compliance with environmental regulations, and information provided to EE&G by the client.

This report was prepared solely for the use of EE&G's client, and is not intended for use by third party beneficiaries. The client shall indemnify and hold EE&G harmless against any liability for any loss arising out of or relating to reliance by any third party on any work performed thereunder, or the contents of this report. EE&G will not be held responsible for the interpretation or use by others of data developed pursuant to the compilation of this report, nor for use of segregated portions of this report.

Mr. Andrew H. Smyth
CH2M Hill
August 17, 2012
Page 2

RESULTS

The EPA has established standards for lead in dust under the Residential Lead-Based Paint Hazard Reduction Act of 1992. Acceptable levels for lead in dust are 40 micrograms per square foot (ug/ft^2) for floors, 250 ug/ft^2 for interior window sills, and 400 ug/ft^2 for window troughs. Results of the analyses of three dust wipe samples indicated that all three samples had concentrations below detection limits. The laboratory report for the wipe sample analyses is attached.

CONCLUSIONS AND RECOMMENDATIONS

Testing conducted on July 24, 2012 after completion of the renovation work at Glynn Archer Elementary School reported 32 of the 34 dust samples collected had lead concentrations below the detection limit of the laboratory method. One of the 34 samples collected had lead concentrations well below the acceptable clearance levels. Sample #16 collected at Building B in Room 104 had a measured lead concentration of 350 ug/ft^2 . This value well exceeds the acceptable level for lead dust on floors. EE&G recommended that room 104 be HEPA-vacuumed, washed, and rinsed with clean water. After the additional cleaning was completed dust samples were collected and sent to EMSL for analysis. Dust samples collected on July 31, 2012 after the additional cleaning reported concentration below laboratories detectable limits. No further action is required, based on these sampling results.


If you have any further questions of concerns regarding this matter, please do not hesitate to contact us at (305) 374-8300.

Submitted by



Hiram Aguiar
EPA Certified Lead Risk Assessor, EE&G

Reviewed by



Daniel J. Cottrell, Ph.D., P.G.
Senior Technical Advisor, EE&G
EPA Certified Lead Risk Assessor

Attachments: Laboratory Reports
Certificates

EMSL LABORATORY REPORT

LEAD IN DUST BY FLAME AAS (SW 846 3050B and 7420)



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-9551

<http://www.emsl.com>

cinnaminsonleadlab@emsl.com

EMSL Order: 201206931

CustomerID: EEG50

CustomerPO:

ProjectID:

Attn: **Hiram Aguiar**
EE & G
5751 Miami Lakes Drive East
Miami Lakes, FL 33014

Phone: (305) 374-8300
Fax:
Received: 07/18/12 10:03 AM
Collected: 7/16/2012

Project: **Glynn Archer School**

Test Report: Lead in Dust by Flame AAS (SW 846 3050B*/7000B)

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
1	0001	7/16/2012	7/20/2012	144 in ²	<10 µg/ft ²
Site: Rm 100 Bldg A					
2	0002	7/16/2012	7/20/2012	144 in ²	<10 µg/ft ²
Site: Rm 103 Bldg A					
3	0003	7/16/2012	7/20/2012	144 in ²	<10 µg/ft ²
Site: Fl-1 Corr Bldg A					
4	0004	7/16/2012	7/20/2012	144 in ²	<10 µg/ft ²
Site: Auditorium Bldg A					
5	0005	7/16/2012	7/20/2012	144 in ²	<10 µg/ft ²
Site: WO-14 Bldg A					
6	0006	7/16/2012	7/20/2012	144 in ²	<10 µg/ft ²
Site: WO-17 Bldg A					
7	0007	7/16/2012	7/20/2012	144 in ²	<10 µg/ft ²
Site: Fl-1 Corr Bldg A					
8	0008	7/16/2012	7/20/2012	144 in ²	<10 µg/ft ²
Site: Rm 102 Bldg A					
9	0009	7/16/2012	7/20/2012	144 in ²	<10 µg/ft ²
Site: Rm 102 Wall Bldg A					
10	0010	7/16/2012	7/20/2012	144 in ²	<10 µg/ft ²
Site: Fl-1 Corr Wall Bldg A					
11	0011	7/16/2012	7/20/2012	144 in ²	<10 µg/ft ²
Site: Fl-2 Corr Bldg A					
12	0012	7/16/2012	7/20/2012	144 in ²	<10 µg/ft ²
Site: Rm 204 Bldg A					
13	0013	7/16/2012	7/20/2012	144 in ²	<10 µg/ft ²
Site: Rm 212 Bldg A					
14	0014	7/16/2012	7/20/2012	144 in ²	<10 µg/ft ²
Site: Rm 212 Bldg A					
15	0015	7/16/2012	7/20/2012	144 in ²	<10 µg/ft ²
Site: Rm 205 Bldg A					

Julie Smith - Laboratory Director
NJ-NELAP Accredited:04653
or other approved signatory

Reporting limit is 10 ug/wipe. ug/wipe = ug/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. QC data associated with this sample set is within acceptable limits, unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependant on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. * slight modifications to methods applied. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10896, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-9551

<http://www.emsl.com>

cinnaminsonleadlab@emsl.com

EMSL Order: 201206931

CustomerID: EEG50

CustomerPO:

ProjectID:

Attn: **Hiram Aguiar**
EE & G
5751 Miami Lakes Drive East
Miami Lakes, FL 33014

Phone: (305) 374-8300
Fax:
Received: 07/18/12 10:03 AM
Collected: 7/16/2012

Project: **Glynn Archer School**

Test Report: Lead in Dust by Flame AAS (SW 846 3050B*/7000B)

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
16	0016	7/16/2012	7/20/2012	144 in ²	<10 µg/ft ²
Site: Rm 205 Bldg A					
17	0017	7/16/2012	7/20/2012	144 in ²	<10 µg/ft ²
Site: Rm 205 Bldg A					
18	0018	7/16/2012	7/20/2012	144 in ²	<10 µg/ft ²
Site: Rm 203 Bldg A					
19	0019	7/16/2012	7/20/2012	144 in ²	<10 µg/ft ²
Site: Rm 104 Bldg B					
20	0020	7/16/2012	7/20/2012	144 in ²	32 µg/ft ²
Site: Rm 104 Wall Bldg B					
21	0021	7/16/2012	7/19/2012	144 in ²	<10 µg/ft ²
Site: Fl-1 Corr Bldg B					
22	0022	7/16/2012	7/19/2012	144 in ²	<10 µg/ft ²
Site: Rm 107 Bldg B					
23	0023	7/16/2012	7/19/2012	144 in ²	22 µg/ft ²
Site: Rm 109 Bldg B					
24	0024	7/16/2012	7/19/2012	144 in ²	<10 µg/ft ²
Site: Rm 105 Bldg B					
25	0025	7/16/2012	7/19/2012	144 in ²	<10 µg/ft ²
Site: Rm 105 Wall Bldg B					
26	0026	7/16/2012	7/19/2012	144 in ²	<10 µg/ft ²
Site: Rm 106 Bldg B					
27	0027	7/16/2012	7/19/2012	144 in ²	<10 µg/ft ²
Site: Rm 210 Bldg B					
28	0028	7/16/2012	7/19/2012	144 in ²	<10 µg/ft ²
Site: Rm 207 Bldg B					
29	0029	7/16/2012	7/19/2012	144 in ²	<10 µg/ft ²
Site: Rm 206 Bldg B					
30	0030	7/16/2012	7/19/2012	144 in ²	<10 µg/ft ²
Site: WA-06 Bldg B					

Julie Smith - Laboratory Director
NJ-NELAP Accredited:04653
or other approved signatory

Reporting limit is 10 ug/wipe. ug/wipe = ug/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. QC data associated with this sample set is within acceptable limits, unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependant on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. * slight modifications to methods applied. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10896, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01



EMSL ANALYTICAL, INC.
LABORATORY • PRODUCTS • TRAINING

Lead (Pb) Chain of Custody

EMSL Order ID (Lab Use Only):

201206931

EMSL ANALYTICAL, INC.
200 ROUT 130 NORTH
CINNAMINSON, NJ 08077

Company : EE&G Environmental Services, LLC			EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different If Bill to is Different note instructions in Comments**	
Street: 5751 Miami Lakes Drive			Third Party Billing requires written authorization from third party	
City: Miami Lakes	State/Province: FL	Zip/Postal Code: 33014	Country: USA	
Report To (Name): Hiram Aguiar			Fax #: 305-374-9004	
Telephone #: 305-374-8300			Email Address: Haguiar@eeandg.com	
Project Name/Number: Glynn Archer School				
Please Provide Results: <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email		Purchase Order:	U.S. State Samples Taken:	
Turnaround Time (TAT) Options* - Please Check				
<input type="checkbox"/> 3 Hours	<input type="checkbox"/> 6 Hours	<input type="checkbox"/> 24 Hours	<input type="checkbox"/> 48 Hours	<input type="checkbox"/> 3 Days
				<input checked="" type="checkbox"/> 4 Days
				<input type="checkbox"/> 5 Days
				<input type="checkbox"/> 10 Days
<small>*Analysis completed in accordance with EMSL's Terms and Conditions located in the Price Guide</small>				
Matrix	Method	Instrument	Reporting Limit	Check
Chips <input type="checkbox"/> mg/cm ² <input type="checkbox"/> % by wt.	SW846-7000B/7420 or AOAC 974.02	Flame Atomic Absorption	0.01%	<input type="checkbox"/>
	Air	NIOSH 7082	Flame Atomic Absorption	4 µg/filter
	NIOSH 7105	Graphite Furnace AA	0.03 µg/filter	<input type="checkbox"/>
	NIOSH 7300 modified	ICP-AES	0.5 µg/filter	<input type="checkbox"/>
Wipe* <input checked="" type="checkbox"/> ASTM <input type="checkbox"/> non ASTM <small>*if no box is checked, non-ASTM Wipe is assumed</small>	SW846-7000B/7420	Flame Atomic Absorption	10 µg/wipe	<input checked="" type="checkbox"/>
	SW846-6010B or C	ICP-AES	0.5 µg/wipe	<input type="checkbox"/>
TCLP	SW846-1311/7420/SM 3111B	Flame Atomic Absorption	0.4 mg/L (ppm)	<input type="checkbox"/>
	SW846-6010B or C	ICP-AES	0.1 mg/L (ppm)	<input type="checkbox"/>
Soil	SW846-7420	Flame Atomic Absorption	40 mg/kg (ppm)	<input type="checkbox"/>
	SW846-7421	Graphite Furnace AA	0.3 mg/kg (ppm)	<input type="checkbox"/>
	SW86-6010B or C	ICP-AES	1 mg/kg (ppm)	<input type="checkbox"/>
Wastewater	SM3111B or SW846-7000B/7420	Flame Atomic Absorption	0.4 mg/L (ppm)	<input type="checkbox"/>
	EPA 200.9	Graphite Furnace AA	0.003 mg/L (ppm)	<input type="checkbox"/>
	SW846-6010B or C	ICP-AES	1 mg/kg (ppm)	<input type="checkbox"/>
Drinking Water	EPA 200.9	Graphite Furnace AA	0.003 mg/L (ppm)	<input type="checkbox"/>
Other:		Preservation Method (Water):		
Name of Sampler: Hiram Aguiar		Signature of Sampler:		
Sample #	Location	Volume/Area	Date/Time Sampled	
1	RM 100 Bldg. A	12" x 12" (1 SF)	7-16-12 1230	
2	RM 103	↓	1232	
3	FI-1 COM		1234	
4	Auditorium		1235	
5	WD -14		1237	
6	WD -17		1240	
Client Sample #'s 1 -			Total # of Samples:	
Relinquished (Client):	Hiram Aguiar	Date:	Time:	
Received (Lab):	<i>[Signature]</i>	Date:	7/18/12	Time: 1:03 PM
Comments:				



EMSL ANALYTICAL, INC.
LABORATORY • PRODUCTS • TRAINING

LEAD (Pb) CHAIN OF CUSTODY

EMSL ORDER ID (Lab Use Only):

201206931

EMSL ANALYTICAL, INC.
200 ROUT 130 NORTH
CINNAMINSON, NJ
08077

PHONE: (856) 858-4800

FAX: (856) 858-3899

Additional Pages of the Chain of Custody are only necessary if needed for additional sample information

Sample #	Location	Volume/Area	Date/Time Sampled
7	F1-1 CORR Bldg A	12"X12" (1SF)	7-16-12 1244
8	RM 102		1246
9	RM 102 Wall		1248
10	F1-1 CORR Wall		1252
11	F1-2 CORR		1255
12	RM 204		1259
13	RM 212		1259
14	RM 212		1300
15	RM 205		1305
16	RM 205		1306
17	RM 205		1307
18	RM 203		1310
19	RM 104 Bldg B		1320
20	RM 104 Wall		1321
21	F1-1 CORR		1323
22	RM 107		1325
23	RM 109		1327
24	RM 105		1330
Comments/Special Instructions:			



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-9551

<http://www.emsl.com>

cinnaminsonleadlab@emsl.com

EMSL Order: 201207282

CustomerID: EEG50

CustomerPO:

ProjectID:

Attn: **Hiram Aguiar**
EE & G
5751 Miami Lakes Drive East
Miami Lakes, FL 33014

Phone: (305) 374-8300
Fax:
Received: 07/26/12 9:30 AM
Collected: 7/24/2012

Project: **Glynn Archer School**

Test Report: Lead in Dust by Flame AAS (SW 846 3050B*/7000B)

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
1	0001	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg A W. Hall Fl 1					
2	0002	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg A N. Hall Fl 1					
3	0003	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg A S. Hall Fl 1					
4	0004	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg A S.E. Hall Fl 1					
5	0005	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg A Rm 100 Fl 1					
6	0006	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg A S.E. Hall Fl 2					
7	0007	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg A Rm 212 Fl 2					
8	0008	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg A Rm 212 Fl 2					
9	0009	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg A Rm 203 Fl 2					
10	0010	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg A Rm 205 Fl 2					
11	0011	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg A Rm 205 Fl 2					
12	0012	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg A Rm 205 Fl 2					
13	0013	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Auditorium					
14	0014	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Auditorium					
15	0015	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg B Rm 104 Fl 1					

Julie Smith - Laboratory Director
NJ-NELAP Accredited:04653
or other approved signatory

Reporting limit is 10 ug/wipe. ug/wipe = ug/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. QC data associated with this sample set is within acceptable limits, unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependant on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. * slight modifications to methods applied. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10896, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 07/27/2012 12:49:22



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-9551

<http://www.emsl.com>

cinnaminsonleadlab@emsl.com

EMSL Order: 201207282

CustomerID: EEG50

CustomerPO:

ProjectID:

Attn: **Hiram Aguiar**
EE & G
5751 Miami Lakes Drive East
Miami Lakes, FL 33014

Phone: (305) 374-8300
Fax:
Received: 07/26/12 9:30 AM
Collected: 7/24/2012

Project: **Glynn Archer School**

Test Report: Lead in Dust by Flame AAS (SW 846 3050B*/7000B)

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
16	0016	7/24/2012	7/26/2012	144 in ²	350 µg/ft ²
Site: Bldg B Rm 104 Fl 1					
17	0017	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg B Rm 109 Fl 1					
18	0018	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg B Boys RRM Fl 1					
19	0019	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg B Boys RRM Fl 1					
20	0020	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg B Rm 105 Fl 1					
22	0022	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg B Rm 105 Fl 1					
23	0023	7/24/2012	7/26/2012	144 in ²	22 µg/ft ²
Site: Bldg B N.W. Hall Fl 1					
24	0024	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg B Rm 106 Fl 1					
25	0025	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg B E. Hall Fl 1					
26	0026	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg B Rm 107 Fl 1					
27	0027	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg B Rm 207 Fl 2					
28	0028	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg B Rm 210 Fl 2					
29	0029	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg B Rm 210 Fl 2					
30	0030	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg See Plan Fl 2					
31	0031	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg See Plan Fl 2					

Julie Smith - Laboratory Director
NJ-NELAP Accredited:04653
or other approved signatory

Reporting limit is 10 ug/wipe. ug/wipe = ug/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. QC data associated with this sample set is within acceptable limits, unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependant on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. * slight modifications to methods applied. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10896, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 07/27/2012 12:49:22



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-9551

<http://www.emsl.com>

cinnaminsonleadlab@emsl.com

EMSL Order: 201207282

CustomerID: EEG50

CustomerPO:

ProjectID:

Attn: **Hiram Aguiar**
EE & G
5751 Miami Lakes Drive East
Miami Lakes, FL 33014

Phone: (305) 374-8300
Fax:
Received: 07/26/12 9:30 AM
Collected: 7/24/2012

Project: **Glynn Archer School**

Test Report: Lead in Dust by Flame AAS (SW 846 3050B*/7000B)

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
32	0032	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg See Plan FI 2					
33	0033	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg Rm 206 FI 2					
34	0034	7/24/2012	7/26/2012	144 in ²	<10 µg/ft ²
Site: Bldg Rm 206 FI 2					

Julie Smith - Laboratory Director
NJ-NELAP Accredited:04653
or other approved signatory

Reporting limit is 10 ug/wipe. ug/wipe = ug/ft2 x area sampled in ft2. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. QC data associated with this sample set is within acceptable limits, unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependant on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. * slight modifications to methods applied. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10896, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 07/27/2012 12:49:22



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS/TEXAS

Lead (Pb) Chain of Custody

EMSL Order ID (Lab Use Only):

201207269

Company : City of Austin LeadSmart Program Street: 1000 East 11 th Street Ste. 200 City: Austin State/Province: TX Report To (Name): Coby Ramirez Telephone #: 512-974-3122 Email Address: coby.ramirez@austintexas.gov Project Name/Number: MA 7200NA120000127 -4519 South 2 nd Street Austin TX, 78745 Project # 32 U.S. State Samples Taken: Texas		EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different If Bill to is Different note instructions in Comments** Third Party Billing requires written authorization from third party Zip/Postal Code: 78702 Country: US Telephone #: 512-974-3122 Fax #: 512-974-3152 Purchase Order: MA7200NA120000127 Please Provide Results: <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email Connecticut Samples: <input type="checkbox"/> Commercial <input type="checkbox"/> Residential		
Turnaround Time (TAT) Options* - Please Check <input type="checkbox"/> 3 Hour <input type="checkbox"/> 6 Hour <input checked="" type="checkbox"/> 24 Hour <input type="checkbox"/> 48 Hour <input type="checkbox"/> 72 Hour <input type="checkbox"/> 96 Hour <input type="checkbox"/> 1 Week <input type="checkbox"/> 2 Week <small>*Analysis completed in accordance with EMSL's Terms and Conditions located in the Price Guide</small>				
Matrix	Method	Instrument	Reporting Limit	Check
Chips <input type="checkbox"/> % by wt. <input type="checkbox"/> mg/cm ² <input type="checkbox"/> ppm	SW846-7000B/7420 or AOAC 974.02	Flame Atomic Absorption	0.01%	<input type="checkbox"/>
Air	NIOSH 7082 NIOSH 7105 NIOSH 7300 modified	Flame Atomic Absorption Graphite Furnace AA ICP-AES	4 µg/filter 0.03 µg/filter 0.5 µg/filter	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Wipe* <input checked="" type="checkbox"/> ASTM <input type="checkbox"/> non ASTM <small>*if no box is checked, non-ASTM Wipe is assumed</small>	SW846-7000B/7420 SW846-6010B or C	Flame Atomic Absorption ICP-AES	10 µg/wipe 0.5 µg/wipe	<input checked="" type="checkbox"/> <input type="checkbox"/>
TCLP	SW846-1311/7420/SM 3111B SW846-6010B or C	Flame Atomic Absorption ICP-AES	0.4 mg/L (ppm) 0.1 mg/L (ppm)	<input type="checkbox"/> <input type="checkbox"/>
Soil	SW846-7000B/7420 SW846-7421 SW846-6010B or C	Flame Atomic Absorption Graphite Furnace AA ICP-AES	40 mg/kg (ppm) 0.3 mg/kg (ppm) 1 mg/kg (ppm)	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Wastewater	SM3111B or SW846-7000B/7420 EPA 200.9 SW846-6010B or C	Flame Atomic Absorption Graphite Furnace AA ICP-AES	0.4 mg/L (ppm) 0.003 mg/L (ppm) 0.020 mg/L (ppm)	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Drinking Water	EPA 200.9	Graphite Furnace AA	0.003 mg/L (ppm)	<input type="checkbox"/>
Other:		Preservation Method (Water):		
Name of Sampler: Coby Ramirez		Signature of Sampler: <i>Coby Ramirez</i>		
Sample #	Location	Volume/Area	Date/Time Sampled	
#82	Dust Wipe Living Room floor entry	12x12	7/25/2012 / 10:30 am	
#83	Dust Wipe Bathroom floor entry	12x12	7/25/2012 / 10:30 am	
#84	Dust Wipe Bathroom floor	12x12	7/25/2012 / 10:30 am	
#85	Dust Wipe Bedroom #3 Window Sill	18x2	7/25/2012 / 10:30 am	
#86	Dust Wipe Bedroom #3 Window Sill	18x2	7/25/2012 / 10:30 am	
Client Sample #'s #82 - #86		Total # of Samples: 5		
Relinquished (Client):	Coby Ramirez	Date: 7/25/2012	Time: 2:30 pm	
Received (Lab):	<i>py</i>	Date: 7/26/12	Time: 1230	

** New COC sent via email from Coby Ramirez to reflect correct
 protect address py 7/26/12 1230*

Comments: Please e-mail results to coby.ramirez@austintexas.gov
Account: CAHD25



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-9551

<http://www.emsl.com>

cinnaminsonleadlab@emsl.com

EMSL Order: 201207495

CustomerID: EEG50

CustomerPO:

ProjectID:

Attn: **Hiram Aguiar**
EE & G
5751 Miami Lakes Drive East
Miami Lakes, FL 33014

Phone: (305) 374-8300
Fax:
Received: 08/01/12 9:40 AM
Collected: 7/31/2012

Project: **Glynn Archer School**

Test Report: Lead in Dust by Flame AAS (SW 846 3050B*/7000B)

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	0001	7/31/2012	8/1/2012	144 in ²	<10 µg/ft ²
Site: Building B room 104					
2	0002	7/31/2012	8/1/2012	144 in ²	<10 µg/ft ²
Site: Building B room 104					
3	0003	7/31/2012	8/1/2012	144 in ²	<10 µg/ft ²
Site: Building B room 104					

Julie Smith - Laboratory Director
NJ-NELAP Accredited:04653
or other approved signatory

Reporting limit is 10 ug/wipe. ug/wipe = ug/ft2 x area sampled in ft2. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. QC data associated with this sample set is within acceptable limits, unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependant on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. * slight modifications to methods applied. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10896, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 08/01/2012 21:18:35



EMSL ANALYTICAL, INC.
LABORATORY • PRODUCTS • TRAINING

Lead (Pb) Chain of Custody

EMSL Order ID (Lab Use Only):

201207495

EMSL ANALYTICAL, INC.
200 ROUT 130 NORTH
CINNAMINSON, NJ 08077

Company : EE&G Environmental Services, LLC			EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different If Bill to is Different note instructions in Comments**		
Street: 5751 Miami Lakes Drive			Third Party Billing requires written authorization from third party		
City: Miami Lakes		State/Province: FL	Zip/Postal Code: 33014	Country: USA	
Report To (Name): Hiram Aguiar			Fax #: 305-374-9004		
Telephone #: 305-374-8300			Email Address: Haguair@eeandg.com		
Project Name/Number: Glynn Archer School					
Please Provide Results: <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email		Purchase Order:		U.S. State Samples Taken:	
Turnaround Time (TAT) Options* - Please Check					
<input type="checkbox"/> 3 Hours	<input type="checkbox"/> 6 Hours	<input checked="" type="checkbox"/> 24 Hours	<input type="checkbox"/> 48 Hours	<input type="checkbox"/> 3 Days	<input type="checkbox"/> 4 Days
<input type="checkbox"/> 5 Days	<input type="checkbox"/> 10 Days				
<small>*Analysis completed in accordance with EMSL's Terms and Conditions located in the Price Guide</small>					
Matrix		Method	Instrument	Reporting Limit	Check
Chips <input type="checkbox"/> mg/cm ² <input type="checkbox"/> % by wt.		SW846-7000B/7420 or AOAC 974.02	Flame Atomic Absorption	0.01%	<input type="checkbox"/>
Air		NIOSH 7082	Flame Atomic Absorption	4 µg/filter	<input type="checkbox"/>
		NIOSH 7105	Graphite Furnace AA	0.03 µg/filter	<input type="checkbox"/>
		NIOSH 7300 modified	ICP-AES	0.5 µg/filter	<input type="checkbox"/>
Wipe* <input checked="" type="checkbox"/> ASTM <input type="checkbox"/> non ASTM		SW846-7000B/7420	Flame Atomic Absorption	10 µg/wipe	<input checked="" type="checkbox"/>
<small>*if no box is checked, non-ASTM Wipe is assumed</small>		SW846-6010B or C	ICP-AES	0.5 µg/wipe	<input type="checkbox"/>
TCLP		SW846-1311/7420/SM 3111B	Flame Atomic Absorption	0.4 mg/L (ppm)	<input type="checkbox"/>
		SW846-6010B or C	ICP-AES	0.1 mg/L (ppm)	<input type="checkbox"/>
Soil		SW846-7420	Flame Atomic Absorption	40 mg/kg (ppm)	<input type="checkbox"/>
		SW846-7421	Graphite Furnace AA	0.3 mg/kg (ppm)	<input type="checkbox"/>
		SW86-6010B or C	ICP-AES	1 mg/kg (ppm)	<input type="checkbox"/>
Wastewater		SM3111B or SW846-7000B/7420	Flame Atomic Absorption	0.4 mg/L (ppm)	<input type="checkbox"/>
		EPA 200.9	Graphite Furnace AA	0.003 mg/L (ppm)	<input type="checkbox"/>
		SW846-6010B or C	ICP-AES	1 mg/kg (ppm)	<input type="checkbox"/>
Drinking Water		EPA 200.9	Graphite Furnace AA	0.003 mg/L (ppm)	<input type="checkbox"/>
Other:			Preservation Method (Water):		
Name of Sampler: Hiram Aguiar			Signature of Sampler:		
Sample #	Location		Volume/Area	Date/Time Sampled	
1	Building B Room 104		12"x12" (1 SF)	7-31-12/1130	
2	Building B Room 104		12"x12" (1 SF)	7-31-12/1130	
3	Building B Room 104		12"x12" (1 SF)	7-31-12/1130	
4					
5					
6					
Client Sample #'s		1 - 3	Total # of Samples:		3
Relinquished (Client):	Hiram Aguiar	Date:	7-31-12	Time:	1730
Received (Lab):	emily maggioncalda	Date:	8/1/12	Time:	9:40 AM
Comments:					

CERTIFICATES

United States Environmental Protection Agency

This is to certify that

Hiram Andres Aguiar

has fulfilled the requirements of the Toxic Substances Control Act (TSCA) Section 402, and has received certification to conduct lead-based paint activities pursuant to 40 CFR Part 745.226 as a:

Risk Assessor

In the Jurisdiction of:

Florida


This certification is valid from the date of issuance and expires August 1, 2014

FL-R-9781-1

Certification #

JUL 28 2011

Issued On


Jeaneanne M. Gettle, Chief

Pesticides and Toxic Substances Branch



United States Environmental Protection Agency

This is to certify that

Daniel Joseph Cottrell

has fulfilled the requirements of the Toxic Substances Control Act (TSCA) Section 402, and has received certification to conduct lead-based paint activities pursuant to 40 CFR Part 745.226 as a:

Risk Assessor

In the Jurisdiction of:

Florida


This certification is valid from the date of issuance and expires December 27, 2013

FL-R-10745-3

Certification #

FEB 2 - 2011

Issued On



Jeaneanne M. Gettle, Chief

Pesticides and Toxic Substances Branch



United States Environmental Protection Agency

This is to certify that



EE&G Environmental Services, LLC

has fulfilled the requirements of the Toxic Substances Control Act (TSCA) Section 402, and has received certification to conduct lead-based paint activities pursuant to 40 CFR Part 745.226

In the Jurisdiction of:

Florida

This certification is valid from the date of issuance and expires September 8, 2013

FL-10142-3

Certification #

SEP 2 2 2010

Issued On

A handwritten signature in blue ink, appearing to read "Jeanne M. Gettle".

Jeanne M. Gettle, Chief

Pesticides and Toxic Substances Branch





ENVIRONMENTAL SERVICES, LLC

**LIMITED
LEAD-BASED PAINT INSPECTION REPORT**

FOR

**GLYNN R. ARCHER ELEMENTARY SCHOOL COMPLEX
CITY HALL PLANNING PROJECT
1302 WHITE STREET
KEY WEST, FLORIDA 33040**

Prepared for

CH2M HILL
6410 5th STREET, SUITE 2A
KEY WEST, FLORIDA 33040

MR. ANDREW H. SMYTH

Prepared by

Hiram A. Aguiar
EPA Lead Risk Assessor Certificate #FL-R-9781-1



EE&G Environmental Services, LLC
5751 Miami Lakes Drive East
Miami, Florida 33014
(305) 374-8300
www.eeandg.com

August 17, 2012
EE&G Project No. 2012-2373

CONTENTS

<u>Section</u>	<u>Page</u>
1.0 - INTRODUCTION.....	1
1.1 INTRODUCTION	1
1.2 OWNER INFORMATION	1
1.3 EDUCATIONAL MATERIALS	1
2.0 – BUILDING DESCRIPTION.....	2
3.0 - METHODS AND LIMITATIONS	3
3.1 XRF METHODS.....	3
3.2 LIMITATIONS	3
4.0 - INSPECTION FINDINGS	5
4.1 XRF TESTING RESULTS.....	5
5.0 - RECOMMENDATIONS.....	6
5.1 RECOMMENDATIONS FOR LEAD-BASED PAINT.....	6
5.2 RECOMMENDATIONS FOR OTHER PAINTS AND COATINGS	7
5.3 OSHA COMPLIANCE	7
5.4 DISCLOSURE OF LBP HAZARDS.....	8
6.0 - SIGNATURE PAGE	9

APPENDICES

- APPENDIX A Renovate Right-Important Lead Hazard Information for Families, Child Care Providers, and Schools
- APPENDIX B XRF Testing Data
- APPENDIX C Figures
- APPENDIX D Photographs

SECTION 1.0

INTRODUCTION

1.1 INTRODUCTION

At the request of the CH2M Hill (hereafter referred to as the Owner), EE&G Environmental Services, LLC (EE&G) conducted a limited Lead-Based Paint (LBP) inspection of buildings A, B, Auditorium, and C at Glynn Archer Elementary School located at 1302 White Street, Key West, Florida in June 2012 by Environmental Protection Agency (EPA) Lead-Based Paint Risk Assessor Hiram Aguiar of EE&G. EE&G's scope of work for this project consisted of evaluating the subject facility utilizing an X-Ray Fluorescence (XRF) instrument to assess for lead concentrations in selected painted building components.

1.2 OWNER INFORMATION

Not Available at the time of this inspection.

1.3 EDUCATIONAL MATERIALS

A copy of *Renovate Right: Important Lead Hazard Information for Families, Child Care Providers, and Schools* has been provided in Appendix A of this report. Federal law requires that individuals receive certain information before renovating more than two square feet of painted surfaces in housing, child care facilities and schools built before 1978.

- Homeowners and tenants: renovators must give you this pamphlet before starting work.
- Child-care facilities, including preschools and kindergarten classrooms, and the families of children under the age of six that attend those facilities: renovators must provide a copy of this pamphlet to child-care facilities and general renovation information to families whose children attend those facilities.

Federal law requires contractors that disturb lead-based paint in homes, child care facilities and schools built before 1978 to be certified and follow specific work practices to prevent lead contamination. Contractors must provide certification prior to renovations.

SECTION 2.0**BUILDING DESCRIPTION
GLYNN ARCHER ELEMENTARY SCHOOL****BUILDING A**

The two-story classroom building, constructed in the 1920's, was observed to be constructed primarily of concrete, steel, and wood; interior walls were observed to be finished with plaster and drywall, ceilings were observed to be finished with laid-in ceiling tile, plaster and drywall. Floors were observed to be finished with vinyl floor tile, wood, and ceramic tile. County records were not available to review during the time of this inspection. See Appendix C for Figures.

BUILDING B

The two-story classroom building, constructed in the 1920's, was observed to be constructed primarily of concrete, steel, and wood; interior walls were observed to be finished with plaster and drywall, ceilings were observed to be finished with laid-in ceiling tile, plaster and drywall. Floors were observed to be finished with vinyl floor tile, wood, and ceramic tile. County records were not available to review during the time of this inspection. See Appendix C for Figures.

AUDITORIUM BUILDING

The one-story auditorium building, constructed in the 1920's, was observed to be constructed primarily of concrete, steel, and wood; interior walls were observed to be finished with plaster and drywall, ceilings were observed to be finished with laid-in ceiling tile, plaster and drywall. Floors were observed to be finished with linoleum and wood. County records were not available to review during the time of this inspection. See Appendix C for Figures.

BUILDING C

The one-story classroom building, constructed in the 1950's, was observed to be constructed primarily of concrete, steel, and wood; interior walls were observed to be finished with plaster and drywall, ceilings were observed to be finished with laid-in ceiling tile, plaster and drywall. Floors were observed to be finished with vinyl floor tile, wood, and ceramic tile. County records were not available to review during the time of this inspection. See Appendix C for Figures.

SECTION 3.0

METHODS AND LIMITATIONS

3.1 XRF METHODS

The limited inspection was performed based on a modified version of the protocol established in the "Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing" by the Department of Housing and Urban Development (HUD) in June 1995. A portable spectrum analyzing XRF instrument manufactured by Niton Corporation was utilized to perform a limited LBP inspection of accessible interior and exterior painted building components of buildings A, B, and Auditorium located at the subject property. The XRF serial number was 7510, and last date of calibration was July 11, 2011.

The XRF instrument performs a self-calibration test on startup. The calibration was then verified using a known standard from the United States Department of Commerce National Institute of Standards and Technology (NIST). QA/QC measurements were taken with the Level III (1.04 mg/cm²) NIST standard at the beginning and end of the inspection. XRF test results expressed lead concentrations in milligram per square centimeter (mg/cm²). The results were stored in the XRF for later retrieval in a spreadsheet format.

XRF testing locations, or testing combinations, were determined on site by an EPA Certified Lead-Based Paint Risk Assessor and the following factors; location (e.g. Building, Floor, Unit, Room), component (e.g. Wall, Ceiling, Door, Door Frame, Baseboard, etc.), substrate (e.g. Drywall, Concrete, Wood, Metal, etc.), and painting history (if available). An XRF reading was obtained from selected testing combinations.

3.2 LIMITATIONS

The limited inspection was conducted to assess selected painted building components for the presence of lead. Because of limitations in access this inspection can not be utilized as a Lead-Based Paint Inspection as defined in the HUD Guidelines, that is beyond the intent and scope of this limited inspection. The inspected areas are assumed to be representative of the materials used throughout the facility. This limited inspection report has been prepared by EE&G in a manner consistent with industry standards exercised by members of the profession practicing under similar conditions. No other warranty, expressed or implied is made. Under no circumstances is this limited inspection report to be utilized as a bid proposal or a project specification document, as this is not its intent. The intent of this inspection report is to assist the client in assessing for lead in selected painted building components.

EPA and HUD define lead-based paint (LBP) as; paint or other coatings that contain lead at or greater than the level of 1.0 mg/cm² or 0.5% by weight; however, the US Department of Labor's Occupational Safety and Health Administration (OSHA) lead regulation, 29 CFR 1926.62, does not recognize a concentration of lead in paint that may be safe for workers therefore, measurable amounts of lead are considered to be a potential source of exposure. This assessment can be utilized to identify building components that contain lead. However, as OSHA does not recognize the absence of lead through XRF, this assessment can not be utilized for establishing that coatings are lead-free for purposes of OSHA compliance.

EE&G's interpretations and recommendations are based upon the results of the XRF testing, environmental regulations, and quality control and assurance standards. The results, conclusions, and recommendations contained in this report pertain to conditions observed at the time of the inspection. Other conditions elsewhere at the subject facility may differ from those in the inspected locations and, such conditions are unknown, may change over time, and have not been considered.

This report was prepared solely for the use of EE&G's client, and is not intended for use by third party beneficiaries. The client shall indemnify and hold EE&G harmless against any liability for any loss arising out of or relating to reliance by any third party on any work performed there under, or the contents of this report. EE&G will not be held responsible for the interpretation or use by others of data developed pursuant to the compilation of this report, or for use of segregated portions of this report.

SECTION 4.0

INSPECTION FINDINGS

4.1 XRF TESTING RESULTS

HUD defines LBP as; paints or coatings with lead concentrations equal to or greater than 1.0 mg/cm² when measured by XRF. The following components were identified as LBP during this inspection:

BUILDING A

DESCRIPTION: **Wall paint**
 LOCATION: **Bathroom room 122, 124**
 COLOR: **Beige top layer**
 XRF NUMBER: **Page #1, XRF #15-17, 25-28**
 CONDITION: **Intact – Not intact**

DESCRIPTION: **Wall paint**
 LOCATION: **Corridor floor 1**
 COLOR: **Blue & beige top layer**
 XRF NUMBER: **Page #2, XRF #39-40, 43-45, 50-51**
 CONDITION: **Intact**

DESCRIPTION: **Wall paint**
 LOCATION: **Floor 1 stairwell**
 COLOR: **Beige top layer**
 XRF NUMBER: **Page #3, XRF #86**
 CONDITION: **Intact**

DESCRIPTION: **Wood trim paint**
 LOCATION: **Class room 203**
 COLOR: **Blue top layer**
 XRF NUMBER: **Page #4, XRF# 110**
 CONDITION: **Not intact**

DESCRIPTION: **Wall paint**
 LOCATION: **Class room 203**
 COLOR: **Beige top layer**
 XRF NUMBER: **Page #4, XRF# 113-114**
 CONDITION: **Intact**

DESCRIPTION: **Ceramic floor tile**
 LOCATION: **Bathroom 212**
 COLOR: **White**
 XRF NUMBER: **Page #5, XRF #146**
 CONDITION: **Not intact**

BUILDING A

DESCRIPTION: Wall paint
LOCATION: Corridor out class room 120
COLOR: Beige top layer
XRF NUMBER: Page #5, XRF# 156
CONDITION: Not intact

DESCRIPTION: Wall paint
LOCATION: Corridor out class room 120
COLOR: Beige top layer
XRF NUMBER: Page #5, XRF# 156
CONDITION: Not intact

DESCRIPTION: Exterior wood door & door casing paint
LOCATION: Building A exterior
COLOR: Green/blue top layer
XRF NUMBER: Page #16, XRF# 522-526, 530-531
CONDITION: Not intact

DESCRIPTION: Exterior metal stair-well paint
LOCATION: Building A exterior
COLOR: Beige top layer
XRF NUMBER: Page #16 & 17, XRF# 532, 552
CONDITION: Not intact

DESCRIPTION: Exterior beam paint
LOCATION: Building A front of the school
COLOR: White top layer
XRF NUMBER: Page #17, XRF# 548
CONDITION: Not intact

DESCRIPTION: Tiger statue
LOCATION: Building A front of the school
COLOR: Orange top layer
XRF NUMBER: Page #17, XRF# 550
CONDITION: Not intact

AUDITORIUM

DESCRIPTION: Wall paint
LOCATION: Auditorium 117
COLOR: Beige top layer
XRF NUMBER: Page #5 & 6, XRF# 162, 164-165, 174
CONDITION: Intact- Not intact

DESCRIPTION: Door paint
 LOCATION: Auditorium 117
 COLOR: Pink top layer
 XRF NUMBER: Page #6, XRF# 182-183
 CONDITION: Intact- Not intact

DESCRIPTION: Door and door casing paint
 LOCATION: Exterior doors of the Auditorium
 COLOR: Green top layer
 XRF NUMBER: Page #15, XRF# 504-505
 CONDITION: Not intact

DESCRIPTION: Exterior wall paint
 LOCATION: Exterior wood shed attached to the Auditorium
 COLOR: Green top layer
 XRF NUMBER: Page #15, XRF# 512
 CONDITION: Poor condition

DESCRIPTION: Exterior wall paint
 LOCATION: Exterior of Auditorium
 COLOR: Beige top layer
 XRF NUMBER: Page #15, XRF# 510
 CONDITION: Not intact

BUILDING B

DESCRIPTION: Door paint
 LOCATION: Corridor floor 1
 COLOR: Blue top layer
 XRF NUMBER: Page #6, XRF# 195
 CONDITION: Intact- Not intact

DESCRIPTION: Wall paint
 LOCATION: Corridor floor 1 & 2
 COLOR: Blue top layer
 XRF NUMBER: Page #7, XRF# 205, 226
 CONDITION: Intact- Not intact

DESCRIPTION: Door paint
 LOCATION: Corridor floor 1
 COLOR: Blue top layer
 XRF NUMBER: Page #7, XRF# 219-220
 CONDITION: Intact- Not intact

DESCRIPTION: Wall paint
 LOCATION: Corridor floor 2
 COLOR: Beige top layer
 XRF NUMBER: Page #7, XRF# 227-228, 234
 CONDITION: Intact- Not intact

AUDITORIUM

DESCRIPTION: Wall paint
LOCATION: Corridor floor 2
COLOR: Blue top layer
XRF NUMBER: Page #8, XRF# 241
CONDITION: Not intact

DESCRIPTION: Wall paint
LOCATION: Class room 207
COLOR: White top layer
XRF NUMBER: Page #8, XRF# 244
CONDITION: Not intact

DESCRIPTION: Trim paint
LOCATION: Class room 215
COLOR: White top layer
XRF NUMBER: Page #8, XRF# 256-257
CONDITION: Not intact

DESCRIPTION: Ceramic baseboard
LOCATION: Bathroom 216
COLOR: White top layer
XRF NUMBER: Page #8 & 9, XRF# 272-273
CONDITION: Not intact

DESCRIPTION: Wall paint
LOCATION: Class room 206
COLOR: White top layer
XRF NUMBER: Page #9, XRF# 287-288
CONDITION: Intact-Not intact

DESCRIPTION: Wall paint
LOCATION: Boys bathroom floor 1
COLOR: Beige top layer
XRF NUMBER: Page #11, XRF# 357
CONDITION: Not intact

DESCRIPTION: Ceramic baseboard
LOCATION: Boys bathroom floor 1
COLOR: Beige top layer
XRF NUMBER: Page #11, XRF# 360
CONDITION: Not intact

DESCRIPTION: Wall paint
LOCATION: Class room 109B
COLOR: Beige top layer
XRF NUMBER: Page #11, XRF# 368-370
CONDITION: Not intact

AUDITORIUM

DESCRIPTION: Exterior wall paint
LOCATION: Exterior of building B
COLOR: Beige top layer
XRF NUMBER: Page #15, XRF# 492-493, 495
CONDITION: Not intact

BUILDING C

DESCRIPTION: Sink
LOCATION: Boys bathroom floor 1
COLOR: White top layer
XRF NUMBER: Page #12, XRF# 392-393
CONDITION: Not intact

DESCRIPTION: Exterior metal stair-well paint
LOCATION: Building A
COLOR: Green/blue top layer
XRF NUMBER: Page #17, XRF# 553
CONDITION: Not intact

Testing combinations and XRF results are presented in Appendix B pages 1-17.

SECTION 5.0

RECOMMENDATIONS

5.1 RECOMMENDATIONS FOR LEAD-BASED PAINT

If the structures are to be *renovated*:

Any LBP that has become damaged should be abated. Any abatement procedure in which LBP is disturbed should be conducted by trained personnel and in accordance with all federal, state and local regulations, including OSHA's lead regulation 29 CFR 1926.62. Also, prior to disposal, the entire waste stream from LBP abatement (paint, rags, protective suits, debris, etc.) must be characterized by a Toxic Characteristic Leachate Procedure (TCLP) test. The EPA requires TCLP testing to determine if the waste is considered hazardous.

To comply with OSHA lead regulation 29 CFR 1926.62, the laboratory analysis (Flame AAS, Method SW 846, 7420) results should be made available to any personnel that will conduct painting operations of these structures. This regulation considers paint that contains any amount of lead to be lead-based paint and mandates protective measures any time a painting or renovation project involves the disturbance of LBP components in such a way as to cause airborne emissions of lead particulate (sanding, scraping, grinding, etc.). These protective measures include: personnel protection (respirators, protective suits, etc.), engineering controls and personnel air monitoring until results of the personnel monitoring indicate airborne lead concentrations below the Permissible Exposure Limit (PEL) of fifty (50) micrograms per cubic meter as an eight-hour time-weighted average (TWA). In lieu of the above protective measures, painting personnel may provide objective historical data from previous similar projects to demonstrate that the PEL for lead will not be exceeded.

If any of the structures are to be *demolished*:

Prior to demolition, a waste stream characterization should be performed on the structure. This waste stream must be characterized by a Toxic Characteristic Leachate Procedure (TCLP) test. The EPA requires TCLP testing to determine if the waste is considered either hazardous (and must be disposed of in a special disposal site) or is nonhazardous, and may be disposed of in a standard landfill. For some materials such as steel and mostly metal components, recycling at a certified recycling facility is another alternative to including these components as a representative fraction of the waste stream characterization. Finally, baseline representative soil samples should be collected from each address/lot on the properties to establish a background "Lead-in Soil" concentration for future post-demolition comparison.

During demolition and disposal operations:

To comply with OSHA lead regulation 29 CFR 1926.62, the paint chip laboratory analysis (Flame AAS, Method SW 846, 7420) results should be made available to any personnel that will conduct demolition operations of this structure. This regulation considers paint that contains any amount of lead to be lead-based paint and mandates protective measures any time a demolition project involves the disturbance of LBP components in such a way as to cause airborne emissions of lead particulate (torching, disc sanding, etc.). These protective measures include:

personnel protection (respirators, protective suits, etc.), engineering controls and personnel air monitoring until results of the personnel monitoring indicate airborne lead concentrations below the Permissible Exposure Limit (PEL) of fifty (50) micrograms per cubic meter as an eight-hour time-weighted average (TWA). In lieu of the above protective measures, demolition personnel may provide objective historical data from previous similar projects to demonstrate that the PEL for lead will not be exceeded.

After demolition, razing, and disposal operations:

At completion of demolition/razing/disposal of the structure down to grade, final representative soil samples should be collected from each address/lot to determine a final background "Lead - in Soil" concentration that should be below EPA/HUD and/or Florida DEP guidelines for Affordable Housing. If levels exceed EPA/HUD and/or Florida DEP guidelines, some soil remediation may be required to eliminate contaminated soil. Additional round(s) of confirmatory testing will then be required to clear this area.

If the structures are to remain "as is" and occupied:

An initial risk assessment should be conducted of the LBP. The risk assessment entails the collection of dust samples from areas adjacent to the LBP components. The dust sample is sent to a laboratory for analysis of lead-content. The dust's lead content provides an indication of the potential exposure to persons that come in contact with dust associated with the LBP components. The collection of dust samples for risk assessment purposes should be performed pursuant to Part III, Section III of the EPA/HUD Lead-Based Paint Risk Assessment Protocol. This protocol was established to evaluate the risk in community buildings where lead-based paint is present.

The owner should adopt an in-place management program for all LBP that is not removed from the structures. Periodic surveillance should be included in the in-place management program. As part of the in-place management program, The owner may also elect to conduct periodic risk assessments (dust sampling) of the remaining LBP. Periodic surveillance should be conducted at least every six months noting any change in the condition of the LBP.

5.2 RECOMMENDATIONS FOR OTHER PAINTS AND COATINGS

OSHA does not recognize the absence of lead through XRF; therefore, these materials must be considered to be lead-containing and a potential source of exposure unless determined to be nonlead-containing through laboratory analysis (i.e. Flame AAS, Method SW 846, 7420).

Any activity that would release lead dust or fumes must be performed by workers in accordance with the OSHA standard for removal of lead containing paint. If these materials can remain intact during renovation or demolition, then no other special handling is required.

5.3 OSHA COMPLIANCE

To comply with OSHA lead regulation 29 CFR 1926.62, this report should be made available to personnel that will conduct painting operations at this facility. This regulation considers coatings that contain measurable amounts of lead to be lead-based paint and mandates protective measures when a painting or demolition project involves the disturbance of painted components

in such a way as to cause airborne emissions of lead particulate (sanding, scraping, grinding, etc.). These protective measures include: hazard communication training, personnel protection (respirators, protective suits, etc.), engineering controls and personnel air monitoring until results of the personnel monitoring indicate airborne lead concentrations below the Action Level (AL) of 30 micrograms per cubic meter as an eight-hour time-weighted average (TWA). In lieu of the above protective measures, painting and or demolition personnel may provide objective historical data from previous similar projects to demonstrate that the AL for lead will not be exceeded.

5.4 DISCLOSURE OF LBP HAZARDS

The Residential Lead-Based Paint Hazard Reduction Act of 1992, also known as Title X, Section 1018 requires the disclosure to the purchaser or lessee of any known information on lead-based paint or lead-based paint hazards and provide to the purchaser or lessee any lead hazard evaluation reports available prior to the sale or lease of most housing built prior to 1978.

SECTION 6.0
SIGNATURE PAGE

Submitted by



Hiram Aguiar
Senior Staff Professional, EE&G
EPA Lead-Based Paint Risk Assessor

Reviewed by



Daniel J. Cottrell, Ph.D., P.G.
Senior Technical Advisor, EE&G
EPA Lead-Based Paint Risk Assessor

APPENDIX A
RENOVATE RIGHT
EPA PAMPHLET

Renovate Right

Important Lead Hazard
Information for Families,
Child Care Providers
and Schools



It's the Law!

Federal law requires that individuals receive certain information before renovating more than two square feet of painted surfaces in housing, child care facilities and schools built before 1978.

- Homeowners and tenants: renovators must give you this pamphlet before starting work.
- Child care facilities, including preschools and kindergarten classrooms, and the families of children under the age of six that attend those facilities: renovators must provide a copy of this pamphlet to child-care facilities and general renovation information to families whose children attend those facilities.

Also, beginning April 2010, federal law will require contractors that disturb lead-based paint in homes, child care facilities and schools, built before 1978 to be certified and follow specific work practices to prevent lead contamination. Therefore beginning in April 2010, ask to see your contractor's certification.

Renovating, Repairing, or Painting?



- Is your home, your building, or the child care facility or school your children attend, being renovated, repaired, or painted?
- Was your home, your building, or the child care facility or school your children under age 6 attend, built before 1978?

If the answer to these questions is YES, there are a few important things you need to know about lead-based paint.

This pamphlet provides basic facts about lead and information about lead safety when work is being done in your home, your building or the childcare facility or school your children attend.

The Facts About Lead

- Lead can affect children's brains and developing nervous systems, causing reduced IQ, learning disabilities, and behavioral problems. Lead is also harmful to adults.
- Lead in dust is the most common way people are exposed to lead. People can also get lead in their bodies from lead in soil or paint chips. Lead dust is often invisible.
- Lead-based paint was used in more than 38 million homes until it was banned for residential use in 1978.
- Projects that disturb lead-based paint can create dust and endanger you and your family. Don't let this happen to you. Follow the practices described in this pamphlet to protect you and your family.

Who Should Read This Pamphlet?

This pamphlet is for you if you:

- Reside in a home built before 1978,
- Own or operate a child care facility, including preschools and kindergarten classrooms, built before 1978, or
- Have a child under six who attends a child care facility built before 1978.

You will learn:

- Basic facts about lead and your health,
- How to choose a contractor, if you are a property owner,
- What tenants, and parents/guardians of a child in a child care facility or school should consider,
- How to prepare for the renovation or repair job,
- What to look for during the job and after the job is done,
- Where to get more information about lead.

This pamphlet is not for:

- **Abatement projects.** Abatement is a set of activities aimed specifically at eliminating lead or lead hazards. EPA has regulations for certification and training of abatement professionals. If your goal is to eliminate lead or lead hazards, contact the National Lead Information Center at **1-800-424-LEAD (5323)** for more information.
- **“Do-it-yourself” projects.** If you plan to do renovation work yourself, this document is a good start, but you will need more information to complete the work safely. Call the National Lead Information Center at **1-800-424-LEAD (5323)** and ask for more information on how to work safely in a home with lead-based paint.
- **Contractor education.** Contractors who want information about working safely with lead should contact the National Lead Information Center at **1-800-424-LEAD (5323)** for information about courses and resources on lead-safe work practices.



Lead and Your Health

Lead is especially dangerous to children under six years of age.

Lead can affect children's brains and developing nervous systems, causing:

- Reduced IQ and learning disabilities.
- Behavior problems.

Even children who appear healthy can have dangerous levels of lead in their bodies.

Lead is also harmful to adults. In adults, low levels of lead can pose many dangers, including:

- High blood pressure and hypertension.
- Pregnant women exposed to lead can transfer lead to their fetus.

Lead gets into the body when it is swallowed or inhaled.

- People, especially children, can swallow lead dust as they eat, play, and do other normal hand-to-mouth activities.
- People may also breathe in lead dust or fumes if they disturb lead-based paint. People who sand, scrape, burn, brush or blast or otherwise disturb lead-based paint risk unsafe exposure to lead.

What should I do if I am concerned about my family's exposure to lead?

- Call your local health department for advice on reducing and eliminating exposures to lead inside and outside your home, child care facility or school.
- Always use lead-safe work practices when renovation or repair will disturb lead-based paint.
- A blood test is the only way to find out if you or a family member already has lead poisoning. Call your doctor or local health department to arrange for a blood test.

For more information about the health effects of exposure to lead, visit the EPA lead website at www.epa.gov/lead/pubs/leadinfo.htm or call 1-800-424-LEAD (5323).



There are other things you can do to protect your family everyday.

- Regularly clean floors, window sills, and other surfaces.
- Wash children's hands, bottles, pacifiers, and toys often.
- Make sure children eat a healthy, nutritious diet consistent with the USDA's dietary guidelines, that helps protect children from the effects of lead.
- Wipe off shoes before entering house.

Where Does the Lead Come From?

Dust is the main problem. The most common way to get lead in the body is from dust. Lead dust comes from deteriorating lead-based paint and lead-contaminated soil that gets tracked into your home. This dust may accumulate to unsafe levels. Then, normal hand to-mouth activities, like playing and eating (especially in young children), move that dust from surfaces like floors and windowsills into the body.


Home renovation creates dust. Common renovation activities like sanding, cutting, and demolition can create hazardous lead dust and chips.

Proper work practices protect you from the dust. The key to protecting yourself and your family during a renovation, repair or painting job is to use lead-safe work practices such as containing dust inside the work area, using dust-minimizing work methods, and conducting a careful cleanup, as described in this pamphlet.

Other sources of lead. Remember, lead can also come from outside soil, your water, or household items (such as lead-glazed pottery and lead crystal). Contact the National Lead Information Center at **1-800-424-LEAD (5323)** for more information on these sources.



Checking Your Home for Lead-Based Paint



Older homes, child care facilities, and schools are more likely to contain lead-based paint. Homes may be single-family homes or apartments. They may be private, government-assisted, or public housing. Schools are preschools and kindergarten classrooms. They may be urban, suburban, or rural.

You have the following options:

You may decide to assume your home, child care facility, or school contains lead. Especially in older homes and buildings, you may simply want to assume lead-based paint is present and follow the lead-safe work practices described in this brochure during the renovation, repair, or painting job.

You or your contractor may also test for lead using a lead test kit. Test kits must be EPA-approved and are available at hardware stores. They include detailed instructions for their use.

You can hire a certified professional to check for lead-based paint. These professionals are certified risk assessors or inspectors, and can determine if your home has lead or lead hazards.

- A certified inspector or risk assessor can conduct an inspection telling you whether your home, or a portion of your home, has lead-based paint and where it is located. This will tell you the areas in your home where lead-safe work practices are needed.
- A certified risk assessor can conduct a risk assessment telling you if your home currently has any lead hazards from lead in paint, dust, or soil. The risk assessor can also tell you what actions to take to address any hazards.
- For help finding a certified risk assessor or inspector, call the National Lead Information Center at **1-800-424-LEAD (5323)**.

For Property Owners

You have the ultimate responsibility for the safety of your family, tenants, or children in your care. This means properly preparing for the renovation and keeping persons out of the work area (see p. 8). It also means ensuring the contractor uses lead-safe work practices.

Beginning April 2010, federal law will require that contractors performing renovation, repair and painting projects that disturb lead-based paint in homes, child care facilities, and schools built before 1978 to be certified and follow specific work practices to prevent lead contamination.

Until contractors are required to be certified, make sure your contractor can explain clearly the details of the job and how the contractor will minimize lead hazards during the work.

- Ask if the contractor is trained to perform lead-safe work practices and to see a copy of their training certificate.
- Ask them what lead-safe methods they will use to set up and perform the job in your home, child care facility or school.
- Ask if the contractor is aware of the lead renovation rules. For example, contractors are required to provide you with a copy of this pamphlet before beginning work. A sample pre-renovation disclosure form is provided at the back of this pamphlet. Contractors may use this form to make documentation of compliance easier.
- Ask for references from at least three recent jobs involving homes built before 1978, and speak to each personally.

Always make sure the contract is clear about how the work will be set up, performed, and cleaned.

- Share the results of any previous lead tests with the contractor.
- Even before contractors are required to be certified you should specify in the contract that they follow the work practices described on pages 9 and 10 of this brochure.
- The contract should specify which parts of your home are part of the work area and specify which lead-safe work practices should be used in those areas. Remember, your contractor should confine dust and debris to the work area and should minimize spreading that dust to other areas of the home.
- The contract should also specify that the contractor clean the work area, verify that it was cleaned adequately, and re-clean it if necessary.

Once these practices are required, if you think a worker is failing to do what they are supposed to do or is doing something that is unsafe, you should:

- Direct the contractor to comply with the contract requirements,
- Call your local health or building department, or
- Call EPA's hotline **1-800-424-LEAD (5323)**.

For Tenants, and Families of Children Under Age Six in Child Care Facilities and Schools

You play an important role ensuring the ultimate safety of your family.

This means properly preparing for the renovation and staying out of the work area (see p. 8).

Beginning April 2010, federal law will require that contractors performing renovation, repair and painting projects that disturb lead-based paint in homes, child care facilities and schools built before 1978 that a child under age six visits regularly to be certified and follow specific work practices to prevent lead contamination.

The law will require anyone hired to renovate, repair, or do painting preparation work on a property built before 1978 to follow the steps described on pages 9 and 10 unless the area where the work will be done contains no lead-based paint.



Once these practices are required, if you think a worker is failing to do what they are supposed to do or is doing something that is unsafe, you should:

- Contact your landlord,
- Call your local health or building department, or
- Call EPA's hotline **1-800-424-LEAD (5323)**.

If you are concerned about lead hazards left behind after the job is over, you can check the work yourself (see page 10).



If your property receives housing assistance from HUD (or a state or local agency that uses HUD funds), you must follow the more stringent requirements of HUD's Lead-safe Housing Rule and the ones described in this pamphlet.

Preparing for a Renovation

The work areas should not be accessible to occupants while the work occurs. The rooms or areas where work is being done may be blocked off or sealed with plastic sheeting to contain any dust that is generated. The contained area will not be available to you until the work in that room or area is complete, cleaned thoroughly, and the containment has been removed. You will not have access to some areas and should plan accordingly.

You may need:

- Alternative bedroom, bathroom, and kitchen arrangements if work is occurring in those areas of your home.
- A safe place for pets because they, too, can be poisoned by lead and can track lead dust into other areas of the home.
- A separate pathway for the contractor from the work area to the outside, in order to bring materials in and out of the home. Ideally, it should not be through the same entrance that your family uses.
- A place to store your furniture. All furniture and belongings may have to be moved from the work area while the work is done. Items that can't be moved, such as cabinets, should be wrapped in heavy duty plastic.
- To turn off forced-air heating and air conditioning systems while work is done. This prevents dust from spreading through vents from the work area to the rest of your home. Consider how this may affect your living arrangements.

You may even want to move out of your home temporarily while all or parts of the work are being done.

Child care facilities and schools may want to consider alternative accommodations for children and access to necessary facilities.



During the Work

Beginning April 2010, federal law will require contractors that are hired to perform renovation, repair and painting projects in homes, child care facilities, and schools built before 1978 that disturb lead-based paint to be certified and follow specific work practices to prevent lead contamination.

Even before contractors are required to be certified and follow specific work practices, the contractor should follow these three simple procedures, described below:



1. Contain the work area. The area should be contained so that dust and debris do not escape from that area. Warning signs should be put up and heavy-duty plastic and tape should be used as appropriate to:

- Cover the floors and any furniture that cannot be moved.
- Seal off doors and heating and cooling system vents.

These will help prevent dust or debris from getting outside the work area.

2. Minimize dust. There is no way to eliminate dust, but some methods make less dust than others. For example, using water to mist areas before sanding or scraping; scoring paint before separating components; and prying and pulling apart components instead of breaking them are techniques that generate less dust than alternatives. Some methods generate large amounts of lead-contaminated dust and should not be used. They are:

- Open flame burning or torching.
- Sanding, grinding, planing, needle gunning, or blasting with power tools and equipment not equipped with a shroud and HEPA vacuum attachment.
- Using a heat gun at temperatures greater than 1100°F.

3. Clean up thoroughly. The work area should be cleaned up daily to keep it as clean as possible. When all the work is done, the area should be cleaned up using special cleaning methods before taking down any plastic that isolates the work area from the rest of the home. The special cleaning methods should include:

- Using a HEPA vacuum to clean up dust and debris on all surfaces, followed by
- Wet mopping with plenty of rinse water.

When the final cleaning is done, look around. There should be no dust, paint chips, or debris in the work area. If you see any dust, paint chips, or debris, the area should be re-cleaned.

For Property Owners: After the Work is Done

When all the work is finished, you will want to know if your home, child care facility, or school has been cleaned up properly. Here are some ways to check.

Even before contractors are required to be certified and follow specific work practices, you should:

Ask about your contractor's final cleanup check. Remember, lead dust is often invisible to the naked eye. It may still be present even if you cannot see it. The contractor should use disposable cleaning cloths to wipe the floor of the work area and compare them to a cleaning verification card to determine if the work area was adequately cleaned.

To order a cleaning verification card and detailed instructions visit the EPA lead website at www.epa.gov/lead or contact the National Lead Information Center at **1-800-424-LEAD (5323)** or visit their website at www.epa.gov/lead/nlic.htm.

You also may choose to have a lead-dust test. Lead-dust tests are wipe samples sent to a laboratory for analysis.

- You can specify in your contract that a lead-dust test will be done. In this case, make it clear who will do the testing.
- Testing should be done by a lead professional.

If you choose to do the testing, some EPA-recognized lead laboratories will send you a kit that allows you to collect samples and send them back to the lab for analysis.

Contact the National Lead Information Center at **1-800-424-LEAD (5323)** for lists of qualified professionals and EPA-recognized lead labs.

If your home, child care facility, or school fails the dust test, the area should be re-cleaned and tested again.

Where the project is done by contract, it is a good idea to specify in the contract that the contractor is responsible for re-cleaning if the home, child care facility, or school fails the test.



For Additional Information


You may need additional information on how to protect yourself and your children while a job is going on in your home, your building, or childcare facility.

■ The **National Lead Information Center** at **1-800-424-LEAD (5323)** or **www.epa.gov/lead/nlic.htm** can tell you how to contact your state, local, and/or tribal programs or get general information about lead poisoning prevention.

- State and tribal lead poisoning prevention or environmental protection programs can provide information about lead regulations and potential sources of financial aid for reducing lead hazards. If your State or local government has requirements more stringent than those described in this pamphlet, you must follow those requirements.
- Local building code officials can tell you the regulations that apply to the renovation work that you are planning.
- State, county, and local health departments can provide information about local programs, including assistance for lead-poisoned children and advice on ways to get your home checked for lead.

■ The **National Lead Information Center** can also provide a variety of resource materials, including the following guides to lead-safe work practices. Many of these materials are also available at **www.epa.gov/lead/pubs/brochure.htm**.

- Lead Paint Safety, a Field Guide for Painting, Home Maintenance, and Renovation Work
- Reducing Lead Hazards When Remodeling Your Home
- Protect Your Family from Lead in Your Home
- Lead in Your Home: A Parent's Reference Guide



For the hearing impaired, call the Federal Information Relay Service at 1-800-877-8339 to access any of the phone numbers in this brochure.

EPA Contacts

EPA Regional Offices

EPA addresses residential lead hazards through several different regulations. EPA requires training and certification for conducting abatement, education about hazards associated with renovations, disclosure about known lead paint and lead hazards in housing, and sets lead-paint hazard standards.

Your Regional EPA Office can provide further information regarding lead safety and lead protection programs at www.epa.gov/lead.

Region 1

(Connecticut, Massachusetts, Maine, New Hampshire, Rhode Island, Vermont)
Regional Lead Contact
U.S. EPA Region 1
Suite 1100
One Congress Street
Boston, MA 02114-2023
(888) 372-7341

Region 2

(New Jersey, New York, Puerto Rico, Virgin Islands)
Regional Lead Contact
U.S. EPA Region 2
2890 Woodbridge Avenue
Building 209, Mail Stop 225
Edison, NJ 08837-3679
(732) 321-6769

Region 3

(Delaware, Maryland, Pennsylvania, Virginia, Washington, DC, West Virginia)
Regional Lead Contact
U.S. EPA Region 3
1650 Arch Street
Philadelphia, PA 19103-2029
(215) 814-5000

Region 4

(Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee)
Regional Lead Contact
U.S. EPA Region 4
61 Forsyth Street, SW
Atlanta, GA 30303-8960
(404) 562-9900

Region 5

(Illinois, Indiana, Michigan, Minnesota, Ohio, Wisconsin)
Regional Lead Contact
U.S. EPA Region 5
77 West Jackson Boulevard
Chicago, IL 60604-3507
(312) 886-6003

Region 6

(Arkansas, Louisiana, New Mexico, Oklahoma, Texas)
Regional Lead Contact
U.S. EPA Region 6
1445 Ross Avenue,
12th Floor
Dallas, TX 75202-2733
(214) 665-6444

Region 7

(Iowa, Kansas, Missouri, Nebraska)
Regional Lead Contact
U.S. EPA Region 7
901 N. 5th Street
Kansas City, KS 66101
(913) 551-7003

Region 8

(Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming)
Regional Lead Contact
U.S. EPA Region 8
999 18th Street, Suite 300
Denver, CO 80202-2466
(303) 312-6312

Region 9

(Arizona, California, Hawaii, Nevada)
Regional Lead Contact
U.S. Region 9
75 Hawthorne Street
San Francisco, CA 94105
(415) 947-8021

Region 10

(Alaska, Idaho, Oregon, Washington)
Regional Lead Contact
U.S. EPA Region 10
1200 Sixth Avenue
Seattle, WA 98101-1128
(206) 553-1200

Other Federal Agencies

CPSC

The Consumer Product Safety Commission (CPSC) protects the public from the unreasonable risk of injury or death from 15,000 types of consumer products under the agency's jurisdiction. CPSC warns the public and private sectors to reduce exposure to lead and increase consumer awareness. Contact CPSC for further information regarding regulations and consumer product safety.

CPSC

4330 East West Highway
Bethesda, MD 20814
Hotline 1-(800) 638-2772
www.cpsc.gov

CDC Childhood Lead Poisoning Prevention Branch

The Centers for Disease Control and Prevention (CDC) assists state and local childhood lead poisoning prevention programs to provide a scientific basis for policy decisions, and to ensure that health issues are addressed in decisions about housing and the environment. Contact CDC Childhood Lead Poisoning Prevention Program for additional materials and links on the topic of lead.

CDC Childhood Lead Poisoning Prevention Branch

4770 Buford Highway, MS F-40
Atlanta, GA 30341
(770) 488-3300
www.cdc.gov/nceh/lead

HUD Office of Healthy Homes and Lead Hazard Control

The Department of Housing and Urban Development (HUD) provides funds to state and local governments to develop cost-effective ways to reduce lead-based paint hazards in America's privately-owned low-income housing. In addition, the office enforces the rule on disclosure of known lead paint and lead hazards in housing, and HUD's lead safety regulations in HUD-assisted housing, provides public outreach and technical assistance, and conducts technical studies to help protect children and their families from health and safety hazards in the home. Contact the HUD Office of Healthy Homes and Lead Hazard Control for information on lead regulations, outreach efforts, and lead hazard control research and outreach grant programs.

U.S. Department of Housing and Urban Development

Office of Healthy Homes
and Lead Hazard Control
451 Seventh Street, SW, Room 8236
Washington, DC 20410-3000
HUD's Lead Regulations Hotline
(202) 402-7698
www.hud.gov/offices/lead/



Current Sample Pre-Renovation Form

Effective until April 2010.

Confirmation of Receipt of Lead Pamphlet

- I have received a copy of the pamphlet, *Renovate Right: Important Lead Hazard Information for Families, Child Care Providers and Schools* informing me of the potential risk of the lead hazard exposure from renovation activity to be performed in my dwelling unit. I received this pamphlet before the work began.

Printed name of recipient

Date

Signature of recipient

Self-Certification Option (for tenant-occupied dwellings only) —

If the lead pamphlet was delivered but a tenant signature was not obtainable, you may check the appropriate box below.

- Refusal to sign** — I certify that I have made a good faith effort to deliver the pamphlet, *Renovate Right: Important Lead Hazard Information for Families, Child Care Providers and Schools*, to the rental dwelling unit listed below at the date and time indicated and that the occupant refused to sign the confirmation of receipt. I further certify that I have left a copy of the pamphlet at the unit with the occupant.
- Unavailable for signature** — I certify that I have made a good faith effort to deliver the pamphlet, *Renovate Right: Important Lead Hazard Information for Families, Child Care providers and Schools*, to the rental dwelling unit listed below and that the occupant was unavailable to sign the confirmation of receipt. I further certify that I have left a copy of the pamphlet at the unit by sliding it under the door.

Printed name of person certifying

Attempted delivery
date and time
lead pamphlet delivery

Signature of person certifying lead pamphlet delivery

Unit Address

Note Regarding Mailing Option — As an alternative to delivery in person, you may mail the lead pamphlet to the owner and/or tenant. Pamphlet must be mailed at least 7 days before renovation (Document with a certificate of mailing from the post office).



Future Sample Pre-Renovation Form

This sample form may be used by renovation firms to document compliance with the Federal pre-renovation education and renovation, repair, and painting regulations.

Occupant Confirmation

Pamphlet Receipt

- I have received a copy of the lead hazard information pamphlet informing me of the potential risk of the lead hazard exposure from renovation activity to be performed in my dwelling unit. I received this pamphlet before the work began.

Owner-occupant Opt-out Acknowledgment

- (A) I confirm that I own and live in this property, that no child under the age of 6 resides here, that no pregnant woman resides here, and that this property is not a child-occupied facility.

Note: A child resides in the primary residence of his or her custodial parents, legal guardians, foster parents, or informal caretaker if the child lives and sleeps most of the time at the caretaker's residence.

Note: A child-occupied facility is a pre-1978 building visited regularly by the same child, under 6 years of age, on at least two different days within any week, for at least 3 hours each day, provided that the visits total at least 60 hours annually.

If Box A is checked, check either Box B or Box C, but not both.

- (B) I request that the renovation firm use the lead-safe work practices required by EPA's Renovation, Repair, and Painting Rule; or
- (C) I understand that the firm performing the renovation will not be required to use the lead-safe work practices required by EPA's Renovation, Repair, and Painting Rule.

Printed Name of Owner-occupant

Signature of Owner-occupant

Signature Date

Renovator's Self Certification Option (for tenant-occupied dwellings only)

Instructions to Renovator: If the lead hazard information pamphlet was delivered but a tenant signature was not obtainable, you may check the appropriate box below.

- Declined** – I certify that I have made a good faith effort to deliver the lead hazard information pamphlet to the rental dwelling unit listed below at the date and time indicated and that the occupant declined to sign the confirmation of receipt. I further certify that I have left a copy of the pamphlet at the unit with the occupant.
- Unavailable for signature** – I certify that I have made a good faith effort to deliver the lead hazard information pamphlet to the rental dwelling unit listed below and that the occupant was unavailable to sign the confirmation of receipt. I further certify that I have left a copy of the pamphlet at the unit by sliding it under the door or by (fill in how pamphlet was left). _____

Printed Name of Person Certifying Delivery

Attempted Delivery Date

Signature of Person Certifying Lead Pamphlet Delivery

Unit Address

Note Regarding Mailing Option — As an alternative to delivery in person, you may mail the lead hazard information pamphlet to the owner and/or tenant. Pamphlet must be mailed at least seven days before renovation. Mailing must be documented by a certificate of mailing from the post office.

Note: This form is not effective until April 2010.



1-800-424-LEAD (5323)
www.epa.gov/lead

EPA-740-F-08-002
March 2008



APPENDIX B
XRF TESTING DATA
PAGES 1-17

GLYNN ARCHER ELEMENTARY SCHOOL - 1302 WHITE STREET, KEY WEST, FL

Reading	Nc	Type	COMPONENT	SUBSTRATE	SIDE	CONDITION	COLOR	ROOM TYPE	ROOM NUMBER	FLOOR	SITE/ADDRESS	BLDG	Results	PbC
1		PAINT	CAL	WOOD	CALIBRATE	INTACT	ORANGE	CR	100	FIRST	GLYNN ARCHER SCHL	A	Positive	1
2		PAINT	DOOR	WOOD	A S	INTACT	BLUE	CR	100	FIRST	GLYNN ARCHER SCHL	A	Negative	0.19
3		PAINT	DOOR C	WOOD	A S	Not Intact- FAIR	BLUE	CR	100	FIRST	GLYNN ARCHER SCHL	A	Negative	-0.56
4		PAINT	BASEBOARD	WOOD	B	Not Intact- FAIR	BLUE	CR	100	FIRST	GLYNN ARCHER SCHL	A	Negative	0.5
5		PAINT	WALL	PLASTER	C	Not Intact- FAIR	BEIGE	CR	100	FIRST	GLYNN ARCHER SCHL	A	Negative	0
6		PAINT	WALL	PLASTER	D	INTACT	BEIGE	CR	100	FIRST	GLYNN ARCHER SCHL	A	Negative	0.8
7		PAINT	TRIM	WOOD	B	Not Intact-POOR	BEIGE	CR	100	FIRST	GLYNN ARCHER SCHL	A	Negative	0.13
8		PAINT	WALL	CERAMIC TILE	C	INTACT	BEIGE	CR	100	FIRST	GLYNN ARCHER SCHL	A	Negative	0.04
9		PAINT	FLOOR	CERAMIC TILE	C	INTACT	WHITE	CR	100	FIRST	GLYNN ARCHER SCHL	A	Negative	0.02
10		PAINT	DOOR C	WOOD	B	INTACT	BEIGE	CR	100	FIRST	GLYNN ARCHER SCHL	A	Negative	0
11		PAINT	DOOR C	WOOD	A	INTACT	BLUE	BATHROOM	122	FIRST	GLYNN ARCHER SCHL	A	Negative	0.08
12		PAINT	DOOR C	WOOD	A	Not Intact-POOR	BLUE	BATHROOM	122	FIRST	GLYNN ARCHER SCHL	A	Negative	0.24
13		PAINT	DOOR	WOOD	A	INTACT	BLUE	BATHROOM	122	FIRST	GLYNN ARCHER SCHL	A	Negative	0.01
14		PAINT	WALL	PLASTER	A	Not Intact- FAIR	BEIGE	BATHROOM	122	FIRST	GLYNN ARCHER SCHL	A	Negative	0.14
15		PAINT	WALL	PLASTER	D	Not Intact-POOR	BEIGE	BATHROOM	122	FIRST	GLYNN ARCHER SCHL	A	Positive	1.7
16		PAINT	WALL	PLASTER	D	Not Intact-POOR	BEIGE	BATHROOM	122	FIRST	GLYNN ARCHER SCHL	A	Positive	1.5
17		PAINT	WALL	PLASTER	B	INTACT	BEIGE	BATHROOM	122	FIRST	GLYNN ARCHER SCHL	A	Positive	1
18		PAINT	WALL	PLASTER	B	INTACT	BEIGE	BATHROOM	122	FIRST	GLYNN ARCHER SCHL	A	Negative	0.7
19		PAINT	WALL	CERAMIC TILE	A	INTACT	BEIGE	BATHROOM	122	FIRST	GLYNN ARCHER SCHL	A	Negative	0.02
20		PAINT	FLOOR	CERAMIC TILE	A	INTACT	GREEN	BATHROOM	122	FIRST	GLYNN ARCHER SCHL	A	Negative	0.01
21		PAINT	TRIM	WOOD	A	Not Intact-POOR	BEIGE	BATHROOM	122	FIRST	GLYNN ARCHER SCHL	A	Negative	0.01
22		PAINT	DOOR	WOOD	A	INTACT	BLUE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0.01
23		PAINT	DOOR C	WOOD	A	Not Intact-POOR	BLUE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0.01
24		PAINT	DOOR C	WOOD	A	INTACT	BEIGE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0
25		PAINT	WALL	PLASTER	D	INTACT	BEIGE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Positive	1.8
26		PAINT	WALL	PLASTER	D	INTACT	BEIGE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Positive	1.4
27		PAINT	WALL	PLASTER	C	INTACT	BEIGE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Positive	1.3
28		PAINT	WALL	PLASTER	C	INTACT	BEIGE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Positive	1.4
29		PAINT	WALL	CERAMIC TILE	A	INTACT	BEIGE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0.01
30		PAINT	FLOOR	CERAMIC TILE	A	INTACT	BEIGE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0.5
31		PAINT	SINK	METAL	D	INTACT	WHITE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0.06
32		PAINT	TOILET	CERAMIC TILE	D	INTACT	WHITE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0.02
33		PAINT	DOOF	WOOD	D	Not Intact-POOR	BLUE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0.26
34		PAINT	DOOR	WOOD	D	Not Intact-POOR	BEIGE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0.18

A = SOUTH

B = WEST

C = NORTH

D = EAST

GLYNN ARCHER ELEMENTARY SCHOOL - 1302 WHITE STREET, KEY WEST, FL

Reading	Nc	Type	COMPONENT	SUBSTRATE	SIDE	CONDITION	COLOR	ROOM TYPE	ROOM NUMBER	FLOOR	SITE/ADDRESS	BLDG	Results	PbC
35		PAINT	DOOR C	WOOD	D	Not Intact-POOR	BEIGE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0.15
36		PAINT	DOOR C	WOOD	D	Not Intact- FAIR	BLUE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0.4
37		PAINT	WALL	PLASTER	D	Not Intact-POOR	BLUE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0.5
38		PAINT	WALL	PLASTER	D	Not Intact-POOR	BLUE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0.09
39		PAINT	WALL	PLASTER	C	INTACT	BLUE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Positive	1.2
40		PAINT	WALL	PLASTER	C	INTACT	BLUE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Positive	1.1
41		PAINT	WALL	PLASTER	D	INTACT	BLUE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0
42		PAINT	BASEBOARD	WOOD	D	INTACT	BEIGE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0.15
43		PAINT	WALL	PLASTER	A	INTACT	BEIGE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Positive	3
44		PAINT	WALL	PLASTER	A	INTACT	BEIGE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Positive	2.9
45		PAINT	WALL	PLASTER	C	INTACT	BEIGE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Positive	3
46		PAINT	TRIM	WOOD	C	INTACT	BLUE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0.01
47		PAINT	WALL	PLASTER	C	INTACT	BLUE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	-0.18
48		PAINT	WALL	PLASTER	C	INTACT	BLUE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0.12
49		PAINT	WALL	PLASTER	A	INTACT	BLUE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0.07
50		PAINT	WALL	PLASTER	D	INTACT	BLUE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Positive	1.1
51		PAINT	WALL	CONCRETE	D	INTACT	BLUE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Positive	1.5
52		PAINT	WALL	CONCRETE	D	INTACT	BEIGE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0.2
53		PAINT	WALL	CONCRETE	D	INTACT	BEIGE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0.24
54		PAINT	WALL	CONCRETE	D	INTACT	BEIGE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0.8
55		PAINT	BASEBOARD	WOOD	D	INTACT	BLUE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0.3
56		PAINT	DOOR	WOOD	D	Not Intact- FAIR	BLUE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0
57		PAINT	DOOR C	WOOD	D	INTACT	BLUE	BATHROOM	124	FIRST	GLYNN ARCHER SCHL	A	Negative	0.06
58		PAINT	DOOR C	WOOD	D	Not Intact- FAIR	BLUE	CLEAN U	120	FIRST	GLYNN ARCHER SCHL	A	Negative	0.02
59		PAINT	DOOR	WOOD	D	Not Intact-POOR	BEIGE	CLEAN U	120	FIRST	GLYNN ARCHER SCHL	A	Negative	0.13
60		PAINT	BKCSE SHELF	WOOD	D	Not Intact-POOR	BEIGE	CLEAN U	120	FIRST	GLYNN ARCHER SCHL	A	Negative	0.01
61		PAINT	WALL	PLASTER	C	Not Intact- FAIR	BEIGE	CLEAN U	120	FIRST	GLYNN ARCHER SCHL	A	Negative	0
62		PAINT	WALL	WOOD	A	INTACT	BLUE	OFFICE	119	FIRST	GLYNN ARCHER SCHL	A	Negative	0
63		PAINT	WALL	WOOD	B	INTACT	BLUE	OFFICE	119	FIRST	GLYNN ARCHER SCHL	A	Negative	0
64		PAINT	WALL	WOOD	C	INTACT	BLUE	OFFICE	119	FIRST	GLYNN ARCHER SCHL	A	Negative	0.01
65		PAINT	BASEBOARD	WOOD	C	Not Intact- FAIR	BLUE	OFFICE	119	FIRST	GLYNN ARCHER SCHL	A	Negative	0
66		PAINT	DOOR	WOOD	B	INTACT	BLUE	OFFICE	119	FIRST	GLYNN ARCHER SCHL	A	Negative	0.1
67		PAINT	DOOR C	WOOD	B	INTACT	WHITE	OFFICE	119	FIRST	GLYNN ARCHER SCHL	A	Negative	0.01
68		PAINT	DOOR J	WOOD	B	INTACT	WHITE	OFFICE	119	FIRST	GLYNN ARCHER SCHL	A	Negative	0.05

A = SOUTH

B = WEST

C = NORTH

D = EAST

GLYNN ARCHER ELEMENTARY SCHOOL - 1302 WHITE STREET, KEY WEST, FL

Reading	Nc	Type	COMPONENT	SUBSTRATE	SIDE	CONDITION	COLOR	ROOM TYPE	ROOM NUMBER	FLOOR	SITE/ADDRESS	BLDG	Results	PbC
69		PAINT	WALL	WOOD	C	INTACT	BEIGE	OFFICE	119	FIRST	GLYNN ARCHER SCHL	A	Negative	0
70		PAINT	WALL	CONCRETE	C	INTACT	BEIGE	OFFICE	119G	FIRST	GLYNN ARCHER SCHL	A	Negative	0.6
71		PAINT	BASEBOARD	WOOD	D	Not Intact-POOR	BEIGE	OFFICE	119G	FIRST	GLYNN ARCHER SCHL	A	Negative	0.4
72		PAINT	W SILL	WOOD	D	INTACT	WHITE	OFFICE	119F	FIRST	GLYNN ARCHER SCHL	A	Negative	0
73		PAINT	W SILL	WOOD	C	INTACT	BLUE	OFFICE	119F	FIRST	GLYNN ARCHER SCHL	A	Negative	0
74		PAINT	DOOR	WOOD	C	Not Intact-POOR	BLUE	CR	102	FIRST	GLYNN ARCHER SCHL	A	Negative	0.19
75		PAINT	DOOR C	WOOD	C	Not Intact-POOR	BLUE	CR	102	FIRST	GLYNN ARCHER SCHL	A	Negative	-0.02
76		PAINT	DOOR C	WOOD	C	INTACT	WHITE	CR	102	FIRST	GLYNN ARCHER SCHL	A	Negative	0.26
77		PAINT	WALL	PLASTER	C	INTACT	WHITE	CR	102	FIRST	GLYNN ARCHER SCHL	A	Negative	0.8
78		PAINT	WALL	PLASTER	A	INTACT	WHITE	CR	102	FIRST	GLYNN ARCHER SCHL	A	Negative	0.6
79		PAINT	WALL	CONCRETE	D	INTACT	WHITE	CR	102	FIRST	GLYNN ARCHER SCHL	A	Negative	0.4
80		PAINT	WALL	CONCRETE	B	INTACT	WHITE	CR	102	FIRST	GLYNN ARCHER SCHL	A	Negative	0.22
81		PAINT	BASEBOARD	WOOD	B	INTACT	BLACK	CR	102	FIRST	GLYNN ARCHER SCHL	A	Negative	0.4
82		PAINT	STR NEWAL P	WOOD	C	Not Intact- FAIR	BLUE	STAIRS	STAIRS	FIRST	GLYNN ARCHER SCHL	A	Negative	0.06
83		PAINT	STR HAND RAI	WOOD	C	Not Intact- FAIR	BLUE	STAIRS	STAIRS	FIRST	GLYNN ARCHER SCHL	A	Negative	-0.12
84		PAINT	STR HAND RAI	WOOD	B	INTACT	BLUE	STAIRS	STAIRS	FIRST	GLYNN ARCHER SCHL	A	Negative	0.17
85		PAINT	WALL	PLASTER	B	INTACT	BLUE	STAIRS	STAIRS	FIRST	GLYNN ARCHER SCHL	A	Negative	0.11
86		PAINT	WALL	PLASTER	B	INTACT	BEIGE	STAIRS	STAIRS	FIRST	GLYNN ARCHER SCHL	A	Positive	3
87		PAINT	TRIM	WOOD	B	INTACT	BLUE	STAIRS	STAIRS	FIRST	GLYNN ARCHER SCHL	A	Negative	0.01
88		PAINT	DOOR	WOOD	D	Not Intact- FAIR	BLUE	CR	205	SECOND	GLYNN ARCHER SCHL	A	Negative	0.14
89		PAINT	DOOR C	WOOD	D	Not Intact-POOR	BLUE	CR	205	SECOND	GLYNN ARCHER SCHL	A	Negative	0.22
90		PAINT	DOOR C	WOOD	D	Not Intact-POOR	RED	CR	205	SECOND	GLYNN ARCHER SCHL	A	Negative	0.14
91		PAINT	BASEBOARD	WOOD	D	Not Intact- FAIR	RED	CR	205	SECOND	GLYNN ARCHER SCHL	A	Negative	0.5
92		PAINT	TRIM	WOOD	D	Not Intact- FAIR	RED	CR	205	SECOND	GLYNN ARCHER SCHL	A	Negative	0
93		PAINT	WAL	PLASTER	A	INTACT	BLUE	CR	205	SECOND	GLYNN ARCHER SCHL	A	Negative	0
94		PAINT	WAL	PLASTER	B	INTACT	BLUE	CR	205	SECOND	GLYNN ARCHER SCHL	A	Negative	0
95		PAINT	WAL	PLASTER	C	INTACT	BEIGE	CORR	CORR	SECOND	GLYNN ARCHER SCHL	A	Negative	0.1
96		PAINT	WAL	PLASTER	C	INTACT	BEIGE	CORR	CORR	SECOND	GLYNN ARCHER SCHL	A	Negative	0.8
97		PAINT	WAL	PLASTER	C	INTACT	BEIGE	CORR	CORR	SECOND	GLYNN ARCHER SCHL	A	Negative	0.16
98		PAINT	WAL	PLASTER	C	INTACT	BEIGE	CORR	CORR	SECOND	GLYNN ARCHER SCHL	A	Negative	0.26
99		PAINT	WAL	PLASTER	C	Not Intact- FAIR	BLUE	CORR	CORR	SECOND	GLYNN ARCHER SCHL	A	Negative	0.01
100		PAINT	WAL	PLASTER	C	INTACT	BLUE	CORR	CORR	SECOND	GLYNN ARCHER SCHL	A	Negative	0.01
101		PAINT	WAL	PLASTER	B	INTACT	BLUE	CORR	CORR	SECOND	GLYNN ARCHER SCHL	A	Negative	0.19
102		PAINT	WAL	PLASTER	A	INTACT	BLUE	CORR	CORR	SECOND	GLYNN ARCHER SCHL	A	Negative	0.1

A = SOUTH

B = WEST

C = NORTH

D = EAST

GLYNN ARCHER ELEMENTARY SCHOOL - 1302 WHITE STREET, KEY WEST, FL

Reading	Nc	Type	COMPONENT	SUBSTRATE	SIDE	CONDITION	COLOR	ROOM TYPE	ROOM NUMBER	FLOOR	SITE/ADDRESS	BLDG	Results	PbC
103		PAINT	WAL	PLASTER	A	INTACT	BLUE	CORR	CORR	SECOND	GLYNN ARCHER SCHL	A	Negative	0
104		PAINT	WALL	PLASTER	A	INTACT	BEIGE	CORR	CORR	SECOND	GLYNN ARCHER SCHL	A	Negative	0.4
105		PAINT	WALL	PLASTER	A	INTACT	BEIGE	CORR	CORR	SECOND	GLYNN ARCHER SCHL	A	Negative	0.9
106		PAINT	WALL	PLASTER	A	INTACT	BEIGE	CORR	CORR	SECOND	GLYNN ARCHER SCHL	A	Negative	0.26
107		PAINT	DOOR	WOOD	C	Not Intact- FAIR	BLUE	CR	203	SECOND	GLYNN ARCHER SCHL	A	Negative	0.16
108		PAINT	DOOR C	WOOD	C	INTACT	BLUE	CR	203	SECOND	GLYNN ARCHER SCHL	A	Negative	0.08
109		PAINT	BASEBOARD	WOOD	C	Not Intact-POOR	BLACK	CR	203	SECOND	GLYNN ARCHER SCHL	A	Negative	0.27
110		PAINT	TRIM	WOOD	A	Not Intact- FAIR	BLUE	CR	203	SECOND	GLYNN ARCHER SCHL	A	Positive	2.1
111		PAINT	WALL	WOOD	A	INTACT	BEIGE	CR	203	SECOND	GLYNN ARCHER SCHL	A	Negative	0.18
112		PAINT	WALL	WOOD	B	Not Intact-POOR	BEIGE	CR	203	SECOND	GLYNN ARCHER SCHL	A	Negative	0
113		PAINT	WALL	PLASTER	B	INTACT	BEIGE	CR	203	SECOND	GLYNN ARCHER SCHL	A	Positive	1.8
114		PAINT	WALL	PLASTER	C	INTACT	BEIGE	CR	203	SECOND	GLYNN ARCHER SCHL	A	Positive	1.7
115		PAINT	WALL	PLASTER	C	INTACT	BEIGE	CR	202	SECOND	GLYNN ARCHER SCHL	A	Negative	0.16
116		PAINT	WALL	PLASTER	B	INTACT	BEIGE	CR	202	SECOND	GLYNN ARCHER SCHL	A	Negative	0.17
117		PAINT	WALL	PLASTER	A	Not Intact- FAIR	BEIGE	CR	202	SECOND	GLYNN ARCHER SCHL	A	Negative	0.12
118		PAINT	BASEBOARD	WOOD	A	INTACT	BEIGE	CR	202	SECOND	GLYNN ARCHER SCHL	A	Negative	0.17
119		PAINT	WALL	DRYWALL	D	INTACT	BEIGE	CR	202	SECOND	GLYNN ARCHER SCHL	A	Negative	0
120		PAINT	DOOR	WOOD	C	Not Intact- FAIR	BLUE	CR	202	SECOND	GLYNN ARCHER SCHL	A	Negative	0.15
121		PAINT	DOOR C	WOOD	C	Not Intact- FAIR	BLUE	CR	202	SECOND	GLYNN ARCHER SCHL	A	Negative	0.11
122		PAINT	DOOR C	WOOD	C	Not Intact- FAIR	PURPLE	CR	213	SECOND	GLYNN ARCHER SCHL	A	Negative	0.16
123		PAINT	DOOR	WOOD	C	Not Intact-POOR	PURPLE	CR	213	SECOND	GLYNN ARCHER SCHL	A	Negative	0.05
124		PAINT	BASEBOARD	WOOD	C	Not Intact-POOR	BLACK	CR	213	SECOND	GLYNN ARCHER SCHL	A	Negative	0.5
125		PAINT	WALL	PLASTER	C	Not Intact-POOR	BEIGE	CR	213	SECOND	GLYNN ARCHER SCHL	A	Negative	0.24
126		PAINT	WALL	PLASTER	D	Not Intact- FAIR	BEIGE	CR	213	SECOND	GLYNN ARCHER SCHL	A	Negative	0.3
127		PAINT	WALL	PLASTER	A	Not Intact- FAIR	BEIGE	CR	213	SECOND	GLYNN ARCHER SCHL	A	Negative	0.9
128		PAINT	WALL	PLASTER	A	INTACT	PURPLE	CR	213	SECOND	GLYNN ARCHER SCHL	A	Negative	0.02
129		PAINT	WALL	PLASTER	C	Not Intact- FAIR	BEIGE	CR	200	SECOND	GLYNN ARCHER SCHL	A	Negative	0.2
130		PAINT	WALL	PLASTER	D	INTACT	BEIGE	CR	200	SECOND	GLYNN ARCHER SCHL	A	Negative	0
131		PAINT	WALL	DRYWALL	D	INTACT	BEIGE	CR	200	SECOND	GLYNN ARCHER SCHL	A	Negative	0
132		PAINT	WALL	PLASTER	A	INTACT	BEIGE	CR	200	SECOND	GLYNN ARCHER SCHL	A	Negative	0.19
133		PAINT	WALL	PLASTER	B	Not Intact-POOR	BEIGE	CR	200	SECOND	GLYNN ARCHER SCHL	A	Negative	0.24
134		PAINT	BASEBOARD	WOOD	B	Not Intact- FAIR	BEIGE	CR	200	SECOND	GLYNN ARCHER SCHL	A	Negative	0.2
135		PAINT	DOOR	WOOD	C	Not Intact-POOR	BEIGE	CR	200	SECOND	GLYNN ARCHER SCHL	A	Negative	0.15
136		PAINT	DOOR C	WOOD	C	Not Intact-POOR	BEIGE	CR	200	SECOND	GLYNN ARCHER SCHL	A	Negative	0.29

A = SOUTH

B = WEST

C = NORTH

D = EAST

GLYNN ARCHER ELEMENTARY SCHOOL - 1302 WHITE STREET, KEY WEST, FL

Reading	Nc	Type	COMPONENT	SUBSTRATE	SIDE	CONDITION	COLOR	ROOM TYPE	ROOM NUMBER	FLOOR	SITE/ADDRESS	BLDG	Results	PbC
137		PAINT	DOOR C	WOOD	D	Not Intact-POOR	PINK	CR	204	SECOND	GLYNN ARCHER SCHL	A	Negative	0.16
138		PAINT	DOOR	WOOD	D	Not Intact-POOR	PINK	CR	204	SECOND	GLYNN ARCHER SCHL	A	Negative	0.22
139		PAINT	BASEBOARD	WOOD	D	Not Intact- FAIR	BLUE	CR	204	SECOND	GLYNN ARCHER SCHL	A	Negative	0.5
140		PAINT	WALL	PLASTER	D	Not Intact-POOR	BLUE	CR	204	SECOND	GLYNN ARCHER SCHL	A	Negative	0.22
141		PAINT	WALL	PLASTER	A	Not Intact-POOR	BLUE	CR	204	SECOND	GLYNN ARCHER SCHL	A	Negative	0.9
142		PAINT	WALL	PLASTER	A	Not Intact-POOR	BEIGE	CR	204	SECOND	GLYNN ARCHER SCHL	A	Negative	0.16
143		PAINT	WALL	PLASTER	A	Not Intact-POOR	BEIGE	CR	204	SECOND	GLYNN ARCHER SCHL	A	Negative	0.25
144		PAINT	TRIM	WOOD	D	Not Intact-POOR	PINK	CR	204	SECOND	GLYNN ARCHER SCHL	A	Negative	0.4
145		PAINT	WALL	CERAMIC TILE	D	INTACT	WHITE	BATHROOM	212	SECOND	GLYNN ARCHER SCHL	A	Negative	0.04
146		PAINT	FLOOR	CERAMIC TILE	D	Not Intact- FAIR	WHITE	BATHROOM	212	SECOND	GLYNN ARCHER SCHL	A	Positive	1.3
147		PAINT	WALL	PLASTER	C	Not Intact- FAIR	BEIGE	BATHROOM	212	SECOND	GLYNN ARCHER SCHL	A	Negative	0
148		PAINT	WALL	PLASTER	D	Not Intact- FAIR	BEIGE	BATHROOM	212	SECOND	GLYNN ARCHER SCHL	A	Negative	0.5
149		PAINT	WALL	PLASTER	A	Not Intact- FAIR	BEIGE	BATHROOM	212	SECOND	GLYNN ARCHER SCHL	A	Negative	0.7
150		PAINT	DOOR	WOOD	A	Not Intact- FAIR	GREEN	BATHROOM	212	SECOND	GLYNN ARCHER SCHL	A	Negative	0.11
151		PAINT	DOOR	WOOD	A	Not Intact- FAIR	BLUE	BATHROOM	212	SECOND	GLYNN ARCHER SCHL	A	Negative	0.11
152		PAINT	DOOR C	WOOD	A	Not Intact- FAIR	BLUE	BATHROOM	212	SECOND	GLYNN ARCHER SCHL	A	Negative	0.4
153		PAINT	CALIBRATE	WOOD	CALIBRATE	INTACT	ORANGE	BATHROOM	212	SECOND	GLYNN ARCHER SCHL	A	Positive	1
154		SHUTTER	CAL											2.76
155		PAINT	CAL	WOOD	CALIBRATE	INTACT	ORANGE	CORR	CORR OUT 120	FIRST	GLYNN ARCHER SCHL	A	Positive	1.1
156		PAINT	WALL	PLASTER	CALIBRATE	Not Intact-POOR	BEIGE	CORR	CORR OUT 120	FIRST	GLYNN ARCHER SCHL	A	Positive	3.2
157		PAINT	DOOR	WOOD	A	Not Intact- FAIR	BLUE	CORR	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.03
158		PAINT	DOOR C	WOOD	A	INTACT	BLUE	CORR	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.16
159		PAINT	DOOR C	WOOD	A	Not Intact- FAIR	GREEN	CORR	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.29
160		PAINT	BASEBOARD	WOOD	B	Not Intact- FAIR	GREEN	CORR	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.13
161		PAINT	DOOR	WOOD	A	INTACT	WHITE	CORR	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.23
162		PAINT	WALL	PLASTER	A	INTACT	BEIGE	CORR	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Positive	1
163		PAINT	WALL	PLASTER	B	INTACT	BEIGE	CORR	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.15
164		PAINT	WALL	PLASTER	D	Not Intact- FAIR	BEIGE	CORR	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Positive	1
165		PAINT	WALL	CONCRETE	D	INTACT	BEIGE	CORR	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Positive	1
166		PAINT	COLUMN	CONCRETE	D	INTACT	BEIGE	CORR	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Positive	1.2
167		PAINT	W SILL	PLASTER	D	Not Intact- FAIR	BEIGE	CORR	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.3
168		PAINT	DOOR	WOOD	D	Not Intact-POOR	BEIGE	CORR	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.18
169		PAINT	DOOR C	WOOD	D	Not Intact-POOR	GREEN	CORR	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.29
170		PAINT	FLOOR	WOOD	C	Not Intact- FAIR	BROWN	CORR	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0

A = SOUTH

B = WEST

C = NORTH

D = EAST

GLYNN ARCHER ELEMENTARY SCHOOL - 1302 WHITE STREET, KEY WEST, FL

Reading Nc	Type	COMPONENT	SUBSTRATE	SIDE	CONDITION	COLOR	ROOM TYPE	ROOM NUMBER	FLOOR	SITE/ADDRESS	BLDG	Results	PbC
171	PAINT	TRIM	WOOD	C	Not Intact- FAIR	GREEN	CORR	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.23
172	PAINT	TRIM	WOOD	C	Not Intact- FAIR	GREEN	CORR	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.22
173	PAINT	WALL	PLASTER	C	INTACT	BEIGE	CORR	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.4
174	PAINT	WALL	CONCRETE	C	Not Intact- FAIR	BEIGE	CORR	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Positive	1.1
175	PAINT	DOOR	WOOD	B	Not Intact- FAIR	BEIGE	CORR	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0
176	PAINT	ST WALL	WOOD	C	Not Intact-POOR	BEIGE	CORR	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.12
177	PAINT	DOOR C	WOOD	B	Not Intact- FAIR	BEIGE	CORR	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.21
178	PAINT	DOOR C	WOOD	B	Not Intact-POOR	BEIGE	AUD	AUD 117C	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.2
179	PAINT	DOOR	WOOD	B	Not Intact- FAIR	BEIGE	AUD	AUD 117C	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.09
180	PAINT	DOOR C	WOOD	B	Not Intact-POOR	BEIGE	AUD	AUD 117D	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.09
181	PAINT	DOOR	WOOD	B	Not Intact-POOR	BEIGE	AUD	AUD 117D	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.08
182	PAINT	DOOR	WOOD	B	Not Intact- FAIR	PINK	AUD	AUD 117D	FIRST	GLYNN ARCHER SCHL	AUD	Positive	2.9
183	PAINT	DOOR C	WOOD	B	Not Intact-POOR	PINK	AUD	AUD 117D	FIRST	GLYNN ARCHER SCHL	AUD	Positive	2
184	PAINT	DOOR C	WOOD	B	Not Intact-POOR	GREY	AUD	AUD 117D	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.08
185	PAINT	BASEBOARD	WOOD	C	Not Intact-POOR	BLACK	AUD	AUD 117D	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.13
186	PAINT	BASEBOARD	WOOD	A	Not Intact-POOR	BLACK	AUD	AUD 117A	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.24
187	PAINT	DOOR	WOOD	D	Not Intact- FAIR	BEIGE	AUD	AUD 117A	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.06
188	PAINT	DOOR C	WOOD	D	Not Intact-POOR	GREY	AUD	AUD 117A	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.3
189	PAINT	DOOR C	WOOD	D	Not Intact-POOR	GREEN	AUD	AUD 117A	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.23
190	PAINT	DOOR C	WOOD	C	Not Intact-POOR	GREY	AUD	AUD 117A	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.5
191	PAINT	DOOR	WOOD	C	Not Intact-POOR	GREY	AUD	AUD 117A	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.5
192	PAINT	WALL	PLASTER	C	Not Intact- FAIR	WHITE	AUD	AUD 117A	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0.4
193	PAINT	AUD CHAIRS	PLASTER	C	Not Intact- FAIR	BROWN	AUD	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0
194	PAINT	AUD CHAIRS	PLASTER	A	Not Intact- FAIR	BROWN	AUD	AUD 117	FIRST	GLYNN ARCHER SCHL	AUD	Negative	0
195	PAINT	DOOR	WOOD	A	Not Intact- FAIR	BLUE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Positive	6.8
196	PAINT	DOOR C	WOOD	A	Not Intact- FAIR	BLUE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0.21
197	PAINT	DOOR C	WOOD	A	Not Intact- FAIR	BLUE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0.21
198	PAINT	DOOR S	METAL	A	Not Intact- FAIR	BLUE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0.01
199	PAINT	TRIM	WOOD	A	Not Intact- FAIR	BLUE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0
200	PAINT	TRIM	WOOD	B	Not Intact- FAIR	BLUE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0.01
201	PAINT	WALL	WOOD	B	Not Intact- FAIR	BLUE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0.07
202	PAINT	WALL	PLASTER	B	Not Intact- FAIR	BEIGE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0.27
203	PAINT	WALL	PLASTER	A	Not Intact- FAIR	BEIGE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0.5
204	PAINT	WALL	CONCRETE	B	Not Intact- FAIR	BEIGE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0.21

A = SOUTH

B = WEST

C = NORTH

D = EAST

GLYNN ARCHER ELEMENTARY SCHOOL - 1302 WHITE STREET, KEY WEST, FL

Reading	Nc	Type	COMPONENT	SUBSTRATE	SIDE	CONDITION	COLOR	ROOM TYPE	ROOM NUMBER	FLOOR	SITE/ADDRESS	BLDG	Results	PbC
205		PAINT	WALL	CONCRETE	B	Not Intact- FAIR	BLUE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Positive	1.7
206		PAINT	DOOR	WOOD	B	Not Intact- FAIR	BLUE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0
207		PAINT	DOOR C	WOOD	B	INTACT	BLUE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0.04
208		PAINT	TRIM	WOOD	B	INTACT	BLUE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0.03
209		PAINT	BASEBOARD	WOOD	B	Not Intact-POOR	BLUE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0.07
210		PAINT	WALLS	WOOD	B	Not Intact- FAIR	BLUE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0.03
211		PAINT	DOOR C	WOOD	B	Not Intact- FAIR	BLUE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0.4
212		PAINT	WALL	PLASTER	C	INTACT	BEIGE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0.22
213		PAINT	WALL	PLASTER	C	Not Intact- FAIR	BEIGE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0.5
214		PAINT	WALL	PLASTER	C	INTACT	BEIGE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0.4
215		PAINT	WALL	PLASTER	C	INTACT	BEIGE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0.3
216		PAINT	WALL	PLASTER	D	INTACT	BEIGE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0
217		PAINT	WALL	PLASTER	D	INTACT	BLUE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0.03
218		PAINT	WALL	PLASTER	A	INTACT	BEIGE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0.4
219		PAINT	DOOR	WOOD	DA	Not Intact- FAIR	BLUE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Positive	9
220		PAINT	DOOR	WOOD	DA	Not Intact-POOR	BLUE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Positive	9.2
221		PAINT	DOOR C	WOOD	DA	Not Intact-POOR	BLUE	CORR	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0.17
222		PAINT	DOOR C	WOOD	CD	Not Intact-POOR	BLUE	CORR ST	CORR	FIRST	GLYNN ARCHER SCHL	B	Negative	0.23
223		PAINT	DOOR	WOOD	D	Not Intact- FAIR	BLUE	CORR ST	CORR	SECOND	GLYNN ARCHER SCHL	B	Negative	0.03
224		PAINT	DOOR C	WOOD	D	Not Intact- FAIR	BLUE	CORR ST	CORR	SECOND	GLYNN ARCHER SCHL	B	Negative	0.01
225		PAINT	BASEBOARD	WOOD	D	Not Intact- FAIR	BLUE	CORR ST	CORR	SECOND	GLYNN ARCHER SCHL	B	Negative	0.4
226		PAINT	WALL	CONCRETE	D	INTACT	BLUE	CORR ST	CORR	SECOND	GLYNN ARCHER SCHL	B	Positive	1.7
227		PAINT	WALL	CONCRETE	D	INTACT	BEIGE	CORR ST	CORR	SECOND	GLYNN ARCHER SCHL	B	Positive	1.5
228		PAINT	WALL	CONCRETE	D	INTACT	BEIGE	CORR ST	CORR	SECOND	GLYNN ARCHER SCHL	B	Positive	1.4
229		PAINT	DOOR	WOOD	D	INTACT	BLUE	CORR ST	CORR	SECOND	GLYNN ARCHER SCHL	B	Negative	0.04
230		PAINT	DOOR C	WOOD	D	INTACT	BLUE	CORR ST	CORR	SECOND	GLYNN ARCHER SCHL	B	Negative	0.02
231		PAINT	BASEBOARD	WOOD	A	Not Intact-POOR	BLUE	CORR ST	CORR	SECOND	GLYNN ARCHER SCHL	B	Negative	0.3
232		PAINT	WALL	WOOD	A	Not Intact- FAIR	BLUE	CORR ST	CORR	SECOND	GLYNN ARCHER SCHL	B	Negative	0.06
233		PAINT	WALL	WOOD	A	INTACT	BLUE	CORR ST	CORR	SECOND	GLYNN ARCHER SCHL	B	Negative	0.07
234		PAINT	WALL	PLASTER	A	INTACT	BEIGE	CORR ST	CORR	SECOND	GLYNN ARCHER SCHL	B	Positive	1.1
235		PAINT	WALL	PLASTER	A	INTACT	BEIGE	CORR ST	CORR	SECOND	GLYNN ARCHER SCHL	B	Negative	0.5
236		PAINT	WALL	DRYWALL	A	INTACT	BEIGE	CORR ST	CORR	SECOND	GLYNN ARCHER SCHL	B	Negative	0
237		PAINT	WALL	DRYWALL	A	INTACT	BLUE	CORR ST	CORR	SECOND	GLYNN ARCHER SCHL	B	Negative	0
238		PAINT	WALL	PLASTER	A	INTACT	BLUE	CORR ST	CORR	SECOND	GLYNN ARCHER SCHL	B	Negative	0.4

A = SOUTH

B = WEST

C = NORTH

D = EAST

GLYNN ARCHER ELEMENTARY SCHOOL - 1302 WHITE STREET, KEY WEST, FL

Reading	Nc	Type	COMPONENT	SUBSTRATE	SIDE	CONDITION	COLOR	ROOM TYPE	ROOM NUMBER	FLOOR	SITE/ADDRESS	INSPECTC	Results	PbC
239		PAINT	WALL	CONCRETE	B	Not Intact- FAIR	BLUE	CORR ST	CORR	SECOND	GAS BLDG B	B	Negative	0.29
240		PAINT	WALL	CONCRETE	B	Not Intact- FAIR	BLUE	CORR ST	CORR	SECOND	GAS BLDG B	B	Negative	0.12
241		PAINT	WALL	CONCRETE	B	Not Intact-POOR	BLUE	CORR ST	CORR	SECOND	GAS BLDG B	B	Positive	1.2
242		PAINT	WALL	CONCRETE	B	INTACT	BLUE	CORR ST	CORR	SECOND	GAS BLDG B	B	Negative	0.4
243		PAINT	WALL	PLASTER	C	INTACT	WHITE	CR	207	SECOND	GAS BLDG B	B	Negative	0.27
244		PAINT	WALL	CONCRETE	C	Not Intact- FAIR	WHITE	CR	207	SECOND	GAS BLDG B	B	Positive	1
245		PAINT	WALL	CONCRETE	A	INTACT	WHITE	CR	207	SECOND	GAS BLDG B	B	Negative	0
246		PAINT	WALL	CONCRETE	B	INTACT	WHITE	CR	207	SECOND	GAS BLDG B	B	Negative	0
247		PAINT	TRIM	WOOD	B	Not Intact- FAIR	WHITE	CR	207	SECOND	GAS BLDG B	B	Negative	0.11
248		PAINT	BASEBOARD	WOOD	B	Not Intact- FAIR	WHITE	CR	207	SECOND	GAS BLDG B	B	Negative	0.4
249		PAINT	DOOR	WOOD	B	Not Intact- FAIR	WHITE	CR	207	SECOND	GAS BLDG B	B	Negative	-0.11
250		PAINT	DOOR C	WOOD	B	Not Intact- FAIR	WHITE	CR	207	SECOND	GAS BLDG B	B	Negative	0.25
251		PAINT	DOOR C	WOOD	C	Not Intact- FAIR	BLUE	CR	215	SECOND	GAS BLDG B	B	Negative	0.4
252		PAINT	DOOR	WOOD	C	Not Intact- FAIR	BLUE	CR	215	SECOND	GAS BLDG B	B	Negative	0.19
253		PAINT	DOOR	WOOD	C	Not Intact-POOR	PURPLE	CR	215	SECOND	GAS BLDG B	B	Negative	0.7
254		PAINT	DOOR C	WOOD	C	Not Intact- FAIR	WHITE	CR	215	SECOND	GAS BLDG B	B	Negative	0.14
255		PAINT	BASEBOARD	WOOD	C	Not Intact- FAIR	WHITE	CR	215	SECOND	GAS BLDG B	B	Negative	0.21
256		PAINT	TRIM	WOOD	D	Not Intact- FAIR	WHITE	CR	215	SECOND	GAS BLDG B	B	Positive	2
257		PAINT	TRIM	WOOD	C	Not Intact- FAIR	WHITE	CR	215	SECOND	GAS BLDG B	B	Positive	1.4
258		PAINT	BASEBOARD	WOOD	C	Not Intact- FAIR	WHITE	CR	215	SECOND	GAS BLDG B	B	Negative	0.3
259		PAINT	DC	WOOD	B	Not Intact-POOR	WHITE	CR	215	SECOND	GAS BLDG B	B	Negative	0.4
260		PAINT	W F	WOOD	B	Not Intact-POOR	WHITE	CR	215	SECOND	GAS BLDG B	B	Negative	0.2
261		PAINT	WALL	PLASTER	A	Not Intact-POOR	WHITE	CR	215	SECOND	GAS BLDG B	B	Negative	0
262		PAINT	DOOR	WOOD	C	Not Intact- FAIR	BLUE	CR	215	SECOND	GAS BLDG B	B	Negative	0.4
263		PAINT	DOOR C	WOOD	C	INTACT	BLUE	CR	215	SECOND	GAS BLDG B	B	Negative	0.3
264		PAINT	DOOR C	WOOD	C	INTACT	BLUE	CR	216	SECOND	GAS BLDG B	B	Negative	0.24
265		PAINT	DOOR	WOOD	C	Not Intact- FAIR	BLUE	CR	216	SECOND	GAS BLDG B	B	Negative	0.22
266		PAINT	DOOR	WOOD	C	Not Intact-POOR	BEIGE	CR	216	SECOND	GAS BLDG B	B	Negative	0.24
267		PAINT	DOOR	WOOD	C	Not Intact- FAIR	BLUE	CR	216	SECOND	GAS BLDG B	B	Negative	0.15
268		PAINT	DOOR	WOOD	C	Not Intact-POOR	BEIGE	CR	216	SECOND	GAS BLDG B	B	Negative	0.11
269		PAINT	WALL	PLASTER	C	INTACT	WHITE	CR	216	SECOND	GAS BLDG B	B	Negative	0.9
270		PAINT	WALL	PLASTER	B	Not Intact- FAIR	WHITE	CR	216	SECOND	GAS BLDG B	B	Negative	0
271		PAINT	WALL	CERAMIC TILE	B	Not Intact- FAIR	WHITE	CR	216	SECOND	GAS BLDG B	B	Negative	0.1
272		PAINT	BASEBOARD	CERAMIC TILE	B	Not Intact-POOR	WHITE	CR	216	SECOND	GAS BLDG B	B	Positive	2.2

A = SOUTH

B = WEST

C = NORTH

D = EAST

GLYNN ARCHER ELEMENTARY SCHOOL - 1302 WHITE STREET, KEY WEST, FL

Reading	Nc	Type	COMPONENT	SUBSTRATE	SIDE	CONDITION	COLOR	ROOM TYPE	ROOM NUMBER	FLOOR	SITE/ADDRESS	INSPECTC	Results	PbC
273		PAINT	BASEBOARD	CERAMIC TILE	B	Not Intact-POOR	WHITE	CR	216	SECOND	GAS BLDG B	B	Positive	1.8
274		PAINT	FLOOR	CERAMIC TILE	B	Not Intact- FAIR	GREY	CR	216	SECOND	GAS BLDG B	B	Negative	0.02
275		PAINT	TRIM	WOOD	B	Not Intact- FAIR	WHITE	CR	216	SECOND	GAS BLDG B	B	Negative	0.01
276		PAINT	WALL	DRYWALL	B	INTACT	BEIGE	CR	216	SECOND	GAS BLDG B	B	Negative	0
277		PAINT	WALL	PLASTER	D	INTACT	BEIGE	BR	217B	SECOND	GAS BLDG B	B	Negative	0
278		PAINT	WALL	CERAMIC TILE	D	INTACT	BEIGE	BR	217B	SECOND	GAS BLDG B	B	Negative	0.01
279		PAINT	FLOOR	CERAMIC TILE	D	Not Intact- FAIR	WHITE	BR	217B	SECOND	GAS BLDG B	B	Negative	0.01
280		PAINT	DOOR	WOOD	C	INTACT	BLUE	BR	217B	SECOND	GAS BLDG B	B	Negative	0.02
281		PAINT	DOOR C	WOOD	C	INTACT	BLUE	BR	217B	SECOND	GAS BLDG B	B	Negative	0
282		PAINT	DOOR C	WOOD	D	INTACT	BLUE	CR	206	SECOND	GAS BLDG B	B	Negative	0.09
283		PAINT	DOOR	WOOD	D	Not Intact- FAIR	BLUE	CR	206	SECOND	GAS BLDG B	B	Negative	0.05
284		PAINT	DOOR	WOOD	D	Not Intact- FAIR	BEIGE	CR	206	SECOND	GAS BLDG B	B	Negative	0.04
285		PAINT	BASEBOARD	WOOD	D	Not Intact-POOR	WHITE	CR	206	SECOND	GAS BLDG B	B	Negative	0.23
286		PAINT	WALL	PLASTER	B	Not Intact- FAIR	WHITE	CR	206	SECOND	GAS BLDG B	B	Negative	0.01
287		PAINT	WALL	PLASTER	A	Not Intact- FAIR	WHITE	CR	206	SECOND	GAS BLDG B	B	Positive	1.3
288		PAINT	WALL	PLASTER	D	INTACT	WHITE	CR	206	SECOND	GAS BLDG B	B	Positive	1.2
289		PAINT	WALL	PLASTER	C	INTACT	WHITE	CR	206	SECOND	GAS BLDG B	B	Negative	0
290		PAINT	TRIM	WOOD	D	Not Intact-POOR	GREEN	CR	206	SECOND	GAS BLDG B	B	Negative	0
291		PAINT	BKCSE	WOOD	B	Not Intact-POOR	GREEN	CR	206	SECOND	GAS BLDG B	B	Negative	0.03
292		PAINT	BKCSE	WOOD	B	Not Intact- FAIR	BROWN	CR	208	SECOND	GAS BLDG B	B	Negative	0.02
293		PAINT	CROWN MOLD	PLASTER	A	Not Intact-POOR	YELLOW	CR	208	SECOND	GAS BLDG B	B	Negative	0.14
294		PAINT	CROWN MOLD	WOOD	A	Not Intact-POOR	YELLOW	CR	208	SECOND	GAS BLDG B	B	Negative	0.07
295		PAINT	WALL	WOOD	A	Not Intact-POOR	YELLOW	CR	208	SECOND	GAS BLDG B	B	Negative	0.15
296		PAINT	WALL	PLASTER	A	Not Intact-POOR	YELLOW	CR	208	SECOND	GAS BLDG B	B	Negative	0.14
297		PAINT	CEILING	PLASTER	A	Not Intact-POOR	WHITE	CR	208	SECOND	GAS BLDG B	B	Negative	0.5
298		PAINT	WALL	PLASTER	B	Not Intact-POOR	BLUE	CR	208	SECOND	GAS BLDG B	B	Negative	0.3
299		PAINT	WALL	PLASTER	B	Not Intact-POOR	BLUE	CR	208	SECOND	GAS BLDG B	B	Negative	0.24
300		PAINT	WALL	PLASTER	C	Not Intact- FAIR	BLUE	CR	208	SECOND	GAS BLDG B	B	Negative	0.02
301		PAINT	WALL	PLASTER	D	Not Intact- FAIR	BLUE	CR	208	SECOND	GAS BLDG B	B	Negative	0
302		PAINT	BASEBOARD	WOOD	D	Not Intact-POOR	BLUE	CR	208	SECOND	GAS BLDG B	B	Negative	0
303		PAINT	TRIM	WOOD	D	Not Intact-POOR	BLUE	CR	208	SECOND	GAS BLDG B	B	Negative	0.04
304		PAINT	TRIM	WOOD	A	Not Intact- FAIR	BLUE	CR	208	SECOND	GAS BLDG B	B	Negative	0
305		PAINT	DOOR C	WOOD	A	Not Intact-POOR	BLUE	CR	208	SECOND	GAS BLDG B	B	Negative	0.2
306		PAINT	DOOR	WOOD	A	Not Intact-POOR	BLUE	CR	208	SECOND	GAS BLDG B	B	Negative	0.4

A = SOUTH

B = WEST

C = NORTH

D = EAST

GLYNN ARCHER ELEMENTARY SCHOOL - 1302 WHITE STREET, KEY WEST, FL

Reading	Nc	Type	COMPONENT	SUBSTRATE	SIDE	CONDITION	COLOR	ROOM TYPE	ROOM NUMBER	FLOOR	SITE/ADDRESS	INSPECTC	Results	PbC
307		SHUTTER	CAL											2.8
308		PAINT	CAL	WOOD		CALIBRATE INTACT	ORANGE	N	N	SECOND	GAS	B	Positive	1
309		PAINT	CAL	WOOD		CALIBRATE INTACT	ORANGE	N	N	SECOND	GAS	B	Positive	1.1
310		PAINT	DOOR	WOOD	A	Not Intact-POOR	BLUE	CR	209	SECOND	GAS	B	Negative	0.27
311		PAINT	DOOR C	WOOD	A	Not Intact-POOR	BLUE	CR	209	SECOND	GAS	B	Negative	0.15
312		PAINT	BASEBOARD	WOOD	A	Not Intact- FAIR	BLUE	CR	209	SECOND	GAS	B	Negative	0.6
313		PAINT	BASEBOARD	WOOD	A	Not Intact- FAIR	BLUE	CR	209	SECOND	GAS	B	Negative	0.28
314		PAINT	WALL	PLASTER	A	Not Intact- FAIR	BLUE	CR	209	SECOND	GAS	B	Negative	0.21
315		PAINT	WALL	PLASTER	C	Not Intact- FAIR	BLUE	CR	209	SECOND	GAS	B	Negative	0.3
316		PAINT	WALL	DRYWALL	D	Not Intact- FAIR	BLUE	CR	209	SECOND	GAS	B	Negative	0
317		PAINT	WALL	DRYWALL	B	Not Intact- FAIR	BLUE	CR	209	SECOND	GAS	B	Negative	0
318		PAINT	CBNT FRONT	WOOD	B	Not Intact- FAIR	WHITE	CR	209	SECOND	GAS	B	Negative	0.04
319		PAINT	DOOR	WOOD	B	Not Intact-POOR	WHITE	CR	210	SECOND	GAS	B	Negative	0.06
320		PAINT	DOOR C	WOOD	B	Not Intact-POOR	WHITE	CR	210	SECOND	GAS	B	Negative	0.26
321		PAINT	BASEBOARD	WOOD	B	Not Intact- FAIR	WHITE	CR	210	SECOND	GAS	B	Negative	0.25
322		PAINT	WALL	PLASTER	A	Not Intact- FAIR	BEIGE	CR	210	SECOND	GAS	B	Negative	0.3
323		PAINT	WALL	PLASTER	C	Not Intact- FAIR	BEIGE	CR	210	SECOND	GAS	B	Negative	0.01
324		PAINT	WALL	PLASTER	C	Not Intact- FAIR	BEIGE	CR	210	SECOND	GAS	B	Negative	0
325		PAINT	WALL	PLASTER	D	Not Intact-POOR	BEIGE	CR	210	SECOND	GAS	B	Negative	0.28
326		PAINT	WALL	PLASTER	A	Not Intact- FAIR	BLUE	CR	107	FIRST	GAS	B	Negative	0.05
327		PAINT	DOOR	WOOD	A	Not Intact- FAIR	BLUE	CR	107	FIRST	GAS	B	Negative	-0.31
328		PAINT	DOOR C	WOOD	A	Not Intact-POOR	BLUE	CR	107	FIRST	GAS	B	Negative	-0.3
329		PAINT	DOOR C	WOOD	A	Not Intact- FAIR	PINK	CR	107	FIRST	GAS	B	Negative	0.19
330		PAINT	DOOR	WOOD	A	Not Intact- FAIR	PINK	CR	107	FIRST	GAS	B	Negative	0.06
331		PAINT	BASEBOARD	WOOD	B	Not Intact-POOR	BLACK	CR	107	FIRST	GAS	B	Negative	0.6
332		PAINT	TRIM	WOOD	B	Not Intact- FAIR	WHITE	CR	107	FIRST	GAS	B	Negative	0.12
333		PAINT	TRIM	WOOD	B	INTACT	YELLOW	CR	107	FIRST	GAS	B	Negative	0
334		PAINT	WALL	PLASTER	B	INTACT	YELLOW	CR	107	FIRST	GAS	B	Negative	0.09
335		PAINT	WALL	PLASTER	A	INTACT	YELLOW	CR	107	FIRST	GAS	B	Negative	0.05
336		PAINT	TRIM	WOOD	A	Not Intact- FAIR	WHITE	CR	107	FIRST	GAS	B	Negative	0.22
337		PAINT	WALL	PLASTER	D	Not Intact- FAIR	YELLOW	CR	107	FIRST	GAS	B	Negative	0.9
338		PAINT	WALL	PLASTER	D	INTACT	WHITE	CR	106	FIRST	GAS	B	Negative	0.3
339		PAINT	WALL	PLASTER	B	INTACT	WHITE	CR	106	FIRST	GAS	B	Negative	0
340		PAINT	WALL	PLASTER	A	INTACT	WHITE	CR	106	FIRST	GAS	B	Negative	0

A = SOUTH

B = WEST

C = NORTH

D = EAST

GLYNN ARCHER ELEMENTARY SCHOOL - 1302 WHITE STREET, KEY WEST, FL

Reading	Nc	Type	COMPONENT	SUBSTRATE	SIDE	CONDITION	COLOR	ROOM TYPE	ROOM NUMBER	FLOOR	SITE/ADDRESS	INSPECTC	Results	PbC
341		PAINT	WALL	PLASTER	A	INTACT	WHITE	CR	106	FIRST	GAS	B	Negative	0.5
342		PAINT	DOOR	WOOD	A	Not Intact-POOR	BEIGE	CR	108	FIRST	GAS	B	Negative	-0.04
343		PAINT	DOOR C	WOOD	A	Not Intact- FAIR	BEIGE	CR	108	FIRST	GAS	B	Negative	0.08
344		PAINT	WALL	WOOD	C	Not Intact- FAIR	BEIGE	CR	108	FIRST	GAS	B	Negative	0
345		PAINT	WALL	PLASTER	A	Not Intact-POOR	BEIGE	CR	105	FIRST	GAS	B	Negative	0.01
346		PAINT	WALL	PLASTER	A	Not Intact-POOR	WHITE	CR	105	FIRST	GAS	B	Negative	0.02
347		PAINT	WALL	PLASTER	D	Not Intact- FAIR	WHITE	CR	105	FIRST	GAS	B	Negative	0.14
348		PAINT	WALL	WOOD	D	INTACT	WHITE	CR	105	FIRST	GAS	B	Negative	0.02
349		PAINT	TRIM	WOOD	C	Not Intact- FAIR	BEIGE	CR	105	FIRST	GAS	B	Negative	0.03
350		PAINT	BASEBOARD	WOOD	C	Not Intact- FAIR	BEIGE	CR	105	FIRST	GAS	B	Negative	0.7
351		PAINT	BASEBOARD	WOOD	B	INTACT	WHITE	CR	121	FIRST	GAS	B	Negative	0
352		PAINT	WAL	WOOD	B	Not Intact- FAIR	BEIGE	CR	121	FIRST	GAS	B	Negative	0.01
353		PAINT	WAL	CERAMIC TILE	C	INTACT	WHITE	CR	121A	FIRST	GAS	B	Negative	0.01
354		PAINT	DOOR	CERAMIC TILE	D	Not Intact- FAIR	WHITE	CR	121A	FIRST	GAS	B	Negative	0.12
355		PAINT	DOOR C	CERAMIC TILE	D	Not Intact- FAIR	WHITE	CR	121A	FIRST	GAS	B	Negative	0.08
356		PAINT	DOOR C	CERAMIC TILE	D	Not Intact-POOR	BLUE	BATHROOM	BOYS	FIRST	GAS	B	Negative	0
357		PAINT	WAL	PLASTER	D	Not Intact-POOR	BEIGE	BATHROOM	BOYS	FIRST	GAS	B	Negative	0.3
358		PAINT	WAL	CERAMIC TILE	B	Not Intact- FAIR	GREEN	BATHROOM	BOYS	FIRST	GAS	B	Negative	0.01
359		PAINT	FLOOR	CERAMIC TILE	B	Not Intact- FAIR	GREY	BATHROOM	BOYS	FIRST	GAS	B	Negative	0.01
360		PAINT	BASEBOARD	CERAMIC TILE	B	Not Intact- FAIR	BEIGE	BATHROOM	BOYS	FIRST	GAS	B	Positive	1.7
361		PAINT	DOOR	WOOD	D	Not Intact- FAIR	BEIGE	CR	104	FIRST	GAS	B	Negative	0.12
362		PAINT	DOOR C	WOOD	D	Not Intact-POOR	BEIGE	CR	104	FIRST	GAS	B	Negative	0.22
363		PAINT	TRIM	WOOD	D	Not Intact-POOR	BEIGE	CR	104	FIRST	GAS	B	Negative	0.11
364		PAINT	TRIM	WOOD	D	Not Intact-POOR	BEIGE	CR	104	FIRST	GAS	B	Negative	0.08
365		PAINT	WALL	PLASTER	B	INTACT	BEIGE	CR	104	FIRST	GAS	B	Negative	0.04
366		PAINT	WALL	PLASTER	A	Not Intact- FAIR	BEIGE	CR	104	FIRST	GAS	B	Negative	0.05
367		PAINT	WALL	PLASTER	A	Not Intact- FAIR	BEIGE	CR	109B	FIRST	GAS	B	Negative	0.07
368		PAINT	WALL	PLASTER	C	Not Intact- FAIR	BEIGE	CR	109B	FIRST	GAS	B	Positive	2.5
369		PAINT	WALL	PLASTER	C	Not Intact- FAIR	BEIGE	CR	109B	FIRST	GAS	B	Negative	0.9
370		PAINT	WALL	PLASTER	B	Not Intact-POOR	BEIGE	CR	109B	FIRST	GAS	B	Positive	1.6
371		PAINT	WALL	PLASTER	D	Not Intact- FAIR	BEIGE	CR	109B	FIRST	GAS	B	Negative	-0.06
372		PAINT	BASEBOARD	WOOD	B	Not Intact-POOR	BEIGE	CR	109B	FIRST	GAS	B	Negative	0.19
373		PAINT	TRIM	WOOD	A	Not Intact-POOR	BLUE	CR	109B	FIRST	GAS	B	Negative	0.13
374		PAINT	WALL	PLASTER	A	Not Intact- FAIR	BEIGE	CR	104	FIRST	GAS	B	Negative	0.21

A = SOUTH

B = WEST

C = NORTH

D = EAST

GLYNN ARCHER ELEMENTARY SCHOOL - 1302 WHITE STREET, KEY WEST, FL

Reading	Nc	Type	COMPONENT	SUBSTRATE	SIDE	CONDITION	COLOR	ROOM TYPE	ROOM NUMBER	FLOOR	SITE/ADDRESS	INSPECTC	Results	PbC
375		PAINT	WALL	PLASTER	D	Not Intact- FAIR	BEIGE	STAIRS	E STAIRS	FIRST	GAS	B	Negative	0.5
376		PAINT	STR HAND RAI	WOOD	D	Not Intact- FAIR	BLUE	STAIRS	E STAIRS	FIRST	GAS	B	Negative	0.21
377		PAINT	STR NEWAL P	WOOD	D	Not Intact- FAIR	BLUE	STAIRS	E STAIRS	FIRST	GAS	B	Negative	0.08
378		PAINT	CAL	WOOD	CALIBRATE	INTACT	ORANGE	STAIRS	E STAIRS	FIRST	GAS	B	Positive	1
379		SHUTTER	CAL											2.88
380		PAINT	CAL	WOOD	CALIBRATE	INTACT	ORANGE	N	N	N	GAS BLDG C	C	Positive	1.2
381		PAINT	D	WOOD	B	INTACT	BLUE	CR	113A	FIRST	GAS BLDG C	C	Negative	0.06
382		PAINT	DC	WOOD	B	Not Intact- FAIR	BLUE	CR	113A	FIRST	GAS BLDG C	C	Negative	0.26
383		PAINT	BASEBOARD	WOOD	B	Not Intact-POOR	YELLOW	CR	113A	FIRST	GAS BLDG C	C	Negative	0.03
384		PAINT	BASEBOARD	WOOD	B	Not Intact-POOR	YELLOW	CR	113A	FIRST	GAS BLDG C	C	Negative	0
385		PAINT	WALL	PLASTER	D	INTACT	YELLOW	CR	113A	FIRST	GAS BLDG C	C	Negative	0
386		PAINT	WALL	PLASTER	B	INTACT	YELLOW	CR	113A	FIRST	GAS BLDG C	C	Negative	0
387		PAINT	D	WOOD	B	INTACT	BLUE	BATHROOM	BOYS	FIRST	GAS BLDG C	C	Negative	0.03
388		PAINT	DC	WOOD	B	Not Intact-POOR	BLUE	BATHROOM	BOYS	FIRST	GAS BLDG C	C	Negative	0
389		PAINT	DC	WOOD	B	INTACT	BEIGE	BATHROOM	BOYS	FIRST	GAS BLDG C	C	Negative	0
390		PAINT	WALL	CERAMIC TILE	A	INTACT	BEIGE	BATHROOM	BOYS	FIRST	GAS BLDG C	C	Negative	0.01
391		PAINT	FLOOR	CERAMIC TILE	A	INTACT	GREY	BATHROOM	BOYS	FIRST	GAS BLDG C	C	Negative	0.01
392		PAINT	SINK	METAL	A	Not Intact- FAIR	WHITE	BATHROOM	BOYS	FIRST	GAS BLDG C	C	Positive	28.3
393		PAINT	SINK	METAL	A	Not Intact-POOR	WHITE	BATHROOM	BOYS	FIRST	GAS BLDG C	C	Positive	28.1
394		PAINT	TOILET	CERAMIC TILE	C	INTACT	WHITE	BATHROOM	BOYS	FIRST	GAS BLDG C	C	Negative	0.03
395		PAINT	D	WOOD	B	Not Intact- FAIR	BLUE	BATHROOM	134	FIRST	GAS BLDG C	C	Negative	0.09
396		PAINT	DC	WOOD	B	INTACT	BLUE	BATHROOM	134	FIRST	GAS BLDG C	C	Negative	0.07
397		PAINT	DC	WOOD	B	Not Intact- FAIR	WHITE	BATHROOM	134	FIRST	GAS BLDG C	C	Negative	0.3
398		PAINT	D	WOOD	B	Not Intact- FAIR	WHITE	BATHROOM	134	FIRST	GAS BLDG C	C	Negative	0.03
399		PAINT	DC	WOOD	B	Not Intact- FAIR	WHITE	BATHROOM	134	FIRST	GAS BLDG C	C	Negative	0.13
400		PAINT	W	CERAMIC TILE	B	Not Intact- FAIR	GREEN	BATHROOM	134	FIRST	GAS BLDG C	C	Negative	0.02
401		PAINT	W	PLASTER	A	INTACT	WHITE	BATHROOM	134	FIRST	GAS BLDG C	C	Negative	0.05
402		PAINT	SINK	CERAMIC TILE	C	INTACT	WHITE	BATHROOM	134	FIRST	GAS BLDG C	C	Negative	0.02
403		PAINT	D	WOOD	B	Not Intact-POOR	BLUE	BATHROOM	126	FIRST	GAS BLDG C	C	Negative	0.2
404		PAINT	DC	WOOD	B	Not Intact- FAIR	BLUE	BATHROOM	126	FIRST	GAS BLDG C	C	Negative	0.23
405		PAINT	DC	WOOD	B	Not Intact-POOR	BEIGE	BATHROOM	126	FIRST	GAS BLDG C	C	Negative	0.22
406		PAINT	W	PLASTER	A	Not Intact- FAIR	BEIGE	BATHROOM	126	FIRST	GAS BLDG C	C	Negative	0
407		PAINT	W	PLASTER	D	Not Intact- FAIR	BEIGE	CORR	CORR	FIRST	GAS BLDG C	C	Negative	0.02
408		PAINT	W	PLASTER	D	Not Intact- FAIR	BLUE	CORR	CORR	FIRST	GAS BLDG C	C	Negative	0.05

A = SOUTH

B = WEST

C = NORTH

D = EAST

GLYNN ARCHER ELEMENTARY SCHOOL - 1302 WHITE STREET, KEY WEST, FL

Reading	Nc	Type	COMPONENT	SUBSTRATE	SIDE	CONDITION	COLOR	ROOM TYPE	ROOM NUMBER	FLOOR	SITE/ADDRESS	INSPECTC	Results	PbC
409		PAINT	W	PLASTER	B	Not Intact- FAIR	BLUE	CORR	CORR	FIRST	GAS BLDG C	C	Negative	0.06
410		PAINT	W	PLASTER	B	Not Intact- FAIR	BEIGE	CORR	CORR	FIRST	GAS BLDG C	C	Negative	0
411		PAINT	D	WOOD	B	Not Intact- FAIR	BLUE	CR	111	FIRST	GAS BLDG C	C	Negative	0.04
412		PAINT	DC	WOOD	B	Not Intact-POOR	BLUE	CR	111	FIRST	GAS BLDG C	C	Negative	0.01
413		PAINT	DC	WOOD	B	Not Intact-POOR	YELLOW	CR	111	FIRST	GAS BLDG C	C	Negative	0.06
414		PAINT	W	PLASTER	B	Not Intact- FAIR	WHITE	CR	111	FIRST	GAS BLDG C	C	Negative	0.1
415		PAINT	W	PLASTER	A	Not Intact- FAIR	WHITE	CR	111	FIRST	GAS BLDG C	C	Negative	0.05
416		PAINT	W	PLASTER	D	Not Intact-POOR	WHITE	CR	111	FIRST	GAS BLDG C	C	Negative	0.05
417		PAINT	TRIM	WOOD	D	Not Intact- FAIR	WHITE	CR	111	FIRST	GAS BLDG C	C	Negative	0.02
418		PAINT	CBNT FRONT	WOOD	C	Not Intact- FAIR	BEIGE	CR	111	FIRST	GAS BLDG C	C	Negative	0.08
419		PAINT	TRIM	WOOD	B	Not Intact- FAIR	BEIGE	CR	111	FIRST	GAS BLDG C	C	Negative	0.05
420		PAINT	TRIM	WOOD	B	Not Intact- FAIR	BEIGE	CR	111	FIRST	GAS BLDG C	C	Negative	0.06
421		PAINT	FLOOR	CERAMIC TILE	D	INTACT	WHITE	CR	111	FIRST	GAS BLDG C	C	Negative	0.09
422		PAINT	SINK	METAL	A	INTACT	WHITE	BATHROOM	111A	FIRST	GAS BLDG C	C	Negative	0.01
423		PAINT	D	WOOD	D	Not Intact- FAIR	BLUE	CR	113C	FIRST	GAS BLDG C	C	Negative	0
424		PAINT	DC	WOOD	D	Not Intact-POOR	BLUE	CR	113C	FIRST	GAS BLDG C	C	Negative	0
425		PAINT	DC	WOOD	D	Not Intact-POOR	GREEN	CR	113C	FIRST	GAS BLDG C	C	Negative	0.4
426		PAINT	BASEBOARD	WOOD	D	Not Intact-POOR	BLACK	CR	113C	FIRST	GAS BLDG C	C	Negative	0.18
427		PAINT	W	PLASTER	D	Not Intact- FAIR	GREEN	CR	113C	FIRST	GAS BLDG C	C	Negative	0.02
428		PAINT	W	PLASTER	C	Not Intact- FAIR	GREEN	CR	113C	FIRST	GAS BLDG C	C	Negative	0
429		PAINT	W	PLASTER	B	Not Intact- FAIR	GREEN	CR	113C	FIRST	GAS BLDG C	C	Negative	0
430		PAINT	WS	CERAMIC TILE	B	INTACT	RED	CR	113C	FIRST	GAS BLDG C	C	Negative	0.15
431		PAINT	WS	WOOD	B	Not Intact-POOR	RED	CR	113C	FIRST	GAS BLDG C	C	Negative	0
432		PAINT	WS	DRYWALL	A	Not Intact- FAIR	GREEN	CR	113C	FIRST	GAS BLDG C	C	Negative	0
433		PAINT	D	WOOD	A	Not Intact- FAIR	BLUE	CR	114	FIRST	GAS BLDG C	C	Negative	0.04
434		PAINT	DC	WOOD	A	INTACT	BLUE	CR	114	FIRST	GAS BLDG C	C	Negative	0.16
435		PAINT	DC	WOOD	D	INTACT	GREY	CR	114	FIRST	GAS BLDG C	C	Negative	0.06
436		PAINT	W	PLASTER	D	INTACT	BEIGE	CR	114	FIRST	GAS BLDG C	C	Negative	0.01
437		PAINT	W	PLASTER	C	INTACT	BEIGE	CR	114	FIRST	GAS BLDG C	C	Negative	0
438		PAINT	W	PLASTER	A	Not Intact- FAIR	BEIGE	CR	114	FIRST	GAS BLDG C	C	Negative	0
439		PAINT	D	WOOD	D	Not Intact-POOR	BLUE	CR	114B	FIRST	GAS BLDG C	C	Negative	0.03
440		PAINT	DC	WOOD	D	Not Intact-POOR	BLUE	CR	114B	FIRST	GAS BLDG C	C	Negative	0.09
441		PAINT	WF	WOOD	A	Not Intact- FAIR	GREY	CR	114B	FIRST	GAS BLDG C	C	Negative	0.05
442		PAINT	D	WOOD	B	Not Intact- FAIR	BLUE	CR	112	FIRST	GAS BLDG C	C	Negative	0.04

A = SOUTH

B = WEST

C = NORTH

D = EAST

GLYNN ARCHER ELEMENTARY SCHOOL - 1302 WHITE STREET, KEY WEST, FL

Reading	Nc	Type	COMPONENT	SUBSTRATE	SIDE	CONDITION	COLOR	ROOM TYPE	ROOM NUMBER	FLOOR	SITE/ADDRESS	INSPECTC	Results	PbC
477		PAINT	W	STUCCO	C	Not Intact- FAIR	YELLOW	EXTERIOR	N	FIRST	GAS BLDG C	C	Negative	0.06
478		PAINT	W	STUCCO	C	Not Intact- FAIR	YELLOW	EXTERIOR	N	FIRST	GAS BLDG C	C	Negative	0.05
479		PAINT	W	STUCCO	C	Not Intact-POOR	YELLOW	EXTERIOR	N	FIRST	GAS BLDG C	C	Negative	0.18
480		PAINT	RISER	METAL	C	Not Intact- FAIR	YELLOW	EXTERIOR	N	FIRST	GAS BLDG C	C	Negative	-0.4
481		PAINT	CONDUIT	METAL	C	Not Intact- FAIR	YELLOW	EXTERIOR	N	FIRST	GAS BLDG C	C	Negative	0
482		PAINT	BRACKET	METAL	C	Not Intact-POOR	YELLOW	EXTERIOR	N	FIRST	GAS BLDG C	C	Negative	0
483		PAINT	HEADER	WOOD	C	Not Intact-POOR	WHITE	EXTERIOR	N	FIRST	GAS BLDG C	C	Negative	0
484		PAINT	W	STUCCO	C	Not Intact- FAIR	YELLOW	EXTERIOR	N	FIRST	GAS BLDG C	C	Negative	0.5
485		PAINT	W	STUCCO	C	Not Intact-POOR	YELLOW	EXTERIOR	N	FIRST	GAS BLDG C	C	Negative	0
486		PAINT	W	STUCCO	A	Not Intact-POOR	YELLOW	EXTERIOR	N	FIRST	GAS BLDG C	C	Negative	0.01
487		PAINT	W	STUCCO	A	Not Intact-POOR	YELLOW	EXTERIOR	N	FIRST	GAS BLDG C	C	Negative	0
488		PAINT	D	WOOD	A	Not Intact- FAIR	GREEN	EXTERIOR	N	FIRST	GAS BLDG C	C	Negative	0
489		PAINT	DC	WOOD	A	Not Intact-POOR	GREEN	EXTERIOR	N	FIRST	GAS BLDG C	C	Negative	0.16
490		PAINT	DC	WOOD	C	Not Intact-POOR	GREEN	EXTERIOR	N	FIRST	GAS BLDG B	B	Negative	0.16
491		PAINT	D	WOOD	C	Not Intact- FAIR	GREEN	EXTERIOR	N	FIRST	GAS BLDG B	B	Negative	0
492		PAINT	W	STUCCO	C	Not Intact- FAIR	BEIGE	EXTERIOR	N	FIRST	GAS BLDG B	B	Positive	1.5
493		PAINT	W	STUCCO	C	Not Intact- FAIR	BEIGE	EXTERIOR	N	FIRST	GAS BLDG B	B	Positive	1.2
494		PAINT	W	STUCCO	C	Not Intact- FAIR	BEIGE	EXTERIOR	N	FIRST	GAS BLDG B	B	Negative	0.13
495		PAINT	W	STUCCO	C	Not Intact- FAIR	BEIGE	EXTERIOR	N	FIRST	GAS BLDG B	B	Positive	1.6
496		PAINT	W SMOOTH	STUCCO	D	Not Intact- FAIR	BEIGE	EXTERIOR	N	FIRST	GAS BLDG B	B	Negative	0.3
497		PAINT	W	STUCCO	A	Not Intact- FAIR	BEIGE	EXTERIOR	N	FIRST	GAS BLDG B	B	Negative	0.08
498		PAINT	W	STUCCO	A	Not Intact- FAIR	BEIGE	EXTERIOR	N	FIRST	GAS BLDG B	B	Negative	0
499		PAINT	WS	CONCRETE	A	Not Intact-POOR	BEIGE	EXTERIOR	N	FIRST	GAS BLDG B	B	Negative	0.02
500		PAINT	WS	STUCCO	A	Not Intact- FAIR	BEIGE	EXTERIOR	N	FIRST	GAS BLDG B	B	Negative	0.06
501		PAINT	W	STUCCO	A	Not Intact- FAIR	BEIGE	EXTERIOR	N	FIRST	GAS BLDG B	B	Negative	0.19
502		PAINT	COLUMN	STUCCO	A	Not Intact-POOR	WHITE	EXTERIOR	N	FIRST	GAS BLDG B	B	Negative	0.08
503		PAINT	L	STUCCO	A	Not Intact- FAIR	WHITE	EXTERIOR	N	FIRST	GAS BLDG B	B	Negative	0.16
504		PAINT	D	WOOD	B	Not Intact-POOR	GREEN	EXTERIOR	N	FIRST	GAS BLDG AUD	AUD	Positive	4.4
505		PAINT	DC	WOOD	B	Not Intact-POOR	GREEN	EXTERIOR	N	FIRST	GAS BLDG AUD	AUD	Positive	5.8
506		PAINT	COLUMN	CONCRETE	B	Not Intact- FAIR	WHITE	EXTERIOR	N	FIRST	GAS BLDG AUD	AUD	Negative	0.4
507		PAINT	TRIM	CONCRETE	B	Not Intact- FAIR	WHITE	EXTERIOR	N	FIRST	GAS BLDG AUD	AUD	Negative	0.3
508		PAINT	L	CONCRETE	B	Not Intact- FAIR	WHITE	EXTERIOR	N	FIRST	GAS BLDG AUD	AUD	Negative	0.24
509		PAINT	W	STUCCO	B	Not Intact- FAIR	BEIGE	EXTERIOR	N	FIRST	GAS BLDG AUD	AUD	Negative	0.01
510		PAINT	W	STUCCO	B	Not Intact- FAIR	BEIGE	EXTERIOR	N	FIRST	GAS BLDG AUD	AUD	Positive	1

A = SOUTH

B = WEST

C = NORTH

D = EAST

GLYNN ARCHER ELEMENTARY SCHOOL - 1302 WHITE STREET, KEY WEST, FL

Reading	Nc	Type	COMPONENT	SUBSTRATE	SIDE	CONDITION	COLOR	ROOM TYPE	ROOM NUMBER	FLOOR	SITE/ADDRESS	INSPECTC	Results	PbC
511		PAINT	W	STUCCO	B	Not Intact- FAIR	BEIGE	EXTERIOR	N	FIRST	GAS BLDG AUD	AUD	Negative	0.4
512		PAINT	W	WOOD	C	Not Intact-POOR	BEIGE	EXTERIOR	ST	FIRST	GAS BLDG AUD	AUD	Positive	1.1
513		PAINT	W	STUCCO	C	Not Intact- FAIR	BEIGE	EXTERIOR	ST	FIRST	GAS BLDG AUD	AUD	Negative	0.08
514		PAINT	W	STUCCO	C	Not Intact- FAIR	BEIGE	EXTERIOR	ST	FIRST	GAS BLDG AUD	AUD	Negative	0.09
515		PAINT	W	STUCCO	C	Not Intact- FAIR	BEIGE	EXTERIOR	ST	FIRST	GAS BLDG AUD	AUD	Negative	0.08
516		PAINT	W	STUCCO	C	Not Intact- FAIR	BEIGE	EXTERIOR	ST	FIRST	GAS BLDG AUD	AUD	Negative	0.01
517		PAINT	W	STUCCO	C	Not Intact- FAIR	BEIGE	EXTERIOR	ST	FIRST	GAS BLDG AUD	AUD	Negative	0.5
518		PAINT	COLUMN	STUCCO	D	Not Intact- FAIR	WHITE	EXTERIOR	ST	FIRST	GAS BLDG AUD	AUD	Negative	0.1
519		PAINT	COLUMN	CONCRETE	D	Not Intact- FAIR	WHITE	EXTERIOR	ST	FIRST	GAS BLDG AUD	AUD	Negative	0.16
520		PAINT	FLOOR	CONCRETE	D	Not Intact- FAIR	GREY	EXTERIOR	ST	FIRST	GAS BLDG AUD	AUD	Negative	0.02
521		PAINT	D	WOOD	D	Not Intact-POOR	GREEN	EXTERIOR	ST	FIRST	GAS BLDG AUD	AUD	Negative	0.29
522		PAINT	DC	WOOD	D	Not Intact-POOR	GREEN	EXTERIOR	ST	FIRST	GAS BLDG AUD	AUD	Positive	1.8
523		PAINT	D	WOOD	C	Not Intact-POOR	GREEN	EXTERIOR	ST	FIRST	GAS BLDG A	A	Positive	8.4
524		PAINT	DC	WOOD	C	Not Intact-POOR	GREEN	EXTERIOR	ST	FIRST	GAS BLDG A	A	Positive	8.2
525		PAINT	D	WOOD	C	Not Intact- FAIR	BLUE	EXTERIOR	ST	FIRST	GAS BLDG A	A	Positive	8.7
526		PAINT	DC	WOOD	C	Not Intact- FAIR	BLUE	EXTERIOR	ST	FIRST	GAS BLDG A	A	Positive	5.4
527		PAINT	W	STUCCO	C	Not Intact- FAIR	BEIGE	EXTERIOR	ST	FIRST	GAS BLDG A	A	Negative	0.15
528		PAINT	W	STUCCO	C	Not Intact- FAIR	BEIGE	EXTERIOR	ST	FIRST	GAS BLDG A	A	Negative	0.05
529		PAINT	COLUMN	CONCRETE	C	Not Intact- FAIR	WHITE	EXTERIOR	ST	FIRST	GAS BLDG A	A	Negative	0.23
530		PAINT	D	WOOD	CB	Not Intact-POOR	GREEN	EXTERIOR	ST	FIRST	GAS BLDG A	A	Positive	6.7
531		PAINT	DC	WOOD	CB	Not Intact-POOR	BLUE	EXTERIOR	ST	FIRST	GAS BLDG A	A	Positive	6.9
532		PAINT	STAIRS	METAL	B	Not Intact-POOR	BEIGE	EXTERIOR	ST	FIRST	GAS BLDG A	A	Positive	1.4
533		PAINT	H RAIL	METAL	B	Not Intact-POOR	BEIGE	EXTERIOR	ST	FIRST	GAS BLDG A	A	Negative	0.13
534		PAINT	D	WOOD	B	INTACT	GREEN	EXTERIOR	ST	SECOND	GAS BLDG A	A	Negative	0
535		PAINT	DC	WOOD	B	Not Intact- FAIR	GREEN	EXTERIOR	ST	SECOND	GAS BLDG A	A	Negative	0.01
536		PAINT	W	STUCCO	B	Not Intact- FAIR	BEIGE	EXTERIOR	ST	SECOND	GAS BLDG A	A	Negative	0.09
537		PAINT	W	STUCCO	B	Not Intact- FAIR	BEIGE	EXTERIOR	ST	SECOND	GAS BLDG A	A	Negative	0.5
538		PAINT	COLUMN	STUCCO	B	Not Intact- FAIR	WHITE	EXTERIOR	ST	SECOND	GAS BLDG A	A	Negative	0.6
539		PAINT	W	STUCCO	A	Not Intact- FAIR	BEIGE	EXTERIOR	ST	FIRST	GAS BLDG A	A	Negative	0.07
540		PAINT	W	STUCCO	A	Not Intact- FAIR	WHITE	EXTERIOR	ST	FIRST	GAS BLDG A	A	Negative	0.15
541		PAINT	W	STUCCO	A	Not Intact- FAIR	BEIGE	EXTERIOR	ST	FIRST	GAS BLDG A	A	Negative	0.9
542		PAINT	COLUMN	CONCRETE	A	Not Intact- FAIR	WHITE	EXTERIOR	ST	FIRST	GAS BLDG A	A	Negative	0.22
543		PAINT	W FRAME	WOOD	A	Not Intact-POOR	GREEN	EXTERIOR	ST	FIRST	GAS BLDG A	A	Negative	0.13
544		PAINT	W SILL	WOOD	A	Not Intact-POOR	GREEN	EXTERIOR	ST	FIRST	GAS BLDG A	A	Negative	0.3

A = SOUTH

B = WEST

C = NORTH

D = EAST

GLYNN ARCHER ELEMENTARY SCHOOL - 1302 WHITE STREET, KEY WEST, FL

Reading	Nc	Type	COMPONENT	SUBSTRATE	SIDE	CONDITION	COLOR	ROOM TYPE	ROOM NUMBER	FLOOR	SITE/ADDRESS	INSPECTC	Results	PbC
545		PAINT	DC	WOOD	A	Not Intact- FAIR	GREEN	EXTERIOR	ST	FIRST	GAS BLDG A	A	Negative	0.04
546		PAINT	D	WOOD	A	Not Intact- FAIR	GREEN	EXTERIOR	ST	FIRST	GAS BLDG A	A	Negative	0
547		PAINT	CEILING	WOOD	A	Not Intact-POOR	WHITE	EXTERIOR	ST	FIRST	GAS BLDG A	A	Negative	0.02
548		PAINT	BEAM	WOOD	A	Not Intact- FAIR	WHITE	EXTERIOR	ST	FIRST	GAS BLDG A	A	Positive	1.8
549		PAINT	CEILING F	WOOD	A	Not Intact-POOR	WHITE	EXTERIOR	ST	FIRST	GAS BLDG A	A	Negative	0.5
550		PAINT	TIGER	METAL	A	Not Intact-POOR	ORANGE	EXTERIOR	ST	FIRST	GAS BLDG A	A	Positive	2.7
551		PAINT	STEPS	CONCRETE	D	Not Intact-POOR	BEIGE	EXTERIOR	ST	FIRST	GAS BLDG A	A	Negative	0.08
552		PAINT	STAIRS	METAL	D	Not Intact-POOR	BEIGE	EXTERIOR	ST	FIRST	GAS BLDG A	A	Positive	1.7
553		PAINT	STAIRS	METAL	D	Not Intact-POOR	BEIGE	EXTERIOR	ST	FIRST	GAS BLDG C	C	Positive	5.1
554		PAINT	N	WOOD	CALIBRATE	INTACT	ORANGE						Positive	1

A = SOUTH

B = WEST

C = NORTH

D = EAST

APPENDIX C

FIGURES

APPENDIX D
PHOTOGRAPHS



Photograph #1: Wall paint identified with LBP (XRF #15).



Photograph #2: Wall paint identified with LBP (XRF #25).



Photograph #3: Wall paint identified with LBP (XRF #28).



Photograph #4: Wall paint identified with LBP (XRF #43).



Photograph #5: Wall paint identified with LBP (XRF #39).



Photograph #6: Wall paint identified with LBP (XRF #113).



Photograph #7: Ceramic tile identified with lead during this inspection (XRF#212).



Photograph #8: Auditorium walls and columns identified with LBP during this inspection.



Photograph #9: Door and door casing identified with LBP during this inspection (XRF #182-183).



Photograph #10: Typical wood door identified with LBP during this inspection (XRF #196, 219, 220).



Photograph #11: LBP identified on wood trim during this inspection (XRF #256-257).



Photograph #12: Lead identified on ceramic baseboard (XRF # 272).



Photograph #13: LBP identified on wall during this inspection (XRF #287-288).



Photograph #14: Lead identified on beige ceramic tile (XRF #360).



Photograph #15: LBP identified on classroom wall (XRF #368).



Photograph #16: Lead identified on metal sink.



Photograph #17: LBP identified on exterior stucco



Photograph #18: LBP identified on exterior stucco



Photograph #19: LBP in poor condition identified on exterior wood shed attached to the Auditorium building (XRF #512)



Photograph #20: LBP in poor condition identified on exterior wood shed attached to the Auditorium building (XRF #512)



Photograph #21: Exterior door paint identified with LBP during this (XRF #504)



Photograph #22: Typical exterior stairwell identified with LBP during this inspection.



Photograph #23: Front entrance to Glynn R. Archer elementary school.



Photograph #24: Exterior wood beam paint identified with LBP during this inspection (XRF #548).



Photograph #25: Exterior metal tiger statue paint identified with LBP during this (XRF #548).

APPENDIX E
CERTIFICATES

United States Environmental Protection Agency

This is to certify that



EE&G Environmental Services, LLC

has fulfilled the requirements of the Toxic Substances Control Act (TSCA) Section 402, and has received certification to conduct lead-based paint activities pursuant to 40 CFR Part 745.226

In the Jurisdiction of:

Florida

This certification is valid from the date of issuance and expires September 8, 2013

FL-10142-3

Certification #

SEP 2 2 2010

Issued On



Jeanne M. Gettle, Chief

Pesticides and Toxic Substances Branch



United States Environmental Protection Agency

This is to certify that

Hiram Andres Aguiar

has fulfilled the requirements of the Toxic Substances Control Act (TSCA) Section 402, and has received certification to conduct lead-based paint activities pursuant to 40 CFR Part 745.226 as a:

Risk Assessor

In the Jurisdiction of:

Florida


This certification is valid from the date of issuance and expires August 1, 2014

FL-R-9781-1

Certification #

JUL 28 2011

Issued On


Jeaneanne M. Gettle, Chief

Pesticides and Toxic Substances Branch



United States Environmental Protection Agency

This is to certify that

Daniel Joseph Cottrell

has fulfilled the requirements of the Toxic Substances Control Act (TSCA) Section 402, and has received certification to conduct lead-based paint activities pursuant to 40 CFR Part 745.226 as a:

Risk Assessor

In the Jurisdiction of:

Florida


This certification is valid from the date of issuance and expires December 27, 2013

FL-R-10745-3

Certification #

FEB 2 - 2011

Issued On



Jeaneanne M. Gettle, Chief

Pesticides and Toxic Substances Branch





Environmental Services, LLC

5751 Miami Lakes Drive
Miami Lakes, Florida 33014
Tel (305) 374-8300
Fax (305) 374-9004
www.eeandg.com

August 21, 2012
Project No. 2012-2373

Mr. Andrew H. Smyth
CH₂M HILL
6410 5th St, Suite 2A
Key West, FL 33040

**Subject: Final Air Clearance Testing Results
Glynn Archer Elementary School Complex (City Hall Planning Project)
Buildings A, B and Auditorium: Exploratory Engineering Studies
Spot VFT/Mastic and Linoleum Abatement
1302 White Street
Key West, FL 33040**

Dear Mr. Smyth,

EE&G Environmental Services, LLC (EE&G) has completed final air clearance testing for the subject work areas. At the request of CH2M Hill (to accommodate exploratory cutting), nonfriable asbestos-containing flooring materials were spot removed from the following 13 areas on July 14-15, 2012 by Simpson Environmental of Trilby, Florida:

Building A – Rooms 102, 103, Main Office (119C), 122

Building B – Rooms 104, 105 (NW and SE), 107, 109, 206 and 208

Auditorium – NW corner, Center seats

In the afternoon of July 14 and 15, following the completion of removal and encapsulation procedures in each area (<12-15SF each), Mr. Sean Nemser conducted PCM final air clearance under aggressive conditions and analyzed the samples by Phase Contrast Microscopy (PCM) in accordance with the National Institute of Occupational Safety and Health (NIOSH) Method 7400.

The United States (US) Environmental Protection Agency (EPA) clean air standard for airborne asbestos fibers is 0.01 fibers/cubic centimeter (f/cc). The airborne fiber concentration of all final air clearance samples collected during this project were less than 0.007 fibers/cc and so remained well below the EPA clean air standard of 0.010 fibers/cc. The results of these final air clearance analyses are attached as Appendix A. See Appendix B-D for other project-related data.

EE&G believes these hall and classroom flooring areas present no asbestos-related health hazard to renovation workers or future employees or patrons at this site.

If you have any questions or comments on any of this material, please call us.

Sincerely,

Richard D. Grupenhoff
GAES Project Manager
RG/DC: rg attachments

Reviewed by

Daniel J. Cottrell, Ph.D., P.G.
Asbestos Consultant #DD0000010

Mr. Andrew Smyth
August 21, 2012
Appendices

APPENDIX A
PCM FINAL
AIR SAMPLE RESULTS
JULY 14-15, 2012

EE&G AIR SAMPLE ANALYSIS REPORT

PREPARED FOR: CH2M HILL
 ATTN: ANDREW SMYTH
 6410 5th STREET, SUITE 2A
 KEY WEST, FL 33040
 (305) 294-1645; FAX (305) 294-4913

TEST TYPE : WIP

PREPARED BY: EE&G ENVIRONMENTAL SERVICES, LLC
 5751 MIAMI LAKES DRIVE
 MIAMI LAKES, FL 33014
 (305) 374-8300; FAX (305) 374-1666

PROJECT : GLYNN ARCHER ELEMENTARY SCHOOL
 LOCATION : BUILDING A & AUDITORIUM

RECEIVED : 7/14/2012
 RECEIVED BY : RDG

SAMPLED BY : SN

Material Being Removed : VFT/MASTIC
 Respiratory Protection : 1/2 FACE

PROJECT NUMBER: 2012-2373

ID#	ANA	SN	SAMPLE NUMBER	DATE SAMPLED	LOCATION DESCRIPTION	VOLUME (Liters)	DURATION (Minutes)	FLOW (L/Min)	# OF FIBERS	# OF FIELDS	CONCENTRATION (Fibers/cc)
01A	SN	1W		7/14/2012	ROOM 122A-HALLWAY	466	233	2.0	4.0	100	< 0.011
02A	SN	2W		7/14/2012	ROOM 122A-HEPA EXHAUST	360	180	2.0	3.0	100	< 0.014
03A	SN	3W		7/14/2012	ROOM 103-HALLWAY	440	220	2.0	2.0	100	< 0.011
04A	SN	4W		7/14/2012	AUDITORIUM	426	213	2.0	5.0	100	< 0.012
05A	SN	5B		7/14/2012	BLANK-IN	0	0	0.0	0.5	100	0.000
06A	SN	6B		7/14/2012	BLANK-OUT	0	0	0.0	0.0	100	0.000

EE&G ACCEPTABLE
 JUL 17 2012

 Quality Control Officer

EE&G, LLC's liability, if any, for the results indicated herein is specifically limited to the cost of this report, all warranties whether expressed or implied being disclaimed.

ABBREVIATIONS: ANA = Analyst; ID# = Sample ID

METHODS: All air sample preparations and laboratory analyses were carried out following NIOSH Method 7400 (Phase Contrast Microscopy).

EE&G AIR SAMPLE ANALYSIS REPORT

PREPARED FOR: CH2M HILL
 ATTN: ANDREW SMYTH
 6410 5th STREET, SUITE 2A
 KEY WEST, FL 33040
 (305) 294-1645; FAX (305) 294-4913

TEST TYPE : PCM FINAL

PROJECT : GLYNN ARCHER ELEMENTARY SCHOOL
LOCATION : BUILDING A & AUDITORIUM


RECEIVED : 7/14/2012
RECEIVED BY : RDG

SAMPLED BY : SN

Material Being Removed : VFT/MASTIC
Respiratory Protection : 1/2 FACE

PROJECT NUMBER: 2012-2373

ID#	ANA	SN	SAMPLE NUMBER	DATE SAMPLED	LOCATION DESCRIPTION	VOLUME (Liters)	DURATION (Minutes)	FLOW (L/Min)	# OF FIBERS	# OF FIELDS	CONCENTRATION (Fibers/cc)
01A	SN	1F	7/14/2012	ROOM 122A	720	48	15.0	2.0	2.0	100	< 0.007
02A	SN	2F	7/14/2012	AUDITORIUM	720	48	15.0	1.0	1.0	100	< 0.007
03A	SN	3F	7/14/2012	AUDITORIUM	720	48	15.0	2.0	2.0	100	< 0.007
04A	SN	4F	7/14/2012	ROOM 196	720	48	15.0	1.0	1.0	100	< 0.007
05A	SN	5F	7/14/2012	ROOM 103	720	48	15.0	3.0	3.0	100	< 0.007
06A	SN	6F	7/14/2012	ROOM 102	720	48	15.0	2.0	2.0	100	< 0.007
07A	SN	7B	7/14/2012	BLANK-IN	0	0	0.0	0.5	0.5	100	0.000
08A	SN	8B	7/14/2012	BLANK-OUT	0	0	0.0	0.0	0.0	100	0.000



 Quality Control Officer



EE&G, LLC's liability, if any, for the results indicated herein is specifically limited to the cost of this report, all warranties whether expressed or implied being disclaimed.

ABBREVIATIONS: ANA = Analyst; ID# = Sample ID

METHODS: All air sample preparations and laboratory analyses were carried out following NIOSH Method 7400 (Phase Contrast Microscopy).

AIR SAMPLE ANALYSIS REPORT

PREPARED FOR:

CH2M HILL
 ATTN: ANDREW SMYTH
 6410 5th STREET, SUITE 2A
 KEY WEST, FL 33040
 (305) 294-1645; FAX (305) 294-4913

TEST TYPE : PCM FINAL

PROJECT : GLYNN ARCHER ELEMENTARY SCHOOL
 LOCATION : BUILDING B

PREPARED BY:

EE&G ENVIRONMENTAL SERVICES, LLC
 5751 MIAMI LAKES DRIVE
 MIAMI LAKES, FLORIDA 33014
 (305) 374-8300; (305) 374-9004

RECEIVED : 7/15/2012
 RECEIVED BY : RDG

SAMPLED BY : SN

Material Being Removed : VFT/MASTIC
 Respiratory Protection : 1/2 FACE

PROJECT NUMBER: 2012-2373

ID#	ANA	SAMPLE NUMBER	DATE SAMPLED	LOCATION DESCRIPTION	VOLUME (Liters)	DURATION (Minutes)	FLOW (L/Min)	# OF FIBERS	# OF FIELDS	CONCENTRATION (Fibers/cc)
01A	SN	7F	7/15/2012	ROOM 109B-ENTRANCE	720	48	15.0	3.0	100	< 0.007
02A	SN	8F	7/15/2012	ROOM 109B-BACK	720	48	15.0	4.0	100	< 0.007
03A	SN	9F	7/15/2012	ROOM 104-ENTRANCE	720	48	15.0	3.0	100	< 0.007
04A	SN	10F	7/15/2012	ROOM 104-BACK	720	48	15.0	2.0	100	< 0.007
05A	SN	11F	7/15/2012	ROOM 208-ENTRANCE	720	48	15.0	3.0	100	< 0.007
06A	SN	12F	7/15/2012	ROOM 208-BACK	720	48	15.0	2.0	100	< 0.007
07A	SN	13F	7/15/2012	ROOM 206-ENTRANCE	720	48	15.0	2.0	100	< 0.007
08A	SN	14F	7/15/2012	ROOM 206-BACK	720	48	15.0	3.0	100	< 0.007
09A	SN	15F	7/15/2012	ROOM 105-ENTRANCE	720	48	15.0	4.0	100	< 0.007
10A	SN	16F	7/15/2012	ROOM 105-BACK	720	48	15.0	3.0	100	< 0.007

QC ACCEPTABLE
 JUL 17 2012

EE&G, LLC's liability, if any, for the results indicated herein is specifically limited to the cost of this report, all warranties whether expressed or implied being disclaimed.

ABBREVIATIONS: ANA = Analyst; ID# = Sample ID

QA/QC OFFICER

METHODS: All air sample preparations and laboratory analyses were carried out following NIOSH Method 7400 (Phase Contrast Microscopy).

CLIENT: CH2M HILL
 PROJECT: GLYNN ARCHER ELEMENTARY SCHOOL
 LOCATION: BUILDING B

AIR SAMPLE ANALYSIS REPORT CONTINUED

PROJECT NUMBER 2012-2373

ID#	ANA	SN	SAMPLE NUMBER	DATE SAMPLED	LOCATION DESCRIPTION	VOLUME (Liters)	DURATION (Minutes)	FLOW (L/Min)	# OF FIBERS	# OF FIELDS	CONCENTRATION (Fibers/cc)
11A	SN	17F		7/15/2012	ROOM 107-ENTRANCE	720	48	15.0	3.0	100	< 0.007
12A	SN	18F		7/15/2012	ROOM 107-BACK	720	48	15.0	5.0	100	< 0.007
13A	SN	19B		7/15/2012	BLANK-IN	0	0	0.0	0.0	100	0.000
14A	SN	20B		7/15/2012	BLANK-OUT	0	0	0.0	0.0	100	0.000

QC ACCEPTABLE
 Quality Control Officer
 JUL 17 2012
QA/QC OFFICER

EE&G, LLC's liability, if any, for the results indicated herein is specifically limited to the cost of this report, all warranties whether expressed or implied being disclaimed.

ABBREVIATIONS: ANA = Analyst; ID# = Sample ID

METHODS: All air sample preparations and laboratory analyses were carried out following NIOSH Method 7400 (Phase Contrast Microscopy).



5751 Miami Lakes Drive
Miami Lakes, Florida 33014
(305) 374-8300 \$ (305) 374-1666 Fax

AM
BPM

DATE: 07/18/12		CLIENT: CH2MHill		PROJECT: Glynn Archer Elem. P/N: 2012-2373		WORK AREA LOCATION(S): Boiling (8')							
TEST TYPE(S): PGM Final		FILTER TYPE: TEM		MEANS OF PUMP CALIBRATION: Roto		RESPIRATOR TYPE: PAPR		FULL FACE TYPE: "C" NONE					
SAMPLE#	SAMPLE DESCRIPTION/LOCATION	CREW WORK ACTIVITY	PUMP #	TIME (IN MIN)	24 HOUR CLOCK	FLOW	RATE	(L/MIN)	TOTAL AIR VOLUME (LITERS)	FIBER # OF FIBERS	COUNT # OF FIELDS	INFO	8HR TWA (FIB/CC)
F-7	104B-Entrance	VFmas	3	75/843	48	15	15	15	720	3	100		
F-8	104B-BACH		1	756/814						4	100		
F-9	104-Entrance		00	405/453						3	100		
F-10	104-BACH		21	404/454						2	100		
F-11	208-Entrance		00	423/401						3	100		
F-12	206-BACH		21	423/400						2	100		
F-13	206-Entrance		3	846/6434						2	100		
F-14	206-BACH		1	847/6436						3	100		
F-15	105-Entrance		00	455/1043						4	100		
F-16	105-BACH		21	458/1044						3	100		
F-17	107-Entrance		3	938/1024						3	100		
F-18	107-BACH		1	939/1027						5	100		
B-1										0	100		
B-2										0	100		

CHAIN OF CUSTODY: NAME & AFFILIATION _____ DATE/TIME 7/15 _____ PURPOSE COLLECTION TRANSPORT ANALYSIS

RESULTS NEEDED BY _____ CONTACT _____ CASSETTE LOT# _____ AT PHONE/BEEPER# _____


Mr. Andrew Smyth
August 21, 2012
Appendices

APPENDIX B

FIGURES

STRUCTURAL INVESTIGATION BUILDINGS A & B AND AUDITORIUM - FIRST FLOOR PLAN

GLYNN ARCHER SCHOOL - 1300 WHITE STREET
Key West - Florida



- LEGEND:**
- ACCESS HOLES:
INDICATES 24"x24" ACCESS HOLE TO BE CUT AT THE EXISTING FIRST LEVEL TO EXPOSE THE EXISTING FLOOR STRUCTURE (BEAMS AND JOISTS) MEMBERS, UNLESS OTHER MEANS TO ACCESS THE UNDER SIDE OF THE FIRST FLOOR STRUCTURE EXISTS.
 - BORE HOLES:
INDICATES APPROXIMATE LOCATIONS OF THE SOIL INVESTIGATION BY BORING.
 - WALL OPENINGS:
INDICATES APPROXIMATE LOCATIONS OF THE INTERIOR WALL INVESTIGATION. EXPOSE BOTTOM OF WALL BY CUTTING 12"x16" OPENING AND EXPOSE TOP OF WALL ABOVE THE DROPPED CEILING LEVEL BY CUTTING 12"x16" OPENING.
 - FOOTING INVESTIGATION:
LOCATE TWO INTERIOR SPREAD FOOTINGS AND EXCAVATE TO THE BOTTOM OF FOOTING TO VERIFY THE FOOTING SIZE (LENGTH, WIDTH, AND THICKNESS).

AREAS ABATED
0714-071512

- ① CUT LATH & VERTICAL TILE AT COLUMN
- ② FLOOR OPENINGS NOT MARKED



Partial First Floor Plan - A&B Wings

UNITED ST.
"A" WING
600T SF - NET AREA

"B" WING
1582 SF - NET AREA

SEMINARY STREET

SEMINARY STREET

PROVIDE 24"x24" TEST PIT HOLE TO VERIFY PERIMETER FOOTING SIZE (WIDTH, THICKNESS).

PROVIDE 24"x24" TEST PIT HOLE TO VERIFY PERIMETER FOOTING SIZE (WIDTH, THICKNESS).

xxx ROOM NUMBER

- NOT USED
- CEILING OPENING
- WALL OPENING
- FLOOR OPENING
- T - TOP OF WALL
- B - BASE OF WALL

**STRUCTURAL INVESTIGATION
BUILDINGS A & B AND AUDITORIUM - SECOND FLOOR PLAN**



Mr. Andrew Smyth
August 21, 2012
Appendices

APPENDIX C
PROJECT PHOTOGRAPHS

Mr. Andrew Smyth
August 21, 2012
Appendices



Photo #1: Auditorium area abated near center



Photo #2: Auditorium area abated near NW corner

Mr. Andrew Smyth
August 21, 2012
Appendices



Photo #3: B105 sealed off for abatement in 2 spots on 7/15



Photo #4: Auditorium HEPA exhaust outside

Mr. Andrew Smyth
August 21, 2012
Appendices



Photo #5: A Building HEPA exhaust to outside



Photo #6: Typical HEPA exhaust in each room

Mr. Andrew Smyth
August 21, 2012
Appendices




Photo #7: Typical signage on rooms when abated




Photo #8: Typical signage on room 122 closet when abated

Mr. Andrew Smyth
August 21, 2012
Appendices




Photo #9: Typical signage on Auditorium entry flaps

Mr. Andrew Smyth
August 21, 2012
Appendices

APPENDIX D
CERTIFICATES

RETRA TRAINING SERVICES

Florida Approval FL49-0001008

113 S Disston Avenue
Tarpon Springs, FL 34689
1-727-938-5459

Sean Nemser

241 SE 9th Ave Apt. 203 Pompano Beach, FL 33060

Has successfully completed the Requisite Training for Asbestos Accreditation
as required by TSCA Title II

Initial Asbestos Supervisor Contractor FL4722

December 12-16, 2011

Course Date:

December 16, 2011

Exam Date:

December 16, 2012

Expiration Date:

Tarpon Springs, FL

Course Location:

F 026357

Certification Number:

Savio Nava

Instructors

John V. Lewis

Course Administrator

Sampling and Evaluating Airborne Asbestos Dust

AIR ANALYTICS

certifies that

Sean Kemser

has satisfactorily completed a NIOSH 582 Equivalent 32 hour course in Phase Contrast Microscopy covering the contents of NIOSH Method 7400 and the Occupational Safety and Health Administration Reference Method for asbestos fiber analysis, and in testimony whereof, we do confer this certificate at Oviedo, Florida, on January 20, 2012.


Edward A. Nuñez, CIH, LAC
Course Director



Certificate # AA01201258203



AC# 5227070

STATE OF FLORIDA

DEPARTMENT OF BUSINESS AND PROFESSIONAL REGULATION
ASBESTOS LICENSING UNIT

SEQ# L10092501299

DATE	BATCH NUMBER	LICENSE NBR
09/25/2010	100120327	DD0000010

The ASBESTOS CONSULTANT
Named below IS LICENSED
Under the provisions of Chapter 469 FS.
Expiration date: NOV 30, 2012

COTTRELL, DANIEL JOSEPH
6367 SW 44 ST
MIAMI

FL 33155-5142



CHARLIE CRIST
GOVERNOR

DISPLAY AS REQUIRED BY LAW

CHARLIE LIEM
SECRETARY



EE&G IAQ Services, LLC

5751 Miami Lakes Drive
Miami Lakes, Florida 33014
(305) 374-8300
(305) 374-9004

September 6, 2012
EE&G Project No: 2012-2373

Mr. Andrew H. Smyth
CH₂M HILL
6410 5th St, Suite 2A
Key West, FL 33040

**Subject: Due Diligence Indoor Air Quality (IAQ)/Building Materials Assessment
Glynn Archer Elementary School Complex (City Hall Planning Project)
Buildings A, B and Auditorium: Exploratory Engineering Studies
1302 White Street
Key West, FL 33040**

Dear Mr. Smyth:

EE&G IAQ Services, LLC (EE&G) was retained by CH₂M HILL (on behalf of the City of Key West) to perform a due diligence assessment at the Glynn Archer Elementary School complex Annex located at 1302 White Street, Key West, Florida (herein referred to as the subject building). This report is based on observations made by Mark Skweres of EE&G, during an assessment of the subject building on July 18, 2012 and while other engineering studies were in progress as school was closed for Summer Break.

The purpose of the assessment was to provide a general understanding of the building as it related to potential Indoor Air Quality (IAQ) issues or any water-damaged materials that may require special remediation during any eventual interior demolition phases. As such, it was not the objective of the assessment to identify each and every potential IAQ issue, but rather, to identify broader potential issues. The assessment was accomplished through the following:

- Visual inspection of the representative building materials. The assessed areas were defined as, and limited to, those areas readily accessible without the use of tools, ladders, or destructive techniques.
- Moisture content testing of building materials suspected of water impacts.
- Photographic documentation to record representative conditions.

LIMITATIONS

This report has been prepared by EE&G in a manner consistent with that level of care and skill ordinarily exercised by members of the profession currently practicing under similar conditions. No other warranty, expressed or implied, is made. EE&G's interpretations and recommendations are based upon our investigative work. Other conditions elsewhere in the subject building may differ from those in the inspected/surveyed suite and such conditions are unknown, may change over time and have not been considered.

EE&G could not access all interstitial wall spaces, upper roof areas or crawl spaces due to various structural hindrances. Additionally, condemned areas existed in the structure and access was restricted at the time of the survey.

Changes or modifications to the site made after the site inspection are not covered. The parameters tested are limited by the methodologies employed for this investigation. The data obtained cannot be used to establish a health-based risk assessment or otherwise be used to establish if an area is "safe for occupancy".

EE&G will not be responsible for the interpretation or use by others of data developed pursuant to the compilation of this report. This report reflects conditions, operations, and practices as observed on the date and time of the site inspection only. The interpretations and recommendations, stated in this report, are based on previous environmental studies and research conclusions. This report should be interpreted in its entirety.

The nature of water intrusion and some mold issues are such that reservoirs of damaged material can exist behind walls or within building cavities. Since this assessment excluded destructive testing it is possible that some hidden reservoirs of mold or water damaged building material were not identified.

This report was not intended to provide documentation or specific recommendations for all conditions that could impact the buildings IAQ, but rather a broad overview of the IAQ-related conditions observed during the inspection.

METHODS

Building Assessment

Materials were visually assessed for evidence of water-impacts, water-damage, and visible assumed mold-growth (AMG). Water impacts, water damage and AMG were defined as materials showing the following characteristics:

- Visible staining on building materials in a pattern that was suggestive of either short term or long term contact with water.
- Corrosion of materials that was indicative of contact with water.
- Visible accumulation of AMG that fit a definite pattern that was associated with water contact.

The impacted building materials as observed during the course of this inspection were categorized and defined as follows:

AMG-Impacted - Characterized by visible accumulations of AMG on building materials (either surficial or penetrated) that fit a definite pattern consistent with a direct water release, condensation, or elevated humidity.

Water Stained - Characterized by visible staining, corrosion, or discoloration in a pattern that was suggestive of short or long term direct water contact either from a water release or condensation whereby the discolored portions of the building material are surficial in nature and did not penetrate the matrix of the material below the first layer.

Water Damaged - Characterized by water staining that includes physical damage and decomposition of the building material without evidence of AMG. Water damage is associated patterns of direct water contact whereby the binders within the material break down and the material loses its physical properties to perform the function for which it was intended.

Areas included in the inspection were those readily accessible meaning that moving of heavy furnishings or destructive testing was not included. Inspection holes had been installed in various locations through Wing A and B. Figure 1 and 2 has been attached to show the approximate locations of the inspected areas.

Moisture Content Measurement

The moisture contents of the impacted building materials were measured using a Delmhorst Total Check. This instrument reports results in potentially three scales depending on the user's selection:

- Wood Scale – 5% to 60% moisture content (MC) for Douglas Fir and can be corrected for 69 individual wood species over that range.
- Drywall Scale – 0.1% to 6% MC. Readings greater than 1% indicate enough moisture present to allow for mold growth if other factors such as a high relative humidity level and food source are present.
- 0 to 100 Reference Scale – Used to compare two non-wood materials. Benchmarks need to be established for comparisons. The scale is a relative-type scale.

The percent MC on the Drywall Scale was categorized into the following classifications:

- 0.1 to 0.5% MC - The material was in a safe, dry condition. Moisture-related problems of decay and deterioration were not likely to occur.
- From 0.5% to 1.0% MC - The material was in a borderline condition. Moisture-related problems of decay and deterioration were possible under certain conditions.
- Greater than 1.0% WME - The material was in a wet condition. Moisture-related problems of decay and deterioration were likely to occur in time unless the moisture level of the material was reduced.

FINDINGS

Building Assessment

The subject Glynn Archer Elementary School (Buildings A, B and Auditorium only) were built in the late 1920's with a major southerly addition (Building C) in 1950's, this portion of the building was not part of the scope and therefore not assessed. Both A and B structures were connected by the Auditorium structure and exterior walkways. Multiple renovations and painting operations had been performed over the past 40 years to meet the changing demands of the school occupants and to respond to maintenance needs. Building finishes included painted block walls, plaster system on wood lath, limited gypsum board, suspended and glued-in-place ceiling tiles. Flooring included various layers of vinyl tile, ceramic tiles, and carpeting over a wood base floor supported by wood joists. It appeared that the plaster system on the exterior walls was applied directly to the concrete, as wood lath was not observed.

The following was the general building layout:

- **Building A: NE most portion**
 - Floor 1 – Administration offices, storage, mechanical rooms, classrooms, common halls and bathrooms.
 - Floor 2 – Various classrooms, storage, mechanical, common halls and bathrooms.
- **Building B: NW most portion**
 - Floor 1 – Teacher's lounge, storage, custodial, classrooms, common halls and bathrooms.
 - Floor 2 – Various classrooms, storage, mechanical, common halls and bathrooms.
- **Auditorium: Central portion**
 - Floor 1 – Seating areas, stage, and rear storage and mechanical rooms.

The following observations were made and pictures are available if requested:

Building A:

Floor 1

Main Office (Rooms 119)

- Two water-stained ceiling tiles were observed in main 119 central areas.
- One water-stained ceiling tile in 119E. AMG was observed on backside and was likely related to a condensation leak.

- AMG was observed on particle board divider wall, which had been partially demolished. The remaining wall was located above the suspended ceiling tile.

Room 102

- Five water-stained ceiling tiles were observed.
- East wall had water-damaged plaster system.
- AC unit was added to this room, AC not running at time of inspection

Room 103

- Two water-stained ceiling tiles were observed in corner by conduit. Water damage may have come from second floor or from exterior.
- Delaminating plaster was observed below the windows, likely associated with prior leaks.

Room 100

- One water-stained ceiling tile was observed in the NW corner, peeling paint plaster below stain.
- AMG was observed in corner of window sill <1 square foot.
- Delaminating plaster was observed below the windows, likely associated with leaks in past.

Room 102 Custodial Closet

- No water-damage observed.

Room 124 Boys Bathroom (Ceramic tile)

- Wet wall on hallway side by office showed that the interior wall may be constructed of cement board. No water damage was observed.

Room 122 Girls Bathroom (Ceramic tile)

- AMG was observed in vestibule wall common to Boys 124 bathroom. Could be a possible leak on the wet wall between the boys and girls room.

Common Halls – First Floor

- Various water stained 2x4' and 1x1' ceiling tiles were observed, sporadically.
- Minor AMG on upper ceiling on SE side.

Floor 2
Room 204

- Six water-stained ceiling tiles were observed likely associated with past roof leaks.
- Water-damaged plaster observed below windows.

Room 200

- Two water-stained ceiling tiles observed.
- Water-damaged plaster system on exterior walls around windows as well as exterior wall without the window.

Room 213

- No water-stained ceiling tiles observed.
- Peeling paint on exterior walls.

Room 202

- No water-stained ceiling tiles observed.
- Water-damaged plaster on exterior walls around windows.

Room 203

- Three water-stained ceiling tiles.
- Water-damaged plaster system around windows

Room 205

- Seven water-stained ceiling tiles.
- Water-damaged plaster system observed around windows.

Room 212

- Water-damaged plaster system on lath below windows.
- AMG (minor) on exposed wood lath.
- Area was open to Auditorium above ceilings.

Common Halls

- Drop and upper ceilings observed in good condition
- Water-damaged plaster system below windows in NW stairwell.

Building B:
Floor 1

Room 106

- Seven water-stained ceiling tiles were observed, with AMG on several, likely associated with ventilator leak from Room 207, which was located above this room.

Room 105

- Water-stained ceiling tiles associated with both ceilings.
- Water damaged plaster walls in corners of exterior walls.

Room 103 Boys Bathroom

- Three water-stained ceiling tiles.

Room 104

- Seven water-stained ceiling tiles.
- Minor peeling paint on window wall.

Room 109

- No water damage observed.

Room 121 (Lounge)

- Water-staining in cabinets below sink.
- Retro-fitted with two bathrooms.

Room 108

- Five water-stained ceiling tiles.

Common Halls – First Floor

- Water-staining was observed associated with the ceiling tiles and plaster.

Floor 2
Room 207

- AC unit leak recently, cause of water-damage observed in Room 106.
- Two water-stained ceiling tiles areas.

Room 210

- No water-stained ceiling tiles observed.
- Minor water-damaged plaster on window wall.

Room 209

- Water-stained 1x1' ceiling tiles on upper ceiling.
- Water-damaged plaster system on window walls.

Room 208

- One water-stained ceiling tile.

Room 206

- No water-damage observed.

Room 215

- Water-damaged plaster along length of window wall.

Girls' Bathroom

- AMG and moss growth was observed around the window, indicative of a damp environment.
- The wet wall showed evidence of tile repair, likely to repair a leak.

Small Boys Bathroom

- No water-damage observed.

Common Halls

- Minor water-stained ceiling tiles observed.

Auditorium
Main Seating Areas

- Five water-stained ceiling tiles near roof leak areas.
- Three water-stained ceiling tiles on wall common to "A" hall.

CONCLUSIONS AND RECOMMENDATIONS

Based on the findings and observations presented above, EE&G concludes the following:

- Evidence of water intrusion issues associated with the building envelope was observed. This came in the form of damage to the exterior walls likely associated with failed window assemblies; issues with the roof, which resulted in damage to ceiling systems; and roof transitions, which likely resulted in the damage associated with Room 212 and the auditorium.
- Additional deferred maintenance issues likely contributed to the AC leak observed in Room 207 of the B-Wing and the conditions observed in the bathroom wet walls.
- The damage plaster observed associated with the perimeter or exterior walls was likely not conducive to creating an environment where mold growth could occur as the plaster system was applied directly to the concrete.
- The observed AMG associated with the ceiling tile systems and remnant particle board divider wall observed in Room 119, did not appear to be wide-spread and indicative of a systemic condition and was more likely localized.

Based on the conclusions reported above, EE&G offers the following recommendations:

- It was reported to EE&G that a large portion of the interior was going to be demolished and new windows installed. Based on the generally localized water-damaged and AMG-impacted materials, these can be addressed during the demolition as the work areas will likely not be conditioned and opened to the exterior. Although wide-spread mold remediation may not be likely based on what was observed, EE&G recommends removing the identified mold-impacted materials under the supervision of a Florida-licensed mold remediator. Procedures should be developed for handling, carefully removing the materials, and disposal to minimize disturbance normally associated with interior demolition. Since asbestos abatement will be required anyway, EE&G suggests having these items remediated on the same mobilization, prior to release of the areas to the general demolition crews. As with the asbestos abatement items, follow-up assessments should be conducted to document that the affected materials have been removed and additional damage is not encountered beyond what was observed.
- Demolition of wet wall areas associated with the bathrooms should be conducted in an exploratory manner as AMG-impacts in these areas may be encountered. These areas could require a more rigid remediation plan, if necessary.

Mr. Smyth
September 6, 2012
Page 10

EE&G appreciates the opportunity to assist you with this project. Please call us if you have any questions.

Respectfully Submitted,

A handwritten signature in blue ink, appearing to read 'M. Skweres', written over a light blue grid background.

Mark A. Skweres, CIEC
Certified Mold Assessor

Very truly yours,

A handwritten signature in black ink, appearing to read 'Richard Grupenhoff', written over a light blue grid background.

Richard Grupenhoff
Sr. Staff Professional
Certified Abatement Designer
EE&G

APPENDIX A
SITE FIGURES


ZONING SITE PLAN DATA:

REQUIRED LRS	PROVIDED
ZONING DESIGNATION	HPS
LOT SIZE	114,155 sq ft
SET BACKS	
FRONT	20'
REAR	10'
STREET SIDE	55' (10')
MAXIMUM FLOOR COVER	20' (10')
MAXIMUM BUILDING COVER	20' (10')
MINIMUM IMPERVIOUS SURFACE	5'
(NOTES: TRAIL LINES AND HATCHING ARE 50% IMPERVIOUS)	40% (27,500 sq ft)
	50% (4,078 sq ft)
	49.2% (57,000 sq ft)

PARKING

LPR REQUIRED: OFFICE USES 120 SPACES. MAINTENANCE USES: 8 SPACES. TOTAL 128 SPACES. ADDITIONAL: 40 SPACES. HOWEVER, SPACE PLANS JOINED TO THIS SET. TOTAL 168 SPACES. TOTAL 168 SPACES IS NOT RECORDED. BICYCLES @ 15% = 25.2. TOTAL 193.2. (NOTE: PARKING MAY BE REDUCED IN FAVOR OF ADDITIONAL LANDSCAPING)

TYPE	QUANTITY	AREA (sq ft)
FULL SIZE SPACES	124	1996
COMPACT SPACES	20	300
LANDSCAPING	6	90
LANDSCAPING SPACES	6	90
TOTAL		1996
PLUS (1) LOADING SPACE		812 x 50
BICYCLES		1500 sq ft @ 2/BIKE
TOTAL		65



SCHEMATIC SITE PLAN

1" = 30'

GLYNN ARCHERS SCHOOL
WHITE STREET
KEY WEST, FLORIDA


Bender & Associates
ARCHITECTS
P.A.
410 Anselmi Street
2nd Floor, Suite 200
Key West, FL 33401
Phone: (305) 236-2311
Fax: (305) 236-2312
Florida License #00000000

Project No. 1003

Date: 8/20/78

OF 30

**STRUCTURAL INVESTIGATION
BUILDINGS A & B AND AUDITORIUM - SECOND FLOOR PLAN**



Partial Second Floor Plan - A&B Wings

Mr. Smyth
September 6, 2012
Page 12

APPENDIX B
INSPECTION PHOTOGRAPHS
JULY 18, 2012

Mr. Smyth
September 6, 2012
Page 13

**AVAILABLE ON FILE
UPON REQUEST**